

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000992/KBA3Q2

Date: 15/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994313

Claimant
Vehicle No : SGY3862U **Insured Vehicle No :** GBE4810C

Date of Loss: 14/01/2020 Nature of Claim: TP Claim No: 8107657252SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY3862U	Engine No:	2ZR0A00429
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W80J007721
Reg. Date:	24/08/2017 (Man. Year: 2017)	Odometer:	27165 km
Colour:	Metallic Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 3 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 3 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,286.18	31,151.11	8,135.07	20.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,560.00	4,580.00	980.00	17.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	44,846.18	35,731.11	9,115.07	20.33
Approved Total (Overridden) (\$\$)		28,000.00		
(\$\$)	44,846.18	28,000.00	16,846.18	37.56
+ GST 7.00/7.00% (\$\$)	3,139.23	1,960.00	1,179.23	37.56
Nett Amount (\$\$)	47,985.41	29,960.00	18,025.41	37.56
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 16/01/2020

Date Inspected: 16/01/2020 Inspected At:

10 ANG MO KIO IND PARK 2A #01-04
ANG MO KIO AUTOPOINT .
SINGAPORE 568047
Repairer: Cheng Hoe Motor Pte Ltd
(Yishun)

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,540.90 FL	*1,540.90 FL
2	1		*FRONT RH DOOR INNER RUBBER	Serviceable	175.40 FL	*- FL
3	1		*FRONT RH DOOR OUTER CHANNEL	*Check	141.07 FL	*- FL
4	1		*FRONT RH DOOR WINDOW GLASS	Cut	611.75 FL	*611.75 FL
5	1		*FRONT RH DOOR WINDOW GLASS REAR GARNISH	Cut	99.80 FL	*99.80 FL
6	1		*SET FRONT RH DOOR FRAME STICKER	Necessary	83.12 FL	*83.12 FL
7	1		*FRONT RH DOOR SIDE MIRROR ASSY	Broken	799.87 FL	*799.87 FL
8	1		*REAR RH DOOR	Bent	1,511.79 FL	*1,511.79 FL
9	1		*REAR RH DOOR TOP HINGE	Repair	78.34 FL	*- FL
10	1		*REAR RH DOOR BOTTOM HINGE	*Check	78.34 FL	*- FL
11	1		*REAR RH DOOR CHECKER	*Check	141.07 FL	*- FL
12	1		*REAR RH DOOR INNER RUBBER (50%)	Cut	138.05 FS	*92.03 FS
13	1		*REAR RH DOOR INNER LOCK	Jammed	377.80 FL	*377.80 FL
14	1		*SET REAR RH DOOR FRAME STICKER	Necessary	71.07 FL	*71.07 FL
15	1		*REAR RH DOOR OUTER CHANNEL	Dented	156.09 FL	*156.09 FL
16	1		*REAR RH DOOR POWER WINDOW MOTOR	Jammed	788.40 FL	*788.40 FL
17	1		*REAR RH DOOR POWER REGULATOR	Bent	191.75 FL	*191.75 FL
18	1		*REAR RH DOOR STRIKER	*Check	39.08 FL	*- FL
19	1		*REAR RH DOOR OUTER GARNISH	Cut	66.97 FL	*66.97 FL
20	1		*REAR RH DOOR INNER TRIM BOARD	*Check	1,221.75 FL	*- FL
21	1		*REAR RH DOOR SPEAKER	*Check	299.80 FL	*- FL
22	1		*REAR RH DOOR STEP GARNISH	*Check	211.67 FL	*- FL
23	1		*REAR RH DOOR INNER RUBBER (FRAME)	*Check	397.60 FL	*- FL
24	1		*REAR RH DOOR AIRBAG SENSOR	Necessary	402.90 FL	*402.90 FL
25	1		*RH SIDE SKIRT	Cracked	1,377.80 FL	*1,377.80 FL
26	1		*RH CENTRE PILLAR	*Check	394.76 FL	*- FL
27	1		*REAR RH FENDER	Bent	921.60 FL	*921.60 FL
28	1		*SET REAR RH FENDER GLASS MOULDING	Necessary	175.20 FL	*175.20 FL
29	1		*REAR BUMPER	Cracked	551.95 FL	*551.95 FL
30	2		*REAR BUMPER SIDE RETAINER	Distorted	175.08 FL	*175.08 FL
31	2		*REAR BUMPER CORNAL RETAINER	Distorted	123.34 FL	*123.34 FL
32	1		*SET REAR BUMPER PARKING SENSOR	Torn	350.00 FL	*350.00 FL
33	5		*REAR BUMPER CLIP	Necessary	19.45 FL	*19.45 FL
34	1		*REAR BUMPER RH INNER SHIELD	Cracked	65.60 FL	*65.60 FL
35	1		*TAILGATE LOGO	Necessary	66.86 FL	*66.86 FL
36	1		*TAILGATE EMBLEM VALVEMATIC	Necessary	51.40 FL	*51.40 FL
37	1		*FRONT WINDSCREEN GLASS	Cracked	1,640.90 FL	*1,640.90 FL
38	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	107.40 FL	*107.40 FL
39	2		*REAR SPORT RIM	Dented	3,648.40 FL	*3,648.40 FL
40	1		*REAR SHOCK ABSORBER	N/S *Check / O/S Bent	443.30 FL	*221.65 FL
41	2		*REAR SHOCK ABSORBER SPRINGS	*Check	623.20 FL	*- FL
42	2		*REAR TOP MOUNTINGS	*Check	281.40 FL	*- FL
43	2		*REAR STOPPERS	*Check	67.98 FL	*- FL
44	1		*REAR AXLE ASSY	Bent	2,543.00 FL	*2,543.00 FL
45	2		*REAR AXLE BUSHES	Necessary	241.20 FL	*241.20 FL
46	1		*REAR STABILIZER BAR	*Check	311.95 FL	*- FL
47	1		*REAR AXLE DAMER	*Check	180.70 FL	*- FL
48	1		*REAR WHEEL HUB ASSY	Bent	692.75 FL	*692.75 FL
49	1		*REAR RH ABS SENSOR WIRE	*Check	146.30 FL	*- FL
50	1		*SET REAR HANDBRAKE CABLE	*Check	1,091.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*DASHBOARD ASSY	Torn	921.75 FL	*921.75 FL
52	1		*PASSENGER AIR BAG	Burst	3,990.70 FL	*3,990.70 FL
53	1		*PASSENGER AIR BAG WIRE	Necessary	61.70 FL	*61.70 FL
54	1		*AIR BAG ECU	Burst	1,007.00 FL	*1,007.00 FL
55	1		*STEERING AIRBAG	Burst	2,997.40 FL	*2,997.40 FL
56	1		*STEERING SPIRAL CABLE	Necessary	754.90 FL	*754.90 FL
57	1		*AIRBAG SENSOR RH	Necessary	402.95 FL	*402.95 FL
58	2		*FRONT SEAT BELT	Jammed	3,400.80 FL	*3,400.80 FL
59	1		*SEAT BELT LOWER CENTRE GARNISH	Distorted	303.70 FL	*303.70 FL
60	1		*ROOF LINING	Torn	2,957.40 FL	*2,957.40 FL
61	1		*RH SIDE CURTAIN AIRBAG	Burst	3,003.95 FL	*3,003.95 FL
62	1		*DASHBOARD CENTRE RADIO CONSOLE	*Check	621.70 FL	*- FL
63	1		*FRONT RH WINDSCREEN PILLAR GARNISH	*Check	265.40 FL	*- FL
64	1		*REAR LH HEIGHT CONTROL SENSOR	*Check	600.79 FL	*- FL
65	1		*REAR MUFFLER	Bent	1,087.40 FL	*1,087.40 FL
66	1		*REAR MUFFLER HEAT SHIELD	*Check	125.40 FL	*- FL
67	1		*REAR MUFFLER MID PIPE	*Check	3,028.95 FL	*- FL
68	1		*FRONT RH DOOR WINDOW GLASS TINTED FILM	Necessary	90.00 FS	*60.00 FS
69	1		*SET DOOR CHROME MOULDING	Dented	360.00 FS	*360.00 FS
70	1		*REAR RH TYRE	Punctured	110.00 FS	*110.00 FS
71	1		*ERP BRACKET	Necessary	25.00 FS	*25.00 FS
72	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
73	1		*REAR RH FENDER GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 52,113.89 41,292.47
- List Item Discount on L Items 25.00/25.00% (S\$) 12,827.71 10,141.36

Total Parts (S\$) 39,286.18 31,151.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (*Check)	New	100.00	0.00
2	REMOVE & REFIX REAR RH FENDER GLASS	New	60.00	60.00
3	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	120.00	120.00
4	REMOVE & REFIX BOTH RH DOORS & ATTACHMENTS ,RH SIDE MIRROR ,REAR BUMPER ,TO CUT ,WELD & RENEW REAR RH FENDER ,RH CENTRE PILLAR ,RH ROCKER PANEK ,KNOCKING & REPAIR REAR END PANEL ,REAR RH FENDER INNER PANEL & REALIGN THE SAME	New	1,600.00	1,400.00
5	PUTTY & RESPRAY REAR BUMPER ,TAILGATE ,REAR BOTH FENDERS ,RH FENDER INNER PANEL,BOTH RH DOORS & CENTRE PILLAR ,RH ROCKER PANEL ,RH SIDE MIRROR ,REAR END PANEL & ALL AFFECTED AREAS	New	1,500.00	1,400.00
6	REMOVE & REFIX REAR SEAT ,CARPET ,GARNISH TO FACILITATE REPAIR	New	150.00	120.00
7	REMOVE & REFIX BOTH RH WINDOW GLASSES & RESET CENTRAL LOCKING	New	120.00	120.00
8	TO MOUNT ON CAR-O-LINER JACK & STRAIGHTEN (*Check)	New	250.00	0.00
9	REMOVE & REFIX ROOF LINING & REALIGN THE SAME	New	120.00	100.00
10	REMOVE & REFIX REAR AXLE ASSY ,BOTH UNDERCARRIAGE & REALIGN THE SAME	New	300.00	240.00
11	REMOVE & REFIX DASHBOARD ASSY & REALIGN THE	New	250.00	250.00
12	REMOVE & REFIX FRT SEAT BELT ,STEERING AIRBAG ,PASSENGER AIRBAG ,AIRBAG ECU ,RH CURTAIN AIRBAG & REALIGN THE SAME	New	350.00	250.00
13	RESET & REPROGRAMME FAULT CODE	New	200.00	180.00
14	REMOVE & REFIX BOTH REAR RIMS ,TYRES ,BALANCE & REALIGN THE SAME	New	50.00	40.00
15	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
16	RUSTPROOFING	New	180.00	120.00
17	REMOVE & REFIX REAR MUFFLER ,MID PIPE & REALIGN THE SAME	New	150.00	120.00
Gross Labour Cost (\$\$)			5,560.00	4,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >