

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20000996/GEA3Q2

**Date:** 29/04/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant** Vehicle No : SJL2330C **Insured Vehicle No :** SMN7044A

Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: 9923605408SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJL2330C</b>	Engine No:	2AZL012842
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR507134762
Reg. Date:	15/08/2017 (Man. Year: 2016)	Odometer:	48153 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,615.00	3,337.50	2,277.50	40.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	1,520.00	3,000.00	66.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,135.00</b>	<b>4,857.50</b>	<b>5,277.50</b>	<b>52.07</b>
<b>+ GST 7.00/7.00% (S\$)</b>	709.45	340.03	369.42	52.07
<b>Nett Amount (S\$)</b>	<b>10,844.45</b>	<b>5,197.53</b>	<b>5,646.92</b>	<b>52.07</b>
<b>+ Car Rental (11.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		1,412.40		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,611.93</b>		

#### INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 18/02/2020 Inspected At:

Jack Cars Enterprise Pte Ltd - Ubi  
(HQ)  
BLK 3007 UBI ROAD 1 #01-450  
Singapore 408701

Estimated Period of Repair: 7.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Buckled	1,100.00 F	*1,100.00 FL
2	1		*REAR BOOT INNER COVER	Not Necessary	320.00 F	*- FL
3	1		*REAR BUMPER	Deformed	980.00 F	*980.00 FL
4	1		*REAR BUMPER CHROME GARNISH (AFTER MARKET)	Deformed	180.00 F	*180.00 FL
5	1		*REAR BUMPER INNER SPONGE	Not Necessary	210.00 F	*- FL
6	1		*REAR END PANEL	Buckled	760.00 F	*760.00 FL
7	1		*REAR END PANEL TOP COVER (AFTER MARKET)	Deformed	250.00 F	*250.00 FL
8	1		*REAR END PANEL LOWER COVER	Deformed	310.00 F	*310.00 FL
9	1		*LOCK -UPPER	Cut	210.00 F	*210.00 FL
10	1		*LOCK -LOWER	Not Necessary	110.00 F	*- FL
11	1		*LOCK COVER	Not Necessary	100.00 F	*- FL
12	1		*REFLECTOR -RIGHT	Cracked	100.00 F	*100.00 FL
13	1		*WEATHERSTRIP	Twisted	280.00 F	*280.00 FL
14	1		*REAR NUMBER PLATE & COVER	Bent	65.00 FS	*40.00 FS
15	1		*BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
16	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
17	1		*RELAY SENSOR	Not Necessary	180.00 FS	*- FS
18	1		*TOYOTA EMBLEM	Necessary	75.00 FS	*75.00 FS
19	1		*ESTIMA EMBLEM	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,615.00</b>	<b>4,380.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	1,042.50
<b>Total Parts (\$)</b>	<b>5,615.00</b>	<b>3,337.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	2,000.00	600.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,500.00	600.00
3	TO CHECK LIGHTING SYSTEM WIRING & REWIRE	New	250.00	0.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	120.00	60.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	180.00	60.00
6	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	200.00	100.00
7	TO REMOVE & REINSTALL REVERSE & RELAY SENSOR	New	150.00	40.00
8	ANTI RUST TREATMENT	New	120.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,520.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >