

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001003/EPA3Q2

Date: 28/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : PA9236H	Insured Vehicle No :	SHC8422C	
Date of Loss: 09/01/2020	Nature of Claim: TP	Claim No: MCT20010204	

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA9236H		
Make & Model:	SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A)	Engine No:	6601675
Reg. Date:	12/01/2010 (Man. Year: 2009)	Chassis No:	YS2K4X20001866728
Colour:	Multi-colour	Odometer:	181396 km
Engine Capacity:	9290 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	950.00	200.00	17.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,150.00	950.00	200.00	17.39
+ GST 7.00/7.00% (S\$)	80.50	66.50	14.00	17.39
Nett Amount (S\$)	1,230.50	1,016.50	214.00	17.39
+ Loss of Use (2.0 x S\$180.00/day) (S\$)		360.00		
Nett Liability (S\$)		1,376.50		

INSPECTION

Date of Assignment:	14/01/2020	
Date Inspected:	16/01/2020 Inspected At:	29 FIRST LOK YANG ROAD 629736
		Repairer: Woodlands Transport
		Service Pte Ltd (HQ)
Estimated Period of Repair:	2.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Mar 2020)	
Parts:	N/A	SCANIA KUB4X2 9.3L A/T ABS TURBO 9.3 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9236H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR PANEL BEAT FRONT BUMPER RHS AND RHS SIDE PANEL	New	450.00	350.00
2	TO PUTTY AND SPRAY PAINTING FRONT BUMPER AND SIDE PANEL	New	700.00	600.00
Gross Labour Cost (\$\$)			1,150.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >