



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2004114  
INV Date 22/05/2020  
Reference CC4/FCI20001010/Eea3n2  
Code FCI2



### PROFESSIONAL SERVICE FEE

Vehicle No. SLB 3823U  
Insured Veh. SHD 6897Z  
Claim No. D20000360MFSH  
Policy No. D-18088936MFSH  
Accident Date 11/01/2020  
Inspection Date 15/01/2020

Description	Total
Third Party Express Settlement	600.00
<b>Subtotal</b>	<b>600.00</b>
<b>GST (7%)</b>	<b>42.00</b>
<b>Grand Total</b>	<b>642.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20001010/Eea3n2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-05-2020



Code : FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6897Z	Veh. Inspected	SLB 3823U
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D20000360MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	15/01/2020

#### 2. Vehicle Particulars & Condition

Make & Model	LAND ROVER DISCOVERY SPORT	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SALCA2AG7FH541714	Colour	WHITE
Odometer	29883	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	PIRELLI	6 mm
L/H Front Tyre	235/60 R18	PIRELLI	6 mm
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	11/01/2020	Inspection Date	15/01/2020
Survey held at	MOTORWAY CAR CARE CENTRE PTE LTD 1094 LOWER DELTA ROAD MOTORWAY BUILDING . SINGAPORE 169205		

#### 5a. Remarks

A)THE INPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 3823U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT LID	DENTED	3,200.00	3,200.00
1	REAR BOOT LID SPORT EMBLEM	NECESSARY	100.00	100.00
1	REAR BOOT LID DISCOVERY EMBLEM	NECESSARY	100.00	100.00
1	REAR BOOT LID LAND ROVER EMBLEM	NECESSARY	180.00	180.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	250.00	250.00
1	REAR BOOT REFLECTOR LAMP LH	NOT NECESSARY	980.00	-
1	REAR TAILLAMP LH	BROKEN	1,300.00	957.20
1	REAR BUMPER	BROKEN	2,800.00	2,606.40
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	1,050.00	-
1	REAR BUMPER RETAINER LH	BROKEN	120.00	120.00
1	REAR UPPER END PANEL	NOT NECESSARY	1,300.00	-
1	REAR END PANEL	NOT NECESSARY	1,150.00	-
1	REAR FLOOR END PANEL	NOT NECESSARY	950.00	-
1	REAR FENDER LH	DENTED	2,550.00	2,550.00
1	REAR FENDER AIR GRILLE LH	NOT NECESSARY	150.00	-
1	REAR TAILLAMP PANEL LH	NOT NECESSARY	480.00	-
1	REAR FENDER UNDER -DUST COVER LH	CRUSHED	680.00	380.00
1	REAR FENDER WHEEL ARCH -MOULDING LH	CUT	550.00	297.00
1	REAR WHEEL -HOUSE INNER PANEL LH	NOT NECESSARY	3,450.00	-
1	REAR LOWER ARM LH	NOT NECESSARY	860.00	-
1	REAR DRIVE SHAFT LH	NOT NECESSARY	2,800.00	-
1	REAR WHEEL BEARING LH	NOT NECESSARY	350.00	-
1	REAR KNUCKLE LH	NOT NECESSARY	1,400.00	-
1	REAR LH CONTROL ARM REAR	NOT NECESSARY	460.00	-
1	FRONT LH CONTROL ARM REAR	NOT NECESSARY	450.00	-
1	SHOCK ABSORBER LH	NOT NECESSARY	1,100.00	-
1	REAR STABILIZER	NOT NECESSARY	980.00	-
1	REAR EXHAUST SILENCER	BENT	4,100.00	2,380.00
1	REAR DOOR LH	DENTED	3,100.00	2,800.00
1	REAR BUMPER REFLECTOR LENS LH (ADDITIONAL)	BROKEN	475.00	475.00
1	REAR FENDER INNER PANEL LH (ADDITIONAL)	DENTED	580.00	480.00

Report Ref No. CC4/FCI20001010/Eea3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-3,799.50	-1,687.56
			34,195.50	15,188.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	250.00	30.00
1	REVERSE SENSORS (SN)	SHORTED	380.00	380.00
1	REAR FENDER WHEEL ARCH MOULDING CLIPS (SN)	NECESSARY	250.00	30.00
1	REAR FENDER UNDER -DUST COVER CLIPS (SN)	NECESSARY	250.00	30.00
1	REAR SPORT RIM LH (SN)	CUT	2,400.00	1,800.00
1	REAR TYRE LH (SN)	BROKEN	2,400.00	1,000.00
1	REAR DOOR WHEEL ARCH MOULDING LH CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR FENDER GLASS SEALANT (SN)	NECESSARY	60.00	30.00
			6,170.00	3,370.00
	<b><u>LABOUR</u></b>			
	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS .INCLUDING PANEL BEAT ,CUT /WELD ,STRAIGHTEN PANEL WHERE STRAIGHTEN.		3,800.00	1,750.00
	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		2,200.00	1,250.00
	TO APPLY RUSTPROOFING /TUCOATING TREATMENT TO REPAIRED PARTS.		180.00	50.00
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES .		180.00	80.00
	REMOVE & REFIT REAR WINDSCREEN GLASS .		180.00	120.00
	TO CHECK REAR WIRES ,CONNECTORS REPLACE DAMAGED LAMPS REVERSE SENSORS.		180.00	30.00
	TO CARRY OUT DIAGNOSTIC TEST.		500.00	100.00
	TO REMOVE AND REPLACE EXHAUST SILENCER AND PIPES.		580.00	200.00
	TRANSFER DOOR MECHANISM .		180.00	50.00
	REMOVE & REPLACE FENDER 1/4 GLASS .		190.00	80.00

Report Ref No. CC4/FCI20001010/Eea3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE REAR UNDERCARRIAGE PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING REPLACING AFFECTED UNDERCARRIAGE PARTS AND PERFORM COMPUTERISED ALIGNMENT AND STEERING ALIGNMENT (STEERING ANGLE ZEROING).		1,000.00	100.00
			9,170.00	3,810.00
<b>GRAND TOTAL</b>			<b>49,535.50</b>	<b>22,368.04</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>22,368.04</b>

Report Ref No. CC4/FCI20001010/Eea3n2

**CHEN TSUE YEE**

**Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.