

REF: CS/TP 20001011/K+302

ASSIGNMENT

30/NOV/2010  
~~16/11~~

Kenneth

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cob

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record) \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 26 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHD 5260K Yr Regn. \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toy with A C.C. 1987

Colour: White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 138369 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 3TDG1320W404003045

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 3/11/2014

Survey held at \_\_\_\_\_

Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame & Body Structure affected due to collision. ✓

Date / Time	Action / Instruction
	SHD 5260K - CS/A/A 110-24030/KHC 302 P/A - 30/11/2011
	Lump Sum \$19,000 (Red: 107819.65; 85%)
	RECEIVED 17 JAN 2020

117x15 = 1755

Date/Time, File Pass to?	Date/Time, File Return to?
1) <u>11/11/10</u> <u>Tupist</u>	2) _____
3) _____	4) _____
5) _____	6) _____

TOTAL LOSS

KIV FOR LOD

Survey Fee:	Date:
Basic & Add.	<u>1701766</u>
S + RS. SI	<u>50</u>
Photo	<u>50</u>
Other	<u>80</u>
TOTAL	<u>2106</u>

## Denise Tay (LKKAuto)

---

**From:** claims <claims@transcab.com.sg>  
**Sent:** Wednesday, 27 February 2019 10:30 AM  
**To:** SUR  
**Cc:** claims@transcab.com.sg  
**Subject:** FW: Request of Survey report-your ref no: AAD1410-337 / our Ref: D14012490MFSH;accident involving SHA7509D and SHD5860K on 27-10-2014  
**Attachments:** AAD1410-337 EST MARKING.pdf, SHD5860K 27.10.2014 - GIA.pdf

Dear Sir/Mdm

This is a past 2014 case.

Could you forward us a copy of the survey report/invoice in order for us to make payment?

Addition information.

Accident involving SHD5850K & SHA7509D.  
Location Alexandra Road X Depot Road  
DOA 27/10/2014  
Manufacturer: Toyota  
Model WISH-2.0 (A)

Attached GIA report and estimate marking for your reference.

Thank You  
Best Regards,  
Calvin Er  
Finance Department  
TEL: 6603 1265 Ext.307

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Tuesday, 26 February, 2019 10:48 PM  
**To:** claims@transcab.com.sg  
**Cc:** Serene Ler <Sereneler@msfirstcapital.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>  
**Subject:** Request of Survey report-your ref no: AAD1410-337 / our Ref: D14012490MFSH;accident involving SHA7509D and SHD5860K on 27-10-2014

Without Prejudice

Dear Sir,

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 16 January 2020 10:46 AM  
**To:** Ng Wai Yin  
**Subject:** RE: Request of Survey report-your ref no: AAD1410-337 / our Ref: D14012490MFSH;accident involving SHA7509D and SHD5860K on 27-10-2014

Dear Wai Yin,

Sorry ah ask you what date did Kenneth survey?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Wai Yin <[waiyin.ng@transcab.com.sg](mailto:waiyin.ng@transcab.com.sg)>  
**Sent:** Thursday, 16 January 2020 10:43 AM  
**To:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Subject:** RE: Request of Survey report-your ref no: AAD1410-337 / our Ref: D14012490MFSH;accident involving SHA7509D and SHD5860K on 27-10-2014

Morning Denise

Amount confirmed \$ 19,000 (before GST).

Chassis Number : VF1ABL15AUC281606

Please proceed to send us the survey report as soon.

Thank You

Best Regards,

**Ng Wai Yin**

Finance Department

TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63

Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

---

**From:** Denise Tay (LKKAuto) [<mailto:denisetay@lkkauto.com>]  
**Sent:** Wednesday, 15 January, 2020 9:30 AM  
**To:** Ng Wai Yin <[waiyin.ng@transcab.com.sg](mailto:waiyin.ng@transcab.com.sg)>  
**Subject:** RE: Request of Survey report-your ref no: AAD1410-337 / our Ref: D14012490MFSH;accident involving SHA7509D and SHD5860K on 27-10-2014

## Denise Tay (LKKAuto)

---

**From:** claims <claims@transcab.com.sg>  
**Sent:** Friday, 21 June 2019 8:53 AM  
**To:** Denise Tay (LKKAuto)  
**Cc:** SUR  
**Subject:** RE: Request of Survey report-your ref no: AAD1410-337 / our Ref: D14012490MFSH;accident involving SHA7509D and SHD5860K on 27-10-2014

Dear Denise

Apologise for the delay.

3. Book Value? -\$44,635.85

Thank You  
Best Regards,  
Calvin Er  
Finance Department  
TEL: 6603 1265 Ext.307

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** claims [mailto:claims@transcab.com.sg]  
**Sent:** Monday, 29 April, 2019 5:53 PM  
**To:** 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>  
**Cc:** 'SUR' <sur@lkkauto.com>  
**Subject:** RE: Request of Survey report-your ref no: AAD1410-337 / our Ref: D14012490MFSH;accident involving SHA7509D and SHD5860K on 27-10-2014

Dear Denise

2 No  
3 book value- will check with jasmine before I reply back to you.

Thank You  
Best Regards,  
Calvin Er  
Finance Department  
TEL: 6603 1265 Ext.307

10 Sin Ming Drive Singapore 575701  
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref 2201150601N033262256

22 Jan 2015

TRANS-CAB SERVICES PTE LTD  
58 DEFU LANE 1  
DEFU INDUSTRIAL ESTATE  
SINGAPORE 539498



Dear M/S TAN LEE TIANG

#### DE-REGISTRATION STATUS OF VEHICLE SHD5860K

The above-mentioned vehicle was de-registered on 22 Jan 2015. We have granted the following rebate(s), where applicable, to you. You may utilise the rebate(s) if you have settled all outstanding matters, eg. road tax arrears, on the vehicle and have submitted satisfactory documentary proof of disposal of your de-registered vehicle to the LTA.

PARF Rebate Amount	: \$11,274.00
PARF Rebate Reference No.	: 1504387MP0000
Expiry Date of PARF Rebate	: 21 Jan 2016
COE Rebate Amount	: \$11,558.00
COE Rebate Reference No.	: 1504387MC0000
Expiry Date of COE Rebate	: 21 Jan 2016

2. The PARF rebate may only be used to offset the Additional Registration Fee (ARF), Registration Fee (RF), Quota Premium (QP) and Used Car Surcharge, where applicable, of a motor car to be registered in your name. The COE rebate may be used to offset the ARF, RF, QP and Used Car Surcharge, where applicable, of any motor vehicle to be registered in your name. The COE rebate can also be used to offset the Prevailing Quota Premium (PQP) payable for revalidating the COE of a vehicle that is currently registered in your name. You may also transfer the PARF/COE rebate(s) together or separately to a third party. A fee of \$10.00 is payable for each transfer.

3. Alternatively, you may apply to encash the PARF/COE rebate(s) before the expiry of the rebate(s). You are encouraged to login to your e-Services@ONE.MOTORING user account to apply online for the encashment. You can also download the application form (Form FR02) for encashment of the rebate(s) from <http://www.onemotoring.com.sg>. Please mail the completed Form FR02 to LTA, 10 Sin Ming Drive, Singapore 575701, Attn: VRL Service Operations Division, at least 2 weeks before the expiry date of your PARF/COE rebate(s).

4. Any unused portion of the road tax will be refunded to you automatically.

5. Please note that a separate PIN is required for the following transactions via the Internet or at our Electronic Service Agents. Before you perform these transactions, please request for your PIN via <http://www.onemotoring.com.sg> or visit our office at 10 Sin Ming Drive, Singapore 575701, VRL Service Operations Division.

- a. Vehicle PIN - Transfer of Ownership and De-registration of Vehicle
- b. TCOE PIN - Transfer of TCOE (For Category C and E COE bid under individual)
- c. Rebate PIN - Transfer and Splitting of PARF/COE Rebate

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/10/2014 17:13
Date Of Accident	27/10/2014 06:15
Exact Location Of Accident	Alexandra Road X Depot Road
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5860K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi

### Insurance Company

Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/3031
Cover Note Number	

### Driver

Name of Driver	LIEW KIM CHOR
NRIC No	S1747138D
Date Of Birth	22/09/1966
Occupation	Outdoor
Date Of Driving Pass	18/03/1985
Driving Experience	29 Years And 7 Months
Gender	Male
Mobile Number	(Local) +65-87263265
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 19 JALAN TENTERAM #28-144
Postcode	321019

Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Other - Hirer
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	Collision- Traffic Light Junction
Weather Conditions	Clear
Road Surface	Dry

#### Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	Yes

#### Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Traffic Police Division Hq
Police Station Address	ROAD: 10 Ubi Avenue 3 , POSTCODE: 408865 , COUNTRY: Singapore
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	No
If Yes, against whom?	

#### Circumstances of Accident

Please refer to Police Report - T/20141030/4069	
Are accident photos available for attachment?	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7509D
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF INJURED PERSON 1

Name	LIEW KIM CHOR
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD5860K
Were seat belts worn?	Yes
Was injured conveyed to hospital by ambulance?	Yes

Address  
Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Handwritten Signature]*


*[Handwritten Signature]*

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: SHD 5860K  
B: SHA 7509D



Police Report Pg.1

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20141030/4069

1 of 3

Report No. T/20141030/4069

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/10/2014 14:46		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: LIEW KIM CHOR			Address: APT BLK 19 JALAN TENTERAM #28-144 SINGAPORE 321019		
ID Type / ID No.: NRIC NO / S1747138D			Contact No.:		Mobile: 87263265
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 22/09/1966	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 3		Date of Expiry:

<b>General Information of the Accident:</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 27/10/2014 06:15	Type of Location:
Location: Along Road 1 ALEXANDRA ROAD  TOWARDS PASIR PANJANG, JUNCTION OF DEPOT ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHA7509D	Car				Seriously Damaged	0
SHD5860K	Car				Seriously Damaged	0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report Pg.1

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20141030/4069

2 of 3

Report No. T/20141030/4069

CONTINUATION OF REPORT

Driver			
Name	LIEW KIM CHOR	ID No.	S1747138D
Related Vehicle	SHD5860K (Car)	Contact No.	87263265
Hospital/Clinic	ALEXANDRA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	11	Degree of Injury	NIL

**Brief Details.**

ON THE ABOVE DATE, TIME AND LOCATION MENTIONED

I WAS TRAVELLING ALONG ALEXANDRA ROAD WHEREBY I WAS DRIVING STRAIGHT TOWARDS PASIR PANJANG. SUDDENLY FROM THE OTHER SIDE OF THE ROAD THERE WAS THIS TAXI (SHA7509D) DASH THROUGH THE ROAD AND HAD COLLIDED FRONT LEFT PORTION OF MY TAXI. THE GREEN LIGHT WAS IN MY FAVOUR. I HAVE THE VIDEO FOOTAGE ON MY HANDPHONE AND ALSO INSIDE MY TAXI THERE WAS AN IN-BILT CAMERA AND IT WAS CLEAR. I WAS INJURED AND CONVEYED TO ALEXANDRA HOSPITAL. THATS ALL.

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20141030/4069

3 of 3

Report No. T/20141030/4069

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / MUHAMMAD FARID BIN SANUSI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/10/2014 14:46
Officer In Charge Of Case: TP / GIT / MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No.: 65476367	Classification Of Case:
Authentication Stamp NP168	 Signature: SINGAPORE POLICE FORCE

Accident Photo



Accident Photo



Accident Photo



Accident Photo



**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 S JNGEI KADUT ET 1 SINGAPORE 729348  
 TEL NO.8287 6668 FAX NO.8366 8862  
 CO/GST REG NO.201019626G  
**SHD 5860K - FCIL**

ROEL

*Not Authorised*  
*U/Say @ ?*  
*Book Value, T/loss ??*

Vehicle No.: SHD 5860K - ROEL  
 Chassis No.: JTDGJ20W405003045\*  
 Vehicle Make: TOYOTA  
 Vehicle Model: WISH 2.0 BI-FUEL  
 Date of Accident : 27.10.2014  
 Third Party Insurer : FCIL

PART		LIST
1	1 Front Bumper	Tn 585.36 ✓
2	1 Front Bumper Lower Absorber	Tn 130.00 ✓
3	1 Front Bumper Reinforcement	Bn 318.11 ✓
4	1 Front Bumper Side Support LH	CMA 76.20 ✓
5	1 Front Bumper Side Support RH	Mil 76.20 ✓
6	1 Front Bumper Retainer RH	CDA 102.00 ✓
7	1 Front Bumper Retainer LH	CMA 102.00 ✓
8	1 Front Bumper Bracket RH	Bt 108.00 ✓
9	1 Front Bumper Bracket LH	Bt 108.00 ✓
10	1 Front Bumper Fog Lamp RH	Mj CM 208.00 ✓
11	1 Front Bumper Fog Lamp Outer Chrome RH	CM 190.00 ✓
12	1 Front Bumper Fog Lamp Grille RH	CM 150.00 ✓
13	1 Front Bumper Fog Lamp LH	Bo 208.00 ✓
14	1 Front Bumper Fog Lamp Outer Chrome LH	Mil 190.00 ✓
15	1 Front Bumper Fog Lamp Grille LH	Mil 150.00 ✓
16	1 Front Bumper Fog Lamp Protector Grille	NIP 100.00 X
17	1 Front Headlamp RH	Mj CM 672.00 ✓
18	1 Headlamp RH inner panel	NIP 732.00 X
19	1 Front Headlamp LH	Bo 672.00 ✓
20	1 Headlamp LH inner panel	NIP 732.00 X
21	1 Front Support Panel Assy	Bt 1,222.32 ✓
22	1 Front Brace Panel	Bt 95.49 ✓
23	1 Horn unit	Nd 125.00 ✓
24	1 Horn high pitch / low pitch	RA 150.00 ✓
25	1 Bonnet	Bt 1,019.16 ✓
26	1 Bonnet Under Weatherstrip Seal	Tn 71.99 ✓
27	1 Bonnet Hinge RH	Bt 81.60 ✓
28	1 Bonnet Hinge LH	Bt 81.60 ✓
29	1 Bonnet Moulding	NIP 194.36 X
30	1 Bonnet Lock	Bt 90.02 ✓
31	1 Bonnet Centre 'TOYOTA' Logo Badge	Nu 115.44 ✓
32	1 Bonnet Insulator	26.7 Tn 524.06 ✓ 50 Wn
33	1 Bonnet Damper Stay	NIP 239.05 X

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGAI KADUT ST 1 SINGAPORE 729346  
 TEL NO 6287 6666 FAX NO.6368 8862  
 CO/GST REG NO.201019628G  
**SHD 5360K - FCIL**

**ROEL**

34	1	Front Fender RH	\$
35	1	Front Fender Liner RH	\$
36	1	Front Fender Indicator Lamp RH	\$
37	1	Front Fender Inner Wheel House Panel RH	\$
38	1	Front Fender LH	\$
39	1	Front Fender Liner LH	\$
40	1	Front Fender Indicator Lamp LH	\$
41	1	Front Fender Inner Wheel House Panel LH	\$
42	1	Front Windscreen	\$
43	1	Front Windscreen Moulding	\$
44	1	Radiator Assembly	\$
45	1	Radiator Grille	\$
46	1	Radiator Fan Blade	\$
47	1	Aircon Fan Blade	\$
48	1	Radiator Cowling	\$
49	1	Radiator Fan Motor	\$
50	1	Aircon Fan Motor	\$
51	1	Radiator Expansion Tank	\$
52	1	Radiator Y - Pipe	\$
53	1	Aircon Condenser	\$
54	1	Aircon hose - condenser to compressor	\$
55	1	Aircon hose - compressor to evaporator	\$
56	1	Aircon hose - condenser to evaporator	\$
57	1	Aircon compressor - pump	\$
58	1	Aircon compressor bracket	\$
59	1	Windscreen Washer Tank - Filler Neck	\$
60	1	Windscreen Washer Tank	\$
61	1	Windscreen Washer Tank Motor	\$
62	1	Front Door RH	\$
63	1	Fuse Box Top (Cover)	\$
64	1	Fuse Box Lower	\$
65	1	Fuse Box Centre	\$
66	1	Fuse Box Centre Cover	\$
67	1	Engine Cover ( Top )	\$
68	1	Intake Manifold	\$
69	1	Air Cleaner Assembly	\$
70	1	Air-Cleaner Intake Duct	\$
71	1	Air-cleaner intake hose	\$
72	1	V-belt	\$
73	1	Front shock absorber assy LH	\$
74	1	Front shock absorber top mounting LH	\$
75	1	Front shock absorber assy RH	\$

Br	837.60	—
Tn	369.14	—
Sn	95.80	X
Bt	714.86	—
Bt	369.14	—
CMT	369.14	—
Sn	95.80	X
Bt	714.86	—
CMT	1,406.64	—
Br	86.40	—
Bt	2,268.24	—
CMT	462.48	—
Bro	223.95	—
NIP	223.95	X
CMT	221.73	—
Tn	372.76	—
NIP	372.76	X
Br	180.76	—
Sn	98.50	X
Bt	1,375.50	—
Sn	389.51	X
Sn	521.93	X
Sn	216.00	X
Br	3,200.00	X
Br	120.76	—
Br Sn	166.00	X
Sn	266.86	X
R	1,554.00	X
CMT	88.44	—
CMT	84.24	—
CMT	254.04	—
CMT	238.32	—
CMT	250.60	—
CMT	1,500.08	—
Bro	1,036.44	—
CMT	101.57	—
NIP	199.42	—
R	146.40	X
Sn	558.00	X
Sn	159.16	X
Sn	558.00	X

**TRANSI-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729348  
 TEL NO.6287 8888 FAX NO.6366 8862  
 CO/GST REG NO.201010826G  
**SHD 5050K - FCIL**

**ROEL**

Item No	Qty	Description	Unit	Price	Code
76	1	Front shock absorber top mounting RH	\$	159.16	X
77	1	Front lower arm RH	\$	620.57	X
78	1	Front lower arm LH	\$	620.57	X
79	1	Front knuckle arm RH	\$	490.74	X
80	1	Front knuckle arm LH	\$	490.74	X
81	1	Steering rack & pinion assy	\$	3,167.33	X
82	1	Steering rack end	\$	246.50	X
83	1	Steering rack & pinion bushing	\$	30.00	X
84	1	Bracket-strg rack no 1 (s10/12)	\$	55.14	X
85	1	Bracket-strg rack no 2 (s10/12)	\$	37.42	X
86	1	Steering tie-rod end	\$	127.44	X
87	1	Power steering pump	\$	5,664.96	X
88	1	Power steering belt	\$	251.33	X
89	1	Power steering reservoir tank	\$	394.62	X
90	1	Power steering inlet / outlet pipe	\$	518.04	X
91	1	Power steering pump pulley	\$	235.68	X
92	1	Power steering hose - pressure	\$	361.68	X
93	1	Power steering hose - non pressure	\$	494.28	X
94	1	Front chassis member/frame	\$	1,550.70	X
95	1	Engine block	\$	9,512.81	X
96	1	Engine main harness wire	\$	1,947.93	✓
97	1	Engine splash cover RH	\$	178.20	✓
98	1	Engine splash cover LH	\$	178.20	✓
99	1	Engine oil sump	\$	350.04	X
100	1	Engine oil sump strainer	\$	115.68	X
101	1	ECU assy	\$	4,584.24	✓
102	1	ABS pump	\$	5,679.60	X
103	1	ABS pump pipe	\$	82.08	X
104	1	Alternator assembly	\$	2,657.64	X
105	1	Gear box assy	\$	16,629.60	X
106	1	Gear box cross member	\$	1,454.28	X
107	1	Gear box cross member Center	\$	539.76	✓
108	1	Gear box mountingRR	\$	349.68	X
109	1	Gear box mounting FRT	\$	189.60	X
110	1	Engine mounting side LH	\$	209.58	X
111	1	Engine mounting RH	\$	254.28	X
112	1	Front Seat Belt RH	\$	862.20	✓
113	1	Front safety belt cover garnish RH	\$	253.68	X
114	1	Front Seat Belt tension RH	\$	126.01	X
115	1	Front Seat Belt LH	\$	862.20	✓
116	1	Front safety belt cover garnish LH	\$	253.68	X
117	1	Front Seat Belt tension LH	\$	126.01	X

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SIJNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.3287 6666 FAX NO.6366 8882  
 CO/GST REG NO.201016826G  
**SHD 5860K - FCIL**

**ROEL**

118	1	Battery	\$	240.00	<i>50% in</i>
119	1	Battery fastener bracket	\$	37.26	<i>✓</i>
120	1	Driver's seat	\$	1,454.28	<i>X</i>
121	1	Drivers seat reclining mechanism	\$	3,599.76	<i>X</i>
122	1	Longitudinal FRT LH	\$	556.33	<i>X</i>
123	1	Longitudinal FRT RH	\$	554.33	<i>X</i>
124	1	Front Door LH	\$	1,554.00	<i>X</i>
125	1	Front Door hinge upper LH	\$	115.56	<i>X</i>
126	1	Front Door hinge lower LH	\$	115.56	<i>X</i>
127	1	Front side view mirror LH	\$	874.43	<i>X</i>
128	1	Front Door RH	\$	1,554.00	<i>X</i>
129	1	Front side view mirror RH	\$	874.43	<i>X</i>
130	1	Rear fender LH	\$	1,216.32	<i>✓</i>
131	1	Rear fender panel deck trim side LH	\$	738.00	<i>X</i>
132	1	Rear shock absorber LH	\$	373.68	<i>X</i>
133	1	Rear axle housing	\$	2,390.04	<i>X</i>
134	1	Rear bumper	\$	585.36	<i>✓</i>
135	1	Rear bumper side retainer RH	\$	68.76	<i>X</i>
136	1	Rear bumper side retainer LH	\$	68.76	<i>✓</i>
137	1	Rear bumper side support RH	\$	104.76	<i>X</i>
138	1	Rear bumper side support LH	\$	104.76	<i>X</i>
139	1	Rear bumper bracket RH	\$	108.00	<i>X</i>
140	1	Rear bumper bracket LH	\$	108.00	<i>X</i>
141	1	Rear bumper reflectors RH	\$	66.00	<i>X</i>
142	1	Rear bumper reflectors LH	\$	66.00	<i>X</i>
<b>TOTAL</b>			<b>\$</b>	<b>112,532.00</b>	
25%			\$	28,133.00	
			\$	84,399.00	

**Special Nett**

1 Set	Front Bumper Fastener Clip	\$	40.00	<i>✓</i>
1	CNG Sticker	\$	15.00	<i>✓</i>
1 Set	Front Fender Liner Clip LH	\$	30.00	<i>✓</i>
1 Set	Front Fender Liner Clip RH	\$	30.00	<i>✓</i>
2	Bonnet Stopper	\$	9.60	<i>✓</i>
1 Set	Bonnet Under Weatherstrip Seal Clips	\$	21.60	<i>✓</i>
1 Set	Bonnet Insulator Clip	\$	42.00	<i>✓</i>
1 Set	Bonnet Damper Stay Clip	\$	10.00	<i>✓</i>
1 Set	Horn High pitch / Low Pitch	\$	100.00	<i>X</i>
1 Set	Front Wiper Garnish / Wiper Grille Clips	\$	18.50	<i>✓</i>
1 Set	Front Wiper Clip	\$	10.68	<i>X</i>

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 S JNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.5287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201016626G  
**SHD 5160K - FCIL**

**ROEL**

1 Set Radiator Grille Clip	\$	na	18.00	✓
2 Can Radiator Coolant	\$	na	40.00	205na
2 Radiator Top Bracket Mounting	\$	Dis	33.84	✓
2 Radiator Lower Mounting Bushing	\$	na	18.43	✓
1 Front Licence Plate	\$	Dis	50.00	255na
1 Front Door Sticker 'Trans-Cab'	\$	na	60.00	X
1 Set Front Side Rocker Panel Garnish Clips	\$	na	18.00	X
1 Front Windscreen Sealant	\$	na	80.00	405na
1 Front Windscreen Inner Sponge Seal	\$	na	60.00	305na
1 Set Roof Lining Clips	\$	na	25.00	X
1 Front ERP Bracket	\$	na	50.00	265na
1 Front ERP Unit	\$	Sm	200.00	X
2 ERP Sticker	\$	Repair	10.00	X
1 Battery	\$	~	240.00	X
1 Air Filter	\$	Sm	36.00	X
1 Set Engine splash cover clip RH	\$	na	12.00	✓
1 Set Engine splash cover clip LH	\$	na	12.00	✓
1 Rear fender 1/4 glass inner sponge seal	\$	na	48.00	305na
1 Rear fender 1/4 glass sealant	\$	na	72.00	805na
1 Rear tyre LH	\$	Sm	190.00	X
1 Rear wheel rim LH	\$	Sm	150.00	X
1 Front tyre LH	\$	Sm	190.00	X
1 Front wheel rim LH	\$	Sm	150.00	X
1 Front tyre RH	\$	Sm	190.00	X
1 Front wheel rim RH	\$	Sm	150.00	X
1 Front fender advertisement sticker LH	\$	na	250.00	1505na
1 Front fender advertisement sticker RH	\$	na	250.00	1505na
1 Front door advertisement sticker LH	\$	na	250.00	X
1 Front door advertisement sticker RH	\$	na	250.00	X
1 Rear fender advertisement sticker LH	\$	na	250.00	1505na
1 Rear bumper advertisement sticker	\$	na	150.00	1005na
1 Door Sticker "TRANS-CAB" LH	\$	na	80.00	X
1 Door Sticker "TRANS-CAB" RH	\$	na	80.00	X

**TOTAL \$ 3,990.65**

**TOTAL PARTS \$ 88,389.65**

Panel Beating, Knocking And Straightening The  
 Necessary Portion, Remove And Renewal Of  
 Parts, Adjust And Realign The Same \$ 16,800.00 *3600*

**TRANSI-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGAI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHD 51160K - FCIL**

ROEL

To Check Electrical Lighting Concerned.	\$	120.00	60d
To Rust-Proofing Of The Affected Areas.	\$	200.00	210d
Putty And Spray Painting Of The Affected	\$	16,200.00	200d
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	350.00	120d
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	250d
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	260d
To remove and renew engine and gear box mounting.	\$	380.00	250d
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	X
To lift-up engine with gear box and refit.	\$	440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To check ABS brake efficiency, final chocking and testing.	\$	380.00	X
To remove and refit ABS pump relay to enable repair.	\$	380.00	80d
Towing Fees.	\$	120.00	50d
To Check Steering Geometry And Computer Wheel Alignment.	\$	200.00	60d
To Transfer Of Tire, Rim And On Wheel	\$	150.00	X
To Vacuum, Replace, Refix And Recharge Air Condenser	\$	350.00	100d

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGAI KADUT ST 1 SINGAPORE 728346  
 TEL NO.8287 6666 FAX NO.8368 8862  
 CO/GST REG NO.201010626G  
**SHD 51160K - FCIL**

ROEL

To Replace, Refix And Top Up Coolant For Radiator	\$	170.00 <i>50h</i>
To Dismantle And Refit Aircon Assy And Attachment, Vacuum And Charge-In-Gas.	\$	350.00 <i>100h</i>
To drop rear axle assy, remove and renewal of the necessary parts	\$	<i>nn</i> 380.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and replace corporate sticker	\$	330.00 <i>80h</i>
To Remove, Replace And Refit Front W/Screen Glass And Rear 1/4 Quarter Glass To Facilitate Bodywork Repair.	\$	380.00 <i>180h</i>

TOTAL	\$	<u>39,430.00</u>
-------	----	------------------

Over All Total	\$	<u>127,819.65</u>
----------------	----	-------------------

Total Repair Days	<del>60</del> DAYS <i>26/4/15</i>
-------------------	--------------------------------------

127819.65



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP20001011/KH3e2	
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 17-01-2020	
		Code : TP378	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SHD 5860K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/11/2014
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH (A)	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTDGJ20W405003045	Colour	WHITE / RED
Odometer	138369	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2014	Inspection Date	03/11/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		26 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Page No.:1 of 8

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5860K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	TORN	585.36	585.36
1	FRONT BUMPER LOWER ABSORBER	TORN	130.00	130.00
1	FRONT BUMPER REINFORCEMENT	BENT	318.11	318.11
1	FRONT BUMPER SIDE SUPPORT LH	CRACKED	76.20	76.20
1	FRONT BUMPER SIDE SUPPORT RH	MISSING	76.20	76.20
1	FRONT BUMPER RETAINER RH	CRACKED	102.00	102.00
1	FRONT BUMPER RETAINER LH	CRACKED	102.00	102.00
1	FRONT BUMPER BRACKET RH	BENT	108.00	108.00
1	FRONT BUMPER BRACKET LH	BENT	108.00	108.00
1	FRONT BUMPER FOG LAMP RH	MTG CRACKED	208.00	208.00
1	FRONT BUMPER FOG LAMP OUTER CHROME RH	CRACKED	190.00	190.00
1	FRONT BUMPER FOG LAMP GRILLE RH	CRACKED	150.00	150.00
1	FRONT BUMPER FOG LAMP LH	BROKEN	208.00	208.00
1	FRONT BUMPER FOG LAMP OUTER CHROME LH	MISSING	190.00	190.00
1	FRONT BUMPER FOG LAMP GRILLE LH	MISSING	150.00	150.00
1	FRONT BUMPER FOG LAMP PROTECTOR GRILLE	NO SUCH PARTS	100.00	-
1	FRONT HEADLAMP RH	MTG CRACKED	672.00	672.00
1	HEADLAMP RH INNER PANEL	NO SUCH PARTS	732.00	-
1	FRONT HEADLAMP LH	BROKEN	672.00	672.00
1	HEADLAMP LH INNER PANEL	NO SUCH PARTS	732.00	-
1	FRONT SUPPORT PANEL ASSY	BENT	1,222.32	1,222.32
1	FRONT BRACE PANEL	BENT	95.49	95.49
1	HORN UNIT	DENTED	125.00	125.00
1	HORN HIGH PITCH / LOWER PITCH	DENTED	150.00	150.00
1	BONNET	BENT	1,019.16	1,019.16
1	BONNET UNDER WEATHERSTRIP SEAL	TORN	71.99	71.99
1	BONNET HINGE RH	BENT	81.60	81.60
1	BONNET HINGE LH	BENT	81.60	81.60
1	BONNET MOULDING	NO SUCH PARTS	194.36	-
1	BONNET LOCK	BENT	90.02	90.02
1	BONNET CENTRE 'TOYOTA' LOGO BADGE	NECESSARY	115.44	115.44
1	BONNET DAMPER STAY	NO SUCH PARTS	239.05	-
1	FRONT FENDER RH	BUCKLED	837.60	837.60
1	FRONT FENDER LINER RH	TORN	369.14	369.14

Report Ref No. CS/TP20001011/Ktf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER INDICATOR LAMP RH	SERVICEABLE	95.80	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL RH	BENT	714.86	714.86
1	FRONT FENDER LH	BENT	369.14	369.14
1	FRONT FENDER LINER LH	CRACKED	369.14	369.14
1	FRONT FENDER INDICATOR LAMP LH	SERVICEABLE	95.80	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	BENT	714.86	714.86
1	FRONT WINDSCREEN	CRACKED	1,406.64	1,406.64
1	FRONT WINDSCREEN MOULDING	NECESSARY	86.40	86.40
1	RADIATOR ASSEMBLY	BENT	2,268.24	2,268.24
1	RADIATOR GRILLE	CRACKED	462.48	462.48
1	RADIATOR FAN BLADE	BROKEN	223.95	223.95
1	AIRCON FAN BLADE	NO SUCH PARTS	223.95	-
1	RADIATOR COWLING	CRACKED	221.73	221.73
1	RADIATOR FAN MOTOR	JAMMED	372.76	372.76
1	AIRCON FAN MOTOR	NO SUCH PARTS	372.76	-
1	RADIATOR EXPANSION TANK	DENTED	180.76	180.76
1	RADIATOR Y - PIPE	SERVICEABLE	98.50	-
1	AIRCON CONDENSER	BENT	1,375.50	1,375.50
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	SERVICEABLE	389.51	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	SERVICEABLE	521.93	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	216.00	-
1	AIRCON COMPRESSOR - PUMP }	SERVICEABLE	3,200.00	-
1	AIRCON COMPRESSOR BRACKET }		-	-
1	WINDSCREEN WASHER TANK - FILLER NECK	DENTED	120.76	120.76
1	WINDSCREEN WASHER TANK	DENTED	166.00	166.00
1	WINDSCREEN WASHER TANK MOTOR	SERVICEABLE	266.86	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,554.00	-
1	FUSE BOX TOP (COVER)	CRACKED	88.44	88.44
1	FUSE BOX LOWER	CRACKED	84.24	84.24
1	FUSE BOX CENTRE	CRACKED	254.04	254.04
1	FUSE BOX CENTRE COVER	CRACKED	238.32	238.32
1	ENGINE COVER (TOP)	CRACKED	250.60	250.60
1	INTAKE MANIFOLD	CRACKED	1,500.08	1,500.08
1	AIR CLEANER ASSEMBLY	BROKEN	1,036.44	1,036.44
1	AIR-CLEANER INTAKE DUCT	CRACKED	101.57	101.57



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR-CLEANER INTAKE HOSE	MISSING	199.42	199.42
1	V-BELT	SERVICEABLE	146.40	-
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	558.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	SERVICEABLE	159.16	-
1	FRONT SHOCK ABSORBER ASSY RH	SERVICEABLE	558.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	SERVICEABLE	159.16	-
1	FRONT LOWER ARM RH	SERVICEABLE	620.57	-
1	FRONT LOWER ARM LH	SERVICEABLE	620.57	-
1	FRONT KNUCKLE ARM RH	SERVICEABLE	490.74	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	490.74	-
1	STEERING RACK & PINION ASSY	TO REPAIR SEE LABOUR	3,167.33	-
1	STEERING RACK END	SERVICEABLE	246.50	-
1	STEERING RACK & PINION BUSHING	SERVICEABLE	30.00	-
1	BRACKET-STRG RACK NO 1 (S10/S12)	SERVICEABLE	55.14	-
1	BRACKET-STRG RACK NO 2 (S10/S12)	SERVICEABLE	37.42	-
1	STEERING TIE-ROD END	SERVICEABLE	127.44	-
1	POWER STEERING PUMP	NO SUCH PARTS	5,664.96	-
1	POWER STEERING BELT	NO SUCH PARTS	251.33	-
1	POWER STEERING RESERVOIR TANK	NO SUCH PARTS	394.62	-
1	POWER STEERING INLET / OUTLET PIPE	NO SUCH PARTS	518.04	-
1	POWER STEERING PUMP PULLEY	NO SUCH PARTS	235.68	-
1	POWER STEERING HOSE - PRESSURE	NO SUCH PARTS	361.68	-
1	POWER STEERING HOSE - NON PRESSURE	NO SUCH PARTS	494.28	-
1	FRONT CHASSIS MEMBER / FRAME	TO REPAIR SEE LABOUR	1,550.70	-
1	ENGINE BLOCK	SERVICEABLE	9,512.81	-
1	ENGINE MAIN HARNESS WIRE	TORN	1,947.93	1,947.93
1	ENGINE SPLASH COVER RH	CRACKED	178.20	178.20
1	ENGINE SPLASH COVER LH	CRACKED	178.20	178.20
1	ENGINE OIL PUMP	SERVICEABLE	350.04	-
1	ENGINE OIL SUMP STRAINER	SERVICEABLE	115.68	-
1	ECU ASSY	BENT	4,584.24	4,584.24
1	ABS PUMP	SERVICEABLE	5,679.60	-
1	ABS PUMP PIPE	SERVICEABLE	82.08	-
1	ALTERNATOR ASSEMBLY	SERVICEABLE	2,657.64	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GEAR BOX ASSY	TO REPAIR SEE LABOUR	16,629.60	-
1	GEAR BOX CROSS MEMBER	SERVICEABLE	1,454.28	-
1	GEAR BOX CROSS MEMBER CENTER	BUCKLED	539.76	539.76
1	GEAR BOX MOUNTINGRR	SERVICEABLE	349.68	-
1	GEAR BOX MOUNTING FRT	SERVICEABLE	189.60	-
1	ENGINE MOUNTING SIDE LH	SERVICEABLE	209.58	-
1	ENGINE MOUNTING RH	SERVICEABLE	254.28	-
1	FRONT SEAT BELT RH	JAMMED	862.20	862.20
1	FRONT SAFETY BELT COVER GARNISH RH	SERVICEABLE	253.68	-
1	FRONT SEAT BELT TENSION RH	SERVICEABLE	126.01	-
1	FRONT SEAT BELT LH	JAMMED	862.20	862.20
1	FRONT SAFETY BELT COVER GARNISH LH	SERVICEABLE	253.68	-
1	FRONT SEAT BELT TENSION LH	SERVICEABLE	126.01	-
1	BATTERY FASTENER BRACKET	DISTORTED	37.26	37.26
1	DRIVER'S SEAT	TO REPAIR SEE LABOUR	1,454.28	-
1	DRIVERS SEAT RECLINING MECHANISM	TO REPAIR SEE LABOUR	3,599.76	-
1	LONGITUDINAL FRT LH	SERVICEABLE	556.33	-
1	LONGITUDINAL FRT RH	SERVICEABLE	554.33	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,554.00	-
1	FRONT DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	115.56	-
1	FRONT DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	115.56	-
1	FRONT SIDE VIEW MIRROR LH	SERVICEABLE	874.43	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,554.00	-
1	FRONT SIDE VIEW MIRROR RH	SERVICEABLE	874.43	-
1	REAR FENDER LH	BENT	1,216.32	1,216.32
1	REAR FENDER PANEL DECK TRIM SIDE LH	SERVICEABLE	738.00	-
1	REAR SHOCK ABSORBER LH	SERVICEABLE	373.68	-
1	REAR AXLE HOUSING	TO REPAIR SEE LABOUR	2,390.04	-
1	REAR BUMPER	BUCKLED	585.36	585.36
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	68.76	68.76

Report Ref No. CS/TP20001011/K1f3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SIDE SUPPORT RH	SERVICEABLE	104.76	-
1	REAR BUMPER SIDE SUPPORT LH	SERVICEABLE	104.76	-
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	108.00	-
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	108.00	-
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	66.00	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	66.00	-
	LESS 25% DISCOUNT		-27,941.99	-8,043.01
			83,825.95	24,129.02
1	BONNET INSULATOR (SN) (50%)	TORN	524.06	262.03
1	BATTERY (SN) (50%)	DENTED	240.00	120.00
	LESS 25% DISCOUNT		-191.02	-
			573.04	382.03
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	40.00	40.00
1	CNG STICKER (SN)	NECESSARY	15.00	15.00
1	SET FRONT FENDER LINER CLIP LH (SN)	NECESSARY	30.00	30.00
1	SET FRONT FENDER LINER CLIP RH (SN)	NECESSARY	30.00	30.00
2	BONNET STOPPER (SN)	MISSING	9.60	9.60
1	SET BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NECESSARY	21.60	21.60
1	SET BONNET INSULATOR CLIP (SN)	NECESSARY	42.00	42.00
1	SET BONNET DAMPER STAY CLIP (SN)	NECESSARY	10.00	10.00
1	SET HORN HIGH PITCH / LOW PITCH (SN)	NOT NECESSARY	100.00	-
1	SET FRONT WIPER GARNISH / WIPER GRILLE CLIPS (SN)	NECESSARY	18.50	18.50
1	SET FRONT WIPER CLIP (SN)	NOT NECESSARY	10.68	-
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	18.00	18.00
2	CAN RADIATOR COOLANT (SN)	NECESSARY	40.00	20.00
2	RADIATOR TOP BRACKET MOUNTING (SN)	DISTORTED	33.84	33.84
2	RADIATOR LOWER MOUNTING BUSHING (SN)	NECESSARY	18.43	18.43
1	FRONT LICENCE PLATE (SN)	DENTED	50.00	25.00
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	60.00	-
1	SET FRONT SIDE ROCKER PANEL GARNISH CLIPS (SN)	NOT NECESSARY	18.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	60.00	30.00

Report Ref No. CS/TP20001011/Ktf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET ROOF LINING CLIPS (SN)	NOT NECESSARY	25.00	-
1	FRONT ERP BRACKET (SN)	NECESSARY	50.00	26.00
1	FRONT ERP UNIT (SN)	SERVICEABLE	200.00	-
2	ERP STICKER (SN)	REPEATED	10.00	-
1	BATTERY (SN)	REPEATED	240.00	-
1	AIR FILTER (SN)	SERVICEABLE	36.00	-
1	SET ENGINE SPLASH COVER CLIP RH (SN)	NECESSARY	12.00	12.00
1	SET ENGINE SPLASH COVER CLIP LH (SN)	NECESSARY	12.00	12.00
1	REAR FENDER 1/4 GLASS INNER SPONGE SEAL (SN)	NECESSARY	48.00	30.00
1	REAR FENDER 1/4 GLASS SEALANT (SN)	NECESSARY	72.00	40.00
1	REAR TYRE LH (SN)	SERVICEABLE	190.00	-
1	REAR WHEEL RIM LH (SN)	SERVICEABLE	150.00	-
1	FRONT TYRE LH (SN)	SERVICEABLE	190.00	-
1	FRONT WHEEL RIM LH (SN)	SERVICEABLE	150.00	-
1	FRONT TYRE RH (SN)	SERVICEABLE	190.00	-
1	FRONT WHEEL RIM RH (SN)	SERVICEABLE	150.00	-
1	FRONT FENDER ADVERTISEMENT STICKER LH (SN)	NECESSARY	250.00	150.00
1	FRONT FENDER ADVERTISEMENT STICKER RH (SN)	NECESSARY	250.00	150.00
1	FRONT DOOR ADVERTISEMENT STICKER LH (SN)	NOT NECESSARY	250.00	-
1	FRONT DOOR ADVERTISEMENT STICKER RH (SN)	NOT NECESSARY	250.00	-
1	REAR FENDER ADVERTISEMENT STICKER LH (SN)	NECESSARY	250.00	150.00
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NECESSARY	150.00	100.00
1	DOOR STICKER "TRANS-CAB" LH (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "TRANS-CAB" RH (SN)	NOT NECESSARY	80.00	-
			3,990.65	1,071.97
	<b>LABOUR</b>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH, STEERING RACK & PINION ASSY, FRONT CHASSIS MEMBER / FRAME, GEAR BOX ASSY, DRIVER'S SEAT, DRIVERS SEAT RECLINING MECHANISM, FRONT DOOR LH, FRONT DOOR HINGE UPPER LH, FRONT DOOR HINGE LOWER LH, FRONT DOOR RH, REAR AXLE HOUSING, REAR BUMPER BRACKET RH AND REAR BUMPER BRACKET LH.		16,800.00	3,600.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		210.00	210.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED.		16,200.00	2,000.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		350.00	120.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		380.00	250.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	260.00
	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING.		380.00	250.00
	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	REPEATED	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR.		380.00	80.00
	TOWING FEES.		120.00	50.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		200.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL.	NOT NECESSARY	150.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		350.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS.		350.00	100.00
	TO DROP REAR AXLE ASSY, REMOVE AND RENEWAL OF THE NECESSARY PARTS.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REPLACE CORPORATE STICKER.		330.00	80.00
	TO REMOVE, REPLACE AND REFIT FRONT W/SCREEN GLASS AND REAR 1/4 QUARTER GLASS TO FACILITATE BODYWORK REPAIR.		380.00	180.00
			39,440.00	7,450.00
<b>GRAND TOTAL</b>			<b>127,829.64</b>	<b>33,033.02</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>19,000.00</b>



Report Ref No. CS/TP20001011/Ktf3e2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.**