

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001022/UES3Q2

Date: 20/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700078848

Claimant
Vehicle No : SLT1343G **Insured Vehicle No :** SLU4407G

Date of Loss: 20/12/2019 Nature of Claim: TP Claim No: 2543734287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1343G	Engine No:	G4FGHH682715
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFJ411MJ5747705
Reg. Date:	19/10/2017 (Man. Year: 2017)	Odometer:	124605 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,158.00	2,141.10	2,016.90	48.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,075.00	985.00	1,090.00	52.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,233.00	3,126.10	3,106.90	49.85
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	6,233.00	2,500.00	3,733.00	59.89
+ GST 7.00/7.00% (S\$)	436.31	175.00	261.31	59.89
Nett Amount (S\$)	6,669.31	2,675.00	3,994.31	59.89
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,998.00		

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 23/12/2019 Inspected At:

NPH Auto Service (HQ)
Blk 9005 Tampines Steet 93, #01-
246/254
Singapore 528839

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent / Dented	1,083.00 F	*1,083.00 FL
2	1		*FRONT DOOR LH HINGE TOP	Twisted	45.00 F	*45.00 FL
3	1		*FRONT DOOR LH HINGE LOWER	Twisted	45.00 F	*45.00 FL
4	1		*FRONT DOOR CHECK LH	Not Necessary	55.00 F	*- FL
5	1		*FRONT DOOR INNER FINISHER LH	Not Necessary	125.00 F	*- FL
6	1		*FRONT FENDER LH	Dented	353.00 F	*353.00 FL
7	1		*FRONT FENDER INDICATOR LAMP LH	Not Necessary	38.00 F	*- FL
8	1		*FRONT FENDER INNER STAND GARNISH LH	Torn	35.00 F	*35.00 FL
9	1		*FRONT FENDER INNER COWLING LH	Not Necessary	95.00 F	*- FL
10	1		*FRONT DOOR SIDE MIRROR ASSY LH	Grazed	511.00 F	*511.00 FL
11	1		*FRONT LOWER ARM LH	Not Necessary	258.00 F	*- FL
12	1		*FRONT KNUCKLE LH	Not Necessary	340.00 F	*- FL
13	1		*FRONT KNUCKLE BEARING LH	Not Necessary	108.00 F	*- FL
14	1		*FRONT SHOCK ABSORBER LH	Not Necessary	280.00 F	*- FL
15	1		*FRONT DOOR WEATHERSTRIP RUBBER LH	Necessary	125.00 F	*125.00 FL
16	2		*FRONT DOOR BLACK STICKER	Necessary	110.00 F	*110.00 FL
17	10		*FRONT FENDER INNER COWLING CLIPS	Necessary	40.00 F	*40.00 FL
18	8		*FRONT DOOR INNER FINISHER CLIPS	Necessary	32.00 F	*32.00 FL
19	1		*FRONT SPORTS RIM LH	Repair	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,158.00	2,379.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	237.90
Total Parts (\$\$)	4,158.00	2,141.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND INSTALL UNDERCARRIAGE	New	250.00	0.00
2	WHEEL ALIGNMENT	New	100.00	60.00
3	REMOVE AND INSTALL FRONT BUMPER ,FRONT FENDER LH ,FENDER INNER COWLING ,FRONT DOOR LH ,INNER FINISHER ,KNOCKING DOOR PILLAR ,RUNNING BOARD SPOILER LH AND RESTRAIGHTEN BODY	New	900.00	400.00
4	SPRAY PAINTING	New	800.00	500.00
5	CHECK WIRING SYSTEM	New	25.00	25.00
Gross Labour Cost (\$\$)			2,075.00	985.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >