

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001025/AKS3Q2

Date: 24/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBD205G **Insured Vehicle No :** SLH7057G

Date of Loss: 13/01/2020 **Nature of Claim:** TP **Claim No:** 8756789031SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD205G		
Make & Model:	NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M)	Engine No:	K9KC400D053507
Reg. Date:	08/05/2014 (Man. Year: 2014)	Chassis No:	VSKYBAM20Z0077785
Colour:	Silver	Odometer:	163329 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,316.08	5,582.20	7,733.88	58.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	2,780.00	2,370.00	46.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,466.08	8,362.20	10,103.88	54.72
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	18,466.08	6,700.00	11,766.08	63.72
+ GST 7.00/7.00% (S\$)	1,292.63	469.00	823.63	63.72
Nett Amount (S\$)	19,758.71	7,169.00	12,589.71	63.72
+ Loss of Use (10.0 x S\$80.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		8,026.45		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 15/01/2020 Inspected At:

Mg Solution - Kaki Bukit (HQ)
23 KAKI BUKIT AVENUE 4, #04-01
Singapore 415933

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	2,130.90 FL	*1,545.00 FL
2	1		*REAR DOOR GLASS WITH MOULDING LH	Necessary	2,055.90 FL	*95.00 FL
3	1		*REAR DOOR RH	Dented	1,285.00 FL	*1,285.00 FL
4	1		*REAR DOOR GLASS WITH MOULDING RH	Necessary	920.00 FL	*85.00 FL
5	1		*REAR DOOR LOGO	Necessary	63.90 FL	*63.90 FL
6	1		*REAR DOOR EMBLEM NV200	Necessary	87.90 FL	*87.90 FL
7	4		*REAR DOOR HINGE	Not Necessary	398.40 FL	*- FL
8	2		*REAR DOOR CHECKER	Not Necessary	174.00 FL	*- FL
9	1		*REAR DOOR EMBLEM DCI	Necessary	87.90 FL	*87.90 FL
10	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	83.60 FL	*- FL
11	1		*REAR BUMPER	Deformed	566.80 FL	*566.80 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	105.80 FL	*105.80 FL
13	1		*REAR BUMPER SPONGE	Cracked	128.90 FL	*128.90 FL
14	1		*REAR BUMPER TOWING COVER	Not Necessary	63.00 FL	*- FL
15	2		*REAR BUMPER REFLECTOR	Cracked	104.60 FL	*104.60 FL
16	1		*REAR END PANEL	Dented	855.90 FL	*552.00 FL
17	1		*REAR END PANEL TOP GARNISH	Deformed	94.20 FL	*94.20 FL
18	1		*REAR END PANEL WEATHERSTRIP	Cut	124.20 FL	*124.20 FL
19	1		*DOOR LOCK BELOW LH	Damaged	135.00 FL	*135.00 FL
20	1		*DOOR LOCK BELOW RH	Damaged	135.00 FL	*135.00 FL
21	1		*REAR SPARE TYRE LOCK WITH BOLT	Not Necessary	262.30 FL	*- FL
22	2		*TAILLAMP	Cracked	561.80 FL	*561.80 FL
23	2		*TAIL LAMP PANEL	Repair	543.00 FL	*- FL
24	1		*REAR FLOOR PANEL	Repair	2,183.20 FL	*- FL
25	1		*REAR NUMBE PLATE	Not Necessary	20.00 FS	*- FS
26	1		*REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
27	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*REAR DOOR SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*REAR DOOR STICKER 70KM/H	Necessary	50.00 FS	*15.00 FS
30	1		*REAR DOOR STICKER 4PAX	Necessary	50.00 FS	*15.00 FS
31	2		*REAR DOOR GLASS SEALANT	Necessary	160.00 FS	*80.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
33	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	20.00 FS	*10.00 FS
34	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
35	1		*REAR FLOOR PANEL INSULATOR SEAL	Not Necessary	550.00 FS	*- FS
36	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,631.20	6,158.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,315.12	575.80
Total Parts (\$\$)	13,316.08	5,582.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	2,000.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	2,000.00	1,100.00
3	TUFF COAT	New	250.00	120.00
4	WIRING CHECK	New	80.00	30.00
5	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
6	TO REMOVE AND REFIX REAR DOOR MECHANISM (2 DOORS)	New	320.00	160.00
7	REMOVE & REINSTALL REAR DOOR WINDOW GLASS	New	160.00	120.00
8	REMOVE AND REFIX REVERSE SENSOR	New	160.00	50.00
Gross Labour Cost (\$\$)			5,150.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >