

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2005495

INV Date 12/08/2020

Reference CC3/CTI20001042/Fba3q2

Code

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SHD 1682J

Insured Veh. GBD 3069M

Claim No. SNM20D200398

Policy No. DMCVSNW0000369200

Accident Date 15/01/2020

Inspection Date 15/01/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
CHIN	INA TAIPING INSURANCE (S) PTE LTD Ref: CC3/CTI20001042/Fba3q2				
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 12-08-2020 Code: CTI			
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	GBD 3069M	Veh. Inspected	SHD 1682J	
	Policy No.	DMCVSNW0000369200	Coverage (\$)	0.00	
	Claim No.	SNM20D200398	Excess (\$)	0.00	
	Assign From		Assign Date	15/01/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model		c.c	1582	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	TMAD281UVHJ142102	Colour	SILVER	
	Odometer	272600	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
	L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
	R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
	L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4.	T	•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	15/01/2020	Inspection Date	15/01/2020	
	Survey held at	PREMIER AUTOMOTIVE SERVI	ICES PTE LTD		
	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443				
5a.			emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	2 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1682J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE LOWER GARNISH	TO REPAIR SEE LABOUR	362.61	-
1	EMBLEM I30	NECESSARY	27.80	27.80
1	EMBLEM CRDI	NECESSARY	29.40	29.40
1	EMBLEM HYUNDAI	NECESSARY	29.40	29.40
1	REAR BUMPER	DEFORMED	811.11	811.11
1	REAR BUMPER SPONGE	BROKEN	79.20	79.20
1	REAR BUMPER REINFORCEMENT	DENTED	815.64	815.64
1	REAR BUMPER REINFORCEMENT CENTRE	NOT NECESSARY	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	NOT NECESSARY	104.40	-
2	REAR BUMPER N/S & O/S REFLECTOR @\$107.50	NOT NECESSARY	215.00	-
	LESS 20% DISCOUNT		-510.75	-358.51
			2,043.01	1,434.04
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET TAILGATE STICKERS (SN)	NECESSARY	100.00	100.00
1	SET TAILGATE LOWER GARNISH CLIPS (SN)	NECESSARY	38.00	38.00
1	SUNDRY (SN)	NECESSARY	50.00	30.00
			516.00	216.00
	LABOUR			
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE END PANEL ,TAILGATE.INCLUSIVE OF THE REPAIR OF TAILGATE LOWER GARNISH.		550.00	360.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE LOWER GARNISH ,END PANEL.		600.00	360.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			1,380.00	820.00
	GRAND TOTAL		3,939.01	2,470.04

RECOMMENDED COST OF LUMP SUM REPAIRS		1,900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC3/CTI20001042/Fba3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

**Automotive Assessor** 




51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Sngapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SHD 1682J


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Sngapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R


# PHOTOGRAPHS FOR VEHICLE NO. SHD 1682J

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R



