



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2004718
INV Date 03/07/2020
Reference CC6/CTI20001043/Ada3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 837B
Insured Veh. GBB 8374J
Claim No. SNM19D205605C02/4
Policy No. DMCVSN1922391900
Accident Date 22/11/2019
Inspection Date 15/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20001043/Ada3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 03-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 8374J	Veh. Inspected	GBJ 837B
Policy No.	DMCVSN1922391900	Coverage (\$)	0.00
Claim No.	SNM19D205605C02/4	Excess (\$)	0.00
Assign From		Assign Date	15/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GDH2012003006	Colour	YELLOW
Odometer	41184	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	6 mm
L/H Front Tyre	195 R15C	MICHELIN	6 mm
R/H Rear Tyre	195 R15C	MICHELIN	6 mm
L/H Rear Tyre	195 R15C	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/11/2019	Inspection Date	15/01/2020
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 837B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED	1,785.00	1,785.00
2	TAILGATE CORNER GARNISH @ \$18.00	NOT NECESSARY	36.00	-
2	TAILGATE STOPPER @ \$19.00	NOT NECESSARY	38.00	-
2	TAILGATE DAMPER @ \$58.00	NOT NECESSARY	116.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	285.00	-
1	TAILGATE LOWER LOCK	NOT NECESSARY	45.00	-
1	TAILGATE LOCK MOTOR	NOT NECESSARY	545.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	410.00	-
1	TAILGATE WEATHERSTRIP PROTECTOR	NOT NECESSARY	135.00	-
1	TAILGATE WINDSCREEN GLASS	SHATTERED	1,120.00	1,120.00
2	TAIL LAMP @ \$380.00	N/S CRACKED	760.00	380.00
2	TAILLAMP LOWER GARNISH @ \$298.00	N/S DEFORMED	596.00	104.70
2	TAILLAMP LOWER GARNISH RETAINER @ \$65.00	N/S DAMAGED	130.00	65.00
1	TAIL LAMP PANEL LH	DENTED	350.00	350.00
1	TAIL LAMP INNER PANEL LH	TO REPAIR SEE LABOUR	540.00	-
1	REAR SIDE PANEL (OUTER) LH	BUCKLED	1,865.00	1,865.00
1	REAR SIDE PANEL (INNER) LH	TO REPAIR SEE LABOUR	1,270.20	-
1	REAR SIDE LOWER CORNER INNER PANEL LH	TO REPAIR SEE LABOUR	187.50	-
1	REAR SIDE INNER TRIM BOARD LH	NOT NECESSARY	345.00	-
1	REAR SIDE AIR VENT LH	NOT NECESSARY	86.30	-
1	REAR CHASSIS MEMBER LH	NOT NECESSARY	795.00	-
1	REAR BUMPER	DEFORMED	479.00	479.00
4	REAR BUMPER LOWER BRACKET @ \$29.00	NOT NECESSARY	116.00	-
2	REAR BUMPER SIDE RETAINER @ \$55.00	N/S DEFORMED	110.00	55.00
1	REAR END PANEL (OUTER)	TO REPAIR SEE LABOUR	597.00	-
	LESS 25% DISCOUNT		-3,185.50	-1,550.92
			9,556.50	4,652.78

Report Ref No. CC6/CTI20001043/Ada3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SPECIAL TYPE) (SN)	NOT NECESSARY	150.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	40.00	10.00
1	REAR FLOOR TOP COVER BOARD (SPECIAL TYPE) (SN)	NOT NECESSARY	1,200.00	-
1	REAR SIDE PANEL (OUTER) SEALANT LH (SN)	NECESSARY	150.00	60.00
1	SET REAR SIDE PANEL INNER TRIM CLIP LH (SN)	NOT NECESSARY	80.00	-
1	SET REAR SIDE PANEL 'COMPANY' STICKER (SN)	NECESSARY	3,800.00	800.00
1	TAILGATE SEALANT (SN)	NOT NECESSARY	150.00	-
1	TAILGATE LOGO (SPECIAL TYPE) (SN)	NECESSARY	180.00	75.00
1	TAILGATE STICKER '70KM/H' (SN)	NECESSARY	40.00	10.00
1	TAILGATE STICKER '8PAX' (SN)	NECESSARY	40.00	10.00
1	SET TAILGATE INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	40.00
1	REAR END PANEL (OUTER) SEALANT (SN)	NOT NECESSARY	150.00	-
			6,250.00	1,075.00
	<u>LABOUR</u>			
	PANEL BEATING AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF TAIL LAMP INNER PANEL LH, REAR SIDE PANEL (INNER) LH, REAR SIDE LOWER CORNER INNER PANEL LH AND REAR END PANEL (OUTER).		2,200.00	1,200.00
	SPRAY PAINTING TO AFFECTED AREA.		1,800.00	800.00
	WIRING, BULB CHECKING.		180.00	30.00
	TRANSFER TAILGATE MECHANISM.		80.00	80.00
	REMOVE AND REFIX REAR VIDEO RECORDER.		80.00	50.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR REVERSE SENSOR.		80.00	50.00
	REMOVE AND REFIX REAR FLOOR BOARD.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX REAR WINDSCREEN.		120.00	120.00
	REMOVE AND REFIX SIDE PANEL RAILING AND SLIDING DOOR LH.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-

Report Ref No. CC6/CTI20001043/Ada3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	VACUUM AND CLEAN REAR WINDSCREEN GLASS SPLINTER.		350.00	80.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			5,540.00	2,410.00
GRAND TOTAL			21,346.50	8,137.78

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00
--	--	--	--	----------

Report Ref No. CC6/CTI20001043/Ada3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.