Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001045/KEA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SMN5934U Insured Vehicle No: SJR1202P

Date of Loss: 13/01/2020 Nature of Claim: TP Claim No: 3042085836SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN5934U

Make & Model: HONDA FREED HYBRID, 1.5 G (A) Engine No: LEB5621719
Reg. Date: 19/08/2019 (Man. Year: 2018) Chassis No: GB71084377
Colour: Metallic Blue Odometer: 28698 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Yokohama 3 mm Rear Left Side: Yokohama 2 mm
Front Right Side: Yokohama 3 mm Rear Right Side: Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,015.84	866.08	149.76	14.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	350.00	350.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,715.84	1,216.08	499.76	29.13
+ GST 7.00/7.00% (S\$)	120.11	85.13	34.98	29.12
Nett Amount (S\$)	1,835.95	1,301.21	534.74	29.13
+ Car Rental (2.0 x S	\$75.00/day) (S\$)	150.00		
+ Doc/	Search Fee (S\$)	2.00		

INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 21/01/2020 Inspected At: Optima Werkz Pte Ltd (HQ)

Nett Liability (S\$)

6 Kung Chong Road Singapore 159143

1,453.21

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars		Condition	Repairer's	Amount
1	1		*FRONT BUMPER		Mtg Cracked	695.40 FL	*695.40 FL
2	8		*FRONT BUMPER	CLIPS	Necessary	46.40 FL	*46.40 FL
3	1		*FRONT BUMPER	REINFORCEMENT	Bent	483.00 FL	*295.80 FL
4	1		*FRONT BUMPER	UPPER SUPPORT BRACKET LH	Cracked	45.00 FL	*45.00 FL
F=Fra	nchise	part. L=ListI	temDisc.				
					Sub Total (S\$)	1,269.80	1,082.60
- List Item Discount on L Items 20.00/20.00% (S\$)					253.96	216.52	
					Total Parts (S\$)	1,015.84	866.08
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST FRONT ACCIDENT AREAS & ETC	New	300.00	150.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT GRILLE & ETC	New	400.00	200.00
	Gross Labour Cost (S\$)		700.00	350.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >