

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20001058/DPA3N2**Date:** 20/07/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MCV0002346_01

Claimant Vehicle No : SH7946H **Insured Vehicle No :** GBC7789Y

Date of Loss: 14/01/2020 Nature of Claim: TP Claim No: MCV2020D0000190

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH7946H**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4DFDU528464

Reg. Date: 30/06/2015 (Man. Year: 2015) Chassis No: KMHLB41UMGU075035

Colour: Blue Odometer: 508375 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,463.68	11,244.08	10,219.60	47.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,800.00	2,140.00	54.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,403.68	13,044.08	12,359.60	48.65
Approved Total (Overridden) (S\$)		10,400.00		
(S\$)	25,403.68	10,400.00	15,003.68	59.06
+ GST 7.00/7.00% (S\$)	1,778.26	728.00	1,050.26	59.06
Nett Amount (S\$)	27,181.94	11,128.00	16,053.94	59.06
+ Car Rental (5.0 x S\$114.95/day) (S\$)		574.75		
+ Loss of Earnings (5.0 x S\$40.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		40.00		
Nett Liability (S\$)		11,950.20		
Global Sum Settlement (S\$)		11,950.00		

INSPECTION

Date of Assignment: 16/01/2020

Date Inspected: 17/01/2020 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming
Industrial Estate
Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2020)
Parts: 143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7946H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,265.90 FL	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Not Necessary	15.70 FL	*- FL
3	1		*BONNET RUBBER (RH)	Not Necessary	6.20 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Bent	164.00 FL	*164.00 FL
5	1		*BONNET LOCK	Bent	42.40 FL	*42.40 FL
6	1		*BONNET ABSORBER (LH ONLY)	Not Necessary	61.60 FL	*- FL
7	1		*BONNET INSULATOR	Not Necessary	202.50 FL	*- FL
8	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
9	1		*BONNET INSULATOR CLIPS	Not Necessary	7.00 FL	*- FL
10	1		*RADIATOR GRILLE H EMBLEM	Dislodged / Broken	39.50 FL	*39.50 FL
11	1		*RADIATOR GRILLE	Broken	1,480.00 FL	*1,480.00 FL
12	1		*FRONT BUMPER COVER	Dented / Distorted	1,052.20 FL	*1,052.20 FL
13	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	438.40 FL	*438.40 FL
15	2		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	98.40 FL	*- FL
16	1		*FRONT BUMPER CENTRE GRILLE	Not fitted	114.00 FL	*- FL
17	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	89.60 FL	*- FL
18	1		*FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40)	Not fitted	32.00 FL	*- FL
19	2		*FRONT BUMPER PROTECTOR (LH/RH)	Not fitted	50.80 FL	*- FL
20	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	98.40 FL	*- FL
21	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	9.20 FL	*- FL
22	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	8.00 FL	*- FL
23	1		*FRONT BUMPER GRILLE AIR DUCT	Not Necessary	26.20 FL	*- FL
24	1		*HEADLAMP SUPPORT PANEL ASSY	Bent / Cracked	907.40 FL	*907.40 FL
25	2		*HEADLAMP (LH/RH)	Mtg Cracked	5,552.00 FL	*2,776.00 FL
26	1		*HEADLAMP SUPPORT TOP COVER	Not fitted	222.60 FL	*- FL
27	2		*HEADLAMP HALOGEN BULB (LH/RH)	Not Necessary	57.60 FL	*- FL
28	1		*RADIATOR	Punctured	708.50 FL	*708.50 FL
29	1		*RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
30	2		*RADIATOR BRACKET (LH/RH)	Not Necessary	10.80 FL	*- FL
31	1		*RADIATOR HOSE UPPER	Not Necessary	39.50 FL	*- FL
32	1		*RADIATOR HOSE LOWER	Not Necessary	39.50 FL	*- FL
33	1		*RADIATOR GUARD	Not Necessary	35.00 FL	*- FL
34	1		*HORN UNIT (LH/RH)	N/S Cracked / O/SNot Necessary	144.60 FL	*72.30 FL
35	1		*HORN WIRE	Not Necessary	156.60 FL	*- FL
36	1		*AIR CLEANER ASSY	Deformed	118.60 FL	*118.60 FL
37	1		*AIR FILTER	Not Necessary	45.70 FL	*- FL
38	1		*AIR CLEANER COVER	Not Necessary	28.60 FL	*- FL
39	1		*AIR DUCT	Not Necessary	171.70 FL	*- FL
40	1		*AIR FLOW SENSOR	Damaged	527.80 FL	*527.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*RESONATOR TANK HOSE	Not Necessary	218.30 FL	*- FL
42	1		*AIR CLEANER HOUSING	Not Necessary	88.50 FL	*- FL
43	1		*AIR CLEANER BOTTOM ASSY	Not Necessary	325.00 FL	*- FL
44	2		*FRONT FENDER (LH/RH)	Dented	1,132.60 FL	*1,132.60 FL
45	2		*FRONT FENDER APRON PANEL(LH/RH)	Not Necessary	1,274.00 FL	*- FL
46	2		*FRONT FENDER SHIELD (LH/RH)	Not Necessary	349.80 FL	*- FL
47	2		*FRONT FENDER MUDFLAP (LH/RH)	Not Necessary	27.00 FL	*- FL
48	2		*FRONT FENDER RETAINER	Not Necessary	6.00 FL	*- FL
49	1		*AIRCON CONDENSER	Bent / Punctured	947.80 FL	*947.80 FL
50	1		*FRONT WINDSCREEN MOULDING	Not Necessary	23.70 FL	*- FL
51	1		*FRONT INTERCOOLER	Punctured	1,032.50 FL	*1,032.50 FL
52	2		*FRONT WINDSCREEN PILLAR OUTER (LH/RH)	Repair	3,071.80 FL	*- FL
53	2		*FRONT WINDSCREEN ENFORCEMENT (LH/RH) INNER	Not Necessary	1,938.80 FL	*- FL
54	1		*FRONT WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS
55	2		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	200.00 FS	*200.00 FS
56	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
57	1		*FRONT NO.PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
58	1		*FRONT ERP STICKER	Not Necessary	26.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	26,749.35	14,005.10
- List Item Discount on L Items 20.00/20.00% (S\$)	5,285.67	2,761.02
Total Parts (S\$)	21,463.68	11,244.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	800.00
2	SPRAY PAINTING CHARGE	New	1,600.00	800.00
3	WIRING CHARGE	New	200.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX RADIATOR	New	90.00	50.00
7	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
8	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
Gross Labour Cost (\$\$)			3,940.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >