

INS. CASE OWNER:

MERINA CHIA

CC4/FCI20001069/T10a3s2

LKK:

IDAC:

Surveyor:

TAUFIKH

DOI:

ASSIGNMENT

12/01/2020

Date / Time : 16/01/2020

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SHC 272X

Name of Insured :

CITYCAB PTE LTD

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A : 14/01/2020 22:00

Claim No. :

D20000402MFSH

Policy No. :

D-20094921MFSH

Make / Model :

HYUNDAI IONIQ

Place of Accident :

PIE TOWARDS AIRPORT BEFORE TAMPINES AVE

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

TAN YEW SENG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

+65-96721470

(V/L: YES / NO)

Insured Liability :

%

Final ? Yes / No

SHD 3033U

SHC 272X

SHC 7798A



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS: OI



INSRS:

WSP: DING

Tel : AUTOMOTIVE

Liability :

RMKS: TP



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

SHC 7798A - CS/FCI18014023/Ntbe2; DOA: 08.03.17
 SHC 272X - CC4/III20001044/Dga3; DOA: 14.01.2020
 - CS/FCI15001921/Agbk3; DOA: 28.01.15

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

I.TA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

22/2/2020

Confirm with Shinah

Email

Call

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia : 04

3 veh c. c. , 02 mas 2nd

Repair Cost: (w/16/15)

SS 7266.63

Loss of Rental (LOR):

SS 760.50

(6.5 days) x \$117

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS 325.00

(\$

50

x

6.5 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 8352.13

Global Sum SS: 8350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 8350.00

Name 1:

Ding Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 7778 A

Yr Regn:

2019, Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Lorry

C.C.

1580

Colour:

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

42615

T/Radio: Insured / Std / NI / NA

Eng/No:

KMH C851CVL4180906

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P - \$ 6791.24 (Red \$ 4567.11 / 40%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Rep. Form:

Lump Sum / R.E. / %

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week end (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

MOTOR SURVEY ASSIGNMENT

Date 16-01-2020 Our Ref No. D20000402MFSH

Accident Date 14-01-2020 Claim Type. Third Party

Insured Vehicle SHC0272X Third Party Vehicle. SHC7798A

Survey Location 31 CORPORATION ROAD

Contact Person. VADIVELAN MOHAN

Contact No. 62657130/ 96891857

Fax No. 0

Survey Type WITHOUT PREJUDICE:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA

Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop DING AUTOMOTIVE PTE LTD

Attention. NIL

Cc : TP Solicitor NA

TP Solicitor Fax No. NA

Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Sur: Taufik
3:18pm @ 16/01/2020
P: V. Mohan
V: In
S: Taufik

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

16/01/2020 8:59

OWNER'S PARTICULARS

JOB-NO: 50112365

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILSLICENSE NO: SHC7798A TRANS: AUTO
MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 D
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1CHASSIS: KMHC851CVLU180906
ENGINE: G4LEKU377522CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,400.00	0.00	1,400.00		Y	300.900
2 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
3 RESPRAY REAR BUMPER CENTER GARNISH (BLACK)	1.00	250.00	0.00	250.00		Y	100
4 RESPRAY REAR LHS FENDER	1.00	250.00	0.00	250.00		Y	100
5 RESPRAY REVERSE SENSOR SET	1.00	150.00	0.00	150.00		Y	30
6 RESPRAY BOOTLID & BOOTLID SPOILER	1.00	300.00	0.00	300.00		Y	250
7 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	150
8 R&R BOOTLID COMPONENTS, BOOTLID SPOILER, LOCK AND TRIM BOARD	1.00	180.00	0.00	180.00		Y	x 111
9 R&R SPARE TYRE / BOARD / TRIM / CARPET TO PANEL BEAT END PANEL	1.00	180.00	0.00	180.00		Y	60
10 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	180.00	0.00	180.00		Y	30
11 RUST PROOFING	1.00	120.00	0.00	120.00		Y	30
TOTAL:		3,510.00	0.00	3,510.00			

Spray spare tyre 1100

1950

MATERIALS

1 REAR BUMPER	1.00	629.30	125.86	503.44	L	Y	cmv
2 REAR BUMPER LHS RETAINER	1.00	68.30	13.66	54.64	L	Y	rel
3 REAR BUMPER CENTER GARNISH (BLACK)	1.00	362.30	72.46	289.84	L	Y	cmv
4 REAR BUMPER REFLECTOR LHS	1.00	58.60	11.72	46.88	L	Y	cmv
5 REAR BUMPER LOWER LIP MOULDING	1.00	156.30	31.26	125.04	L	Y	de
6 REAR CENTER UNDERCARRIAGE COVER <i>*plus</i>	1.00	286.30	57.26	229.04	L	Y	de
7 REAR LHS LOWER COVER <i>*plus</i>	1.00	186.30	37.26	149.04	L	Y	de
8 REAR BUMPER LHS TOWING CAP	1.00	38.50	7.30	29.20	L	Y	mig
9 REAR BUMPER REINFORCEMENT	1.00	361.30	72.26	289.04	L	Y	bt
10 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	146.30	29.26	117.04	L	Y	bt
11 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	146.30	29.26	117.04	L	Y	bt
12 REAR END PANEL	1.00	658.30	131.66	526.64	L	Y	Rel
13 REAR END PANEL TOP GARNISH	1.00	166.30	33.26	133.04	L	Y	x nn
14 REAR FOG LAMP ASSY	1.00	356.80	71.36	285.44	L	Y	cmv
15 REAR LHS FENDER (REPAIR)	1.00	0.00	0.00	0.00	L	Y	Rp
16 REAR LHS BLIND SPOT MONITORING UNIT	1.00	1,620.83	324.17	1,296.66	L	Y	x cmv
17 REAR NUMBER PLATE LAMP RHS	1.00	146.80	29.36	117.44	L	Y	x nn

DING AUTOMOTIVE PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle:	SHC7798A
Model:	HYUNDAI IONIQ
Chassis:	KMHC851CVLU180906

PARTS SUPPLEMENTARY & QUOTATION FORM

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR BUMPER SMART KEY ANTENNA <i>car</i>	1	\$ 128.86	20%	\$ 103.09	
				PARTS	\$ 103.09	

17/1/20

Part By part

Labour = \$ 1950

S/N = \$ 395

Parts = \$ 4446.24

Lcs+p = \$ 6791.24

Final Amount = \$ 6791.24

R - 4045.33
? 2951.05

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

16/01/2020 8:59

JOB-NO: 50112365

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHC7798A TRANS: AUTO
MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: KMHC851CVLU180906
ENGINE: G4LEKU377522

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,400.00	0.00	1,400.00	Y		700.
2 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
3 RESPRAY REAR BUMPER CENTER GARNISH (BLACK)	1.00	250.00	0.00	250.00	Y		100.
4 RESPRAY REAR LHS FENDER	1.00	250.00	0.00	250.00	Y		100.
5 RESPRAY REVERSE SENSOR SET	1.00	150.00	0.00	150.00	Y		30
6 RESPRAY BOOTLID & BOOTLID SPOILER	1.00	300.00	0.00	300.00	Y		250.
7 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		150.
8 R&R BOOTLID COMPONENTS, BOOTLID SPOILER, LOCK AND TRIM BOARD	1.00	180.00	0.00	180.00	Y		X
9 R&R SPARE TYRE / BOARD / TRIM / CARPET TO PANEL BEAT END PANEL	1.00	180.00	0.00	180.00	Y		60.
10 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE) & RE-POSITION TAIL LAMP	1.00	180.00	0.00	180.00	Y		30.
11 RUST PROOFING	1.00	120.00	0.00	120.00	Y		30.
TOTAL:		3,510.00	0.00	3,510.00			
MATERIALS							
1 REAR BUMPER	1.00	629.30	125.86	503.44	L	Y	cut ✓
2 REAR BUMPER LHS RETAINER	1.00	68.30	13.66	54.64	L	Y	del ✓
3 REAR BUMPER CENTER GARNISH (BLACK)	1.00	362.30	72.46	289.84	L	Y	cut ✓
4 REAR BUMPER REFLECTOR LHS	1.00	58.60	11.72	46.88	L	Y	cut ✓
5 REAR BUMPER LOWER LIP MOULDING	1.00	156.30	31.26	125.04	L	Y	del ✓
6 REAR CENTER UNDERCARRIAGE COVER <i>*plus to</i>	1.00	286.30	57.26	229.04	L	Y	3/0 ✓
7 REAR LHS LOWER COVER <i>+ plus to</i>	1.00	186.30	37.26	149.04	L	Y	del ✓
8 REAR BUMPER LHS TOWING CAP	1.00	36.50	7.30	29.20	L	Y	mis ✓
9 REAR BUMPER REINFORCEMENT	1.00	361.30	72.26	289.04	L	Y	del ✓
10 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	146.30	29.26	117.04	L	Y	?
11 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	146.30	29.26	117.04	L	Y	?
12 REAR END PANEL	1.00	658.30	131.66	526.64	L	Y	Rx
13 REAR END PANEL TOP GARNISH	1.00	166.30	33.26	133.04	L	Y	?
14 REAR FOG LAMP ASSY	1.00	356.80	71.36	285.44	L	Y	?
15 REAR LHS FENDER (REPAIR)	1.00	0.00	0.00	0.00	L	Y	Rx
16 REAR LHS BLIND SPOT MONITORING UNIT	1.00	1,620.83	324.17	1,296.66	L	Y	?
17 REAR NUMBER PLATE LAMP RHS	1.00	146.80	29.36	117.44	L	Y	?

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
18 REAR NUMBER PLATE LAMP LHS	1.00	146.80	29.36	117.44	L	Y	?
19 BBOTLID (REPAIR)	1.00	0.00	0.00	0.00	L	Y	Ry
20 BOOTLID SPOILER (REPAIR)	1.00	0.00	0.00	0.00	L	Y	Ry
21 BOOTLID LOCK	1.00	195.81	39.16	156.65	L	Y	dis
22 BOOTLID LOCK CATCH	1.00	48.21	9.64	38.57	L	Y	X
23 BOOTLID EMBLEM-LOGO	1.00	68.20	13.64	54.56	L	Y	nei
24 BOOTLID EMBLEM "HYUNDAI" HYBRID	1.00	46.60	9.32	37.28	L	Y	nei
25 BOOTLID EMBLEM -IONIC	1.00	44.60	8.92	35.68	L	Y	nei
26 REAR LHS TAIL LAMP (BODY)	1.00	957.44	191.49	765.95	L	Y	?
27 REAR BUMPER CLIPS	1.00	45.00	0.00	45.00	S	Y	30 nei
28 REVERSE SENSOR SET	1.00	240.00	0.00	240.00	S	Y	200 nei
29 REAR NUMBER PLATE WITH FRAME	1.00	140.00	0.00	140.00	S	Y	45 nei
30 REAR CENTER UNDERCARRIAGE COVER & LHS LOWER COVER CLIPS SET	1.00	50.00	0.00	50.00	S	Y	20 nei
31 REAR END PANEL SEALANT	1.00	150.00	0.00	150.00	S	Y	X
32 BOOTLID STICKER-COMFORTDELGRO & BOOKING 65521111 &BOOK NOW	1.00	200.00	0.00	200.00	S	Y	100 nei
TOTAL:		7,719.49	378.90	6,340.59			
TOTAL PARTS & LABOUR:		11,229.49	1,378.90	9,850.59			

EXCESS/LOADING:\$S 0.00

No. Of Day:

05 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$S

DATE OF SURVEY:

17 / 1 / 20

SURVEYED BY:

Tanfilm

WP

tanfilm@lkkauto.com

CONTACT NO:

97495749

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20001069/T1da3s2

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 27-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 272X	Veh. Inspected	SHC 7798A
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D20000402MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	16/01/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU180906	Colour	YELLOW
Odometer	42615	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/01/2020	Inspection Date	17/01/2020
Survey held at	DING AUTOMOTIVE PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7798A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRACKED	629.30	629.30
1	REAR BUMPER LHS RETAINER	NECESSARY	68.30	68.30
1	REAR BUMPER CENTER GARNISH (BLACK)	CRACKED	362.30	362.30
1	REAR BUMPER REFLECTOR LHS	CUT	58.60	58.60
1	REAR BUMPER LOWER LIP MOULDING	DEFORMED	156.30	156.30
1	REAR CENTER UNDERCARRIAGE COVER	DEFORMED	286.30	286.30
1	REAR LHS LOWER COVER	DEFORMED	186.30	186.30
1	REAR BUMPER LHS TOWING CAP	MISSING	36.50	36.50
1	REAR BUMPER REINFORCEMENT	BENT	361.30	361.30
1	REAR BUMPER REINFORCEMENT BRACKET RH	BENT	146.30	146.30
1	REAR BUMPER REINFORCEMENT BRACKET LH	BENT	146.30	146.30
1	REAR END PANEL	BENT	658.30	658.30
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	166.30	-
1	REAR FOG LAMP ASSY	CRACKED	356.80	356.80
1	REAR LHS FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR LHS BLIND SPOT MONITORING UNIT	CRACKED	1,620.83	1,620.83
1	REAR NUMBER PLATE LAMP RHS	NOT NECESSARY	146.80	-
1	REAR NUMBER PLATE LAMP LHS	NOT NECESSARY	146.80	-
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
1	BOOTLID SPOILER (NPA)	TO REPAIR SEE LABOUR	-	-
1	BOOTLID LOCK	DISTORTED	195.81	195.81
1	BOOTLID LOCK CATCH	NOT NECESSARY	48.21	-
1	BOOTLID EMBLEM - LOGO	NECESSARY	68.20	68.20
1	BOOTLID EMBLEM "HYBRID"	NECESSARY	46.60	46.60
1	BOOTLID EMBLEM - IONIC	NECESSARY	44.60	44.60
1	REAR LHS TAIL LAMP (BODY)	NOT NECESSARY	957.44	-
1	REAR BUMPER SMART KEY ANTENNA (ADDITIONAL)	CRACKED	128.86	128.86

Report Ref No. CC4/FCI20001069/T1da3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,404.67	-1,111.56
			5,618.68	4,446.24
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	240.00	200.00
1	REAR NUMBER PLATE WITH FRAME (SN)	CRACKED	140.00	45.00
1	SET REAR CENTER UNDERCARRIAGE COVER & LHS LOWER COVER CLIPS (SN)	NECESSARY	50.00	20.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	BOOTLID STICKER - COMFORTDELGRO & BOOKING 65521111 & BOOK NOW (SN)	NECESSARY	200.00	100.00
			825.00	395.00
	<u>LABOUR</u>			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR LHS FENDER, BOOTLID AND BOOTLID SPOILER.		1,400.00	900.00
	RESPRAY REAR BUMPER.		250.00	200.00
	RESPRAY REAR BUMPER CENTER GARNISH (BLACK).		250.00	100.00
	RESPRAY REAR LHS FENDER.		250.00	100.00
	RESPRAY REVERSE SENSOR SET.		150.00	30.00
	RESPRAY BOOTLID & BOOTLID SPOILER.		300.00	250.00
	RESPRAY REAR END PANEL.		250.00	150.00
	R&R BOOTLID COMPONENTS, BOOTLID SPOILER, LOCK AND TRIM BOARD.	NOT NECESSARY	180.00	-
	R&R SPARE TYRE / BOARD / TRIM / CARPET TO PANEL BEAT END PANEL.		180.00	60.00
	CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE) & RE-POSITION TAIL LAMP.		180.00	30.00
	RUST PROOFING.		120.00	30.00
	SPRAY SPARE TYRE.		100.00	100.00
			-	-
			-	-
			-	-
			3,610.00	1,950.00

Report Ref No. CC4/FCI20001069/T1da3s2



GRAND TOTAL		10,053.68	6,791.24
RECOMMENDED COST OF REPAIRS			6,791.24

Report Ref No. CC4/FCI20001069/T1da3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.