

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001106/KBS3Q2

Date: 17/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800127156
Claimant
Vehicle No : SJG7181J **Insured Vehicle No :** SMF4719Z
Date of Loss: 15/01/2020 Nature of Claim: TP Claim No: 0921767272SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG7181J**
Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4092474
Reg. Date: 14/07/2008 (Man. Year: 2008) Chassis No: GE61082323
Colour: Metallic Blue Odometer: 278663 km
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/45ZR16 Rear Tyre Size: 205/45ZR16
Front Left Side: Kenda 8 mm Rear Left Side: Kenda 8 mm
Front Right Side: Kenda 8 mm Rear Right Side: Kenda 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,507.00	7,046.13	460.87	6.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	3,950.00	260.00	6.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,717.00	10,996.13	720.87	6.15
Approved Total (Overridden) (S\$)		8,750.00		
(S\$)	11,717.00	8,750.00	2,967.00	25.32
+ GST 7.00/7.00% (S\$)	820.19	612.50	207.69	25.32
Nett Amount (S\$)	12,537.19	9,362.50	3,174.69	25.32
+ Car Rental (22.0 x S\$85.00/day) (S\$)		1,870.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		11,240.50		
Global Sum Settlement (S\$)		11,240.00		

INSPECTION

Date of Assignment: 17/01/2020
Date Inspected: 17/01/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761
Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	497.20 FL	*497.20 FL
2	2		*REAR BUMPER SIDE RETAINERS	Distorted	33.00 FL	*33.00 FL
3	6		*REAR BUMPER CLIPS	Necessary	22.20 FL	*22.20 FL
4	1		*REAR BUMPER TOW COVER	Dented	13.00 FL	*13.00 FL
5	1		*REAR TAILGATE	Bent	771.50 FL	*771.50 FL
6	1		*TAILGATE EMBLEM (FIT)	Necessary	35.00 FL	*35.00 FL
7	1		*TAILGATE INNER LOCK	Jammed	189.90 FL	*189.90 FL
8	1		*TAILGATE INNER BOARD	Distorted / Buckled	100.20 FL	*100.20 FL
9	1		*TAILGATE OUTER GARNISH	Warped	110.60 FL	*110.60 FL
10	1		*TAILGATE LOGO	Necessary	27.40 FL	*27.40 FL
11	1		*REAR WINDSCREEN GLASS	Shattered	1,200.50 FL	*1,200.50 FL
12	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	120.80 FL	*120.80 FL
13	1		*REAR WIPER MOTOR	Jammed	218.30 FL	*218.30 FL
14	1		*REAR NUMBER PLATE LAMP	Cracked	48.00 FL	*48.00 FL
15	1		*REAR SPARE TYRE PANEL	Bent	737.00 FL	*737.00 FL
16	1		*REAR SPARE TYRE PANEL INNER TOP BOARD	Deformed	190.70 FL	*190.70 FL
17	1		*REAR RH FENDER	Buckled	652.90 FL	*652.90 FL
18	1		*REAR RH FENDER INNER GARNISH	Deformed	250.30 FL	*250.30 FL
19	1		*REAR RH FENDER AIR SCROP GRILLE	Dented	28.80 FL	*28.80 FL
20	1		*REAR RH FENDER INNER SHIELD	Torn	28.00 FL	*28.00 FL
21	1		*REAR RH FENDER GLASS	Serviceable	280.60 FL	*- FL
22	1		*REAR PANEL	Bent	276.50 FL	*276.50 FL
23	1		*REAR PANEL INNER TOP GARNISH	Dented	60.80 FL	*60.80 FL
24	2		*TAILLAMPS	Broken	413.00 FL	*413.00 FL
25	1		*TAILLAMP PANELS	N/S Repair / O/S Bent	271.00 FL	*135.50 FL
26	1		*REAR LH FENDER INNER GARNISH	Cracked	250.30 FL	*250.30 FL
27	1		*REAR EXHAUST PIPE	Bent	529.40 FL	*529.40 FL
28	1		*CENTRE EXHAUST PIPE	Bent	506.90 FL	*506.90 FL
29	1		*ROLL REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
30	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
31	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
32	1		*REVERSE CAMERA	Shorted	380.00 FS	*380.00 FS
33	1		*REAR SPARE PANEL TOP COAT	Necessary	80.00 FS	*60.00 FS
34	1		*REAR RH FENDER GLASS GUM	Necessary	30.00 FS	*30.00 FS
35	1		*REAR SPARE TYRE TOOL SPONGE	Cracked	220.40 FL	*220.40 FL
36	1		*REAR BOOT INNER RUBBER (50%)	Cut	74.64 FS	*46.65 FS
37	1		*REAR RH TYRE (60%)	Cut	200.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **9,123.84** **8,579.75**
- List Item Discount on L Items 20.00/20.00% (S\$) 1,616.84 1,533.62

Total Parts (S\$) **7,507.00** **7,046.13**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (FROM SCENE TO HOME)	New	70.00	70.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE & REFIX REAR RH FENDER GLASS	New	60.00	50.00
4	REMOVE & REFIX TOP ROOF LINING ,SEAT ,GARNISH ,ETC	New	120.00	120.00
5	REMOVE & REFIX REAR EXHAUST ,STRAIGHTEN CENTRE EXHAUST	New	80.00	80.00
6	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,TAILGATE ASSY ,CUT ,WELD & RENEW REAR END PANEL,TAILLAMP PANELS ,REAR RH FENDER ,REAR SPARE TYRE COMPARTMENT ,KNOCK & REPAIR REAR LH FENDER ,REAR BOTH CHASSIS ,TOP ROOF PANEL & REALIGN THE SAME	New	1,850.00	1,700.00
7	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT ,TAILLAMP PANELS ,REAR BOTH FENDERS ,TAILGATE ,REAR PANEL,REAR BUMPER	New	1,500.00	1,400.00
8	REMOVE & REFIX REAR UNDER CARRIAGE	New	180.00	180.00
9	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
10	RUSTPROOFING	New	120.00	120.00
11	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	50.00	50.00
Gross Labour Cost (\$\$)			4,210.00	3,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >