

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2020 Edit Reg		10 Feb 2020 00:00 Edit Adj Rpt	S\$17,559.30 Edit Estimates	S\$17,559.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ASSET LIMO , Co. Reg. No.: 53309913K									
Main Claimant: PHUAH YI QI									
Vehicle Reg. No.: SLR9504S		Date of Loss: 17/01/2020 12:00 - :59 [28 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6265339568SG		Policy/Cover Note No.: (Third Party Only)							
Vehicle Reg. No. (Insured): SME5465D		Policy No. (Claimant): VPA/P2064655							
		Excess:							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (02/04/2020): Alert - Adj Mandate Approved (S\$19215.90) - SLR9504S - Claim Handler: Tan, Benni... - AIG_SG_EXPRESS (27/03/2020): Alert - Adj Mandate Approved (S\$19155.90) - SLR9504S - Claim Handler: Tan, Benni...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR9504S (6265339568SG)
[SME5465D]
TP
PHUAH YI QI
Jan 17 2020 12:00PM
[ASSET LIMO]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/03/20 09:27	Odometer Reading	1	Load JPG	☒
2	20/03/20 09:27	Chassis Number	1	Load JPG	☒
3	20/03/20 09:27	General View	1	Load JPG	☒
4	20/03/20 09:27	General View	1	Load JPG	☒
5	20/03/20 09:27	General View	1	Load JPG	☒
6	20/03/20 09:27	General View	1	Load JPG	☒
7	20/03/20 09:27	General View	1	Load JPG	☒
8	20/03/20 09:27	General View	1	Load JPG	☒
9	20/03/20 09:27	General View	1	Load JPG	☒
10	20/03/20 09:27	General View	1	Load JPG	☒
11	20/03/20 09:27	General View	1	Load JPG	☒
12	20/03/20 09:27	General View	1	Load JPG	☒
13	20/03/20 09:27	General View	1	Load JPG	☒
14	20/03/20 09:27	General View	1	Load JPG	☒
15	20/03/20 09:27	General View	1	Load JPG	☒
16	20/03/20 09:27	General View	1	Load JPG	☒
17	20/03/20 09:27	General View	1	Load JPG	☒
18	20/03/20 09:27	General View	1	Load JPG	☒
19	20/03/20 09:27	General View	1	Load JPG	☒
20	20/03/20 09:27	General View	1	Load JPG	☒
21	20/03/20 09:27	General View	1	Load JPG	☒
22	20/03/20 09:27	General View	1	Load JPG	☒
23	20/03/20 09:27	General View	1	Load JPG	☒
24	20/03/20 09:27	General View	1	Load JPG	☒
25	20/03/20 09:27	General View	1	Load JPG	☒
26	20/03/20 09:27	General View	1	Load JPG	☒
27	20/03/20 09:27	General View	1	Load JPG	☒
28	20/03/20 09:27	General View	1	Load JPG	☒
29	20/03/20 09:27	General View	1	Load JPG	☒
30	20/03/20 09:27	General View	1	Load JPG	☒
31	20/03/20 09:27	General View	1	Load JPG	☒
32	20/03/20 09:27	General View	1	Load JPG	☒
33	20/03/20 09:27	General View	1	Load JPG	☒
34	20/03/20 09:27	General View	1	Load JPG	☒
35	20/03/20 09:27	General View	1	Load JPG	☒
36	20/03/20 09:27	General View	1	Load JPG	☒
37	20/03/20 09:27	General View	1	Load JPG	☒

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	20/03/20 09:27	General View		Load JPG	☒
39	20/03/20 09:27	General View		Load JPG	☒
40	20/03/20 09:27	General View		Load JPG	☒
41	20/03/20 09:27	General View		Load JPG	☒
42	20/03/20 09:27	General View		Load JPG	☒
43	20/03/20 09:28	Reinspection Photo		Load JPG	☒
44	20/03/20 09:28	Reinspection Photo		Load JPG	☒
45	20/03/20 09:28	Reinspection Photo		Load JPG	☒
46	20/03/20 09:28	Reinspection Photo		Load JPG	☒
47	20/03/20 09:28	Reinspection Photo		Load JPG	☒
48	20/03/20 09:28	Reinspection Photo		Load JPG	☒
49	20/03/20 09:28	Reinspection Photo		Load JPG	☒
50	20/03/20 09:28	Reinspection Photo		Load JPG	☒
51	20/03/20 09:28	Reinspection Photo		Load JPG	☒
52	20/03/20 09:28	Reinspection Photo		Load JPG	☒
53	20/03/20 09:28	Reinspection Photo		Load JPG	☒
54	20/03/20 09:28	Reinspection Photo		Load JPG	☒
55	20/03/20 09:28	Reinspection Photo		Load JPG	☒
56	20/03/20 09:28	Reinspection Photo		Load JPG	☒
57	20/03/20 09:28	Reinspection Photo		Load JPG	☒
58	20/03/20 09:28	Reinspection Photo		Load JPG	☒
59	20/03/20 09:28	Reinspection Photo		Load JPG	☒
60	20/03/20 09:28	Reinspection Photo		Load JPG	☒
61	20/03/20 09:28	Reinspection Photo		Load JPG	☒
62	20/03/20 09:28	Reinspection Photo		Load JPG	☒
63	20/03/20 09:28	Reinspection Photo		Load JPG	☒
64	20/03/20 09:28	Reinspection Photo		Load JPG	☒
65	20/03/20 09:28	Reinspection Photo		Load JPG	☒
66	20/03/20 09:28	Reinspection Photo		Load JPG	☒
67	20/03/20 09:28	Reinspection Photo		Load JPG	☒
68	20/03/20 09:28	Reinspection Photo		Load JPG	☒
69	20/03/20 09:28	Reinspection Photo		Load JPG	☒
70	20/03/20 09:28	Reinspection Photo		Load JPG	☒
71	20/03/20 09:28	Reinspection Photo		Load JPG	☒
72	20/03/20 09:28	Reinspection Photo		Load JPG	☒
73	20/03/20 09:28	Reinspection Photo		Load JPG	☒
74	20/03/20 09:28	Reinspection Photo		Load JPG	☒
75	20/03/20 09:28	Reinspection Photo		Load JPG	☒
76	20/03/20 09:28	Reinspection Photo		Load JPG	☒
77	20/03/20 09:28	Reinspection Photo		Load JPG	☒
78	20/03/20 09:28	Reinspection Photo		Load JPG	☒
79	20/03/20 09:28	Reinspection Photo		Load JPG	☒
80	20/03/20 09:28	Reinspection Photo		Load JPG	☒
81	20/03/20 09:28	Reinspection Photo		Load JPG	☒
82	20/03/20 09:28	Reinspection Photo		Load JPG	☒
83	20/03/20 09:28	Reinspection Photo		Load JPG	☒
84	20/03/20 09:28	Reinspection Photo		Load JPG	☒
85	20/03/20 09:28	Reinspection Photo		Load JPG	☒
86	20/03/20 09:28	Reinspection Photo		Load JPG	☒
87	20/03/20 09:28	Reinspection Photo		Load JPG	☒
88	20/03/20 09:28	Reinspection Photo		Load JPG	☒
89	20/03/20 09:28	Reinspection Photo		Load JPG	☒
90	20/03/20 09:28	Reinspection Photo		Load JPG	☒

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
91	20/03/20 09:28	Reinspection Photo		Load JPG	☒
92	20/03/20 09:28	Reinspection Photo		Load JPG	☒
93	20/03/20 09:28	Reinspection Photo		Load JPG	☒
94	20/03/20 09:28	Reinspection Photo		Load JPG	☒
95	20/03/20 09:28	Reinspection Photo		Load JPG	☒
96	20/03/20 09:28	Reinspection Photo		Load JPG	☒
97	20/03/20 09:28	Reinspection Photo		Load JPG	☒
98	20/03/20 09:28	Reinspection Photo		Load JPG	☒
99	20/03/20 09:28	Reinspection Photo		Load JPG	☒
100	20/03/20 09:28	Reinspection Photo		Load JPG	☒
101	20/03/20 09:28	Reinspection Photo		Load JPG	☒
102	20/03/20 09:28	Reinspection Photo		Load JPG	☒
103	20/03/20 09:28	Reinspection Photo		Load JPG	☒
104	20/03/20 09:28	Reinspection Photo		Load JPG	☒
105	20/03/20 09:28	Reinspection Photo		Load JPG	☒
106	20/03/20 09:28	Reinspection Photo		Load JPG	☒
107	20/03/20 09:28	Reinspection Photo		Load JPG	☒
108	20/03/20 09:28	Reinspection Photo		Load JPG	☒

Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/01/20 22:00	TP ESTIMATE + docs.		Load PDF	
2	19/01/20 22:00	TP GIA REPORT		Load PDF	
3	16/02/20 23:15	TP ESTIMATE - MARKED		Load PDF	
4	24/02/20 16:14	EMAIL TO OI		Load PDF	
5	18/03/20 17:43	LOD		Load PDF	
6	18/03/20 17:43	LTA SEARCH		Load PDF	
7	31/03/20 15:28	EMAIL FROM WSP DD 310320		Load PDF	
8	14/04/20 10:43	Authorisation to Act		Load PDF	
9	14/04/20 10:43	Release Voucher		Load PDF	
10	14/04/20 10:43	WORKSHOP INVOICE		Load PDF	

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	21/01/20 10:38	OI GIA REPORT		Load PDF	
2	16/03/20 16:46	Letter of Demand from Third Party		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SME5465D (Insd veh)	Model:	BMW X1 SDRIVE18i 1.5 LED
	SLR9504S (TP veh)		NAV (A)
Date of Accident:	17/01/2020		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	31,296.86
Final Repair Cost	:	\$	18,788.45
Loss of Use	:	\$	420.00
Rental (if any)	:	\$	7.00 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	19,215.90
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u>	
BOLA Liability: <u>100</u> (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 19,215.90
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

14 Apr
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20001131/R1EA3S2**Date:** 14/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLR9504S**Insured Vehicle No :** SME5465D

Date of Loss: 17/01/2020

Nature of Claim: TP

Claim No: 6265339568SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLR9504S**

Make & Model: BMW X1 SDRIVE18I, 1.5 LED NAV (A)

Engine No: G394H480B38A15A

Reg. Date: 31/08/2017 (Man. Year: 2017)

Chassis No: WBAHS120605J97126

Colour: Black

Odometer: 33082 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,359.40	10,066.30	5,293.10	34.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,890.00	7,493.00	6,397.00	46.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,249.40	17,559.30	11,690.10	39.97
+ GST 7.00/7.00% (S\$)	2,047.46	1,229.15	818.31	39.97
Nett Amount (S\$)	31,296.86	18,788.45	12,508.41	39.97
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		19,215.90		

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance
Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*RUBBER MOUNTING	Not Necessary	35.60 FS	*- FS
2	1		*REAR SILENCER	Bent	1,465.05 FS	*1,178.35 FS
3	1		*TAILPIPE TRIM BLACK CHROME	Not Necessary	110.55 FS	*- FS
4	1		*HOLDER EXHAUST SYSTEM	Not Necessary	58.65 FS	*- FS
5	1		*BOOTLID	Bent	1,236.65 FS	*1,236.65 FS
6	1		*INTERIOR TAIL TRIM	Not Necessary	317.25 FS	*- FS
7	1		*REINFORCEMENT PLATE UNIVERSAL	Serviceable	52.50 FS	*- FS
8	1		*LH REINFORCEMENT PLATE SILL	Serviceable	53.75 FS	*- FS
9	1		*REINFORCEMENT	Serviceable	53.75 FS	*- FS
10	1		*LH REINFORCEMENT PLATE C PILLAR	Serviceable	53.75 FS	*- FS
11	1		*REINFORCEMENT	Serviceable	53.75 FS	*- FS
12	1		*LH REINFORCEMENT PLATE D PILLAR	Serviceable	65.35 FS	*- FS
13	1		*LH REINFORCEMENT PLATE D PILLAR	Serviceable	65.35 FS	*- FS
14	1		*REINFORCEMENT	Serviceable	65.35 FS	*- FS
15	1		*REAR LH BUMPER MOUNT	Serviceable	161.40 FS	*- FS
16	1		*REAR RH BUMPER MOUNT	Serviceable	161.40 FS	*- FS
17	1		*RR BUMPER CARRIER	Bent	496.35 FS	*496.35 FS
18	1		*MOUNTING SMART OPENER	Cracked	45.55 FS	*45.55 FS
19	1		*REAR TRIM UNDERRIDE PROTECTION (X L	Cracked	190.80 FS	*190.80 FS
20	1		*RR BUMPER LH CORNER MOUNTING	Cracked	142.65 FS	*142.65 FS
21	1		*RR BUMPER RH CORNER MOUNTING	Cracked	142.65 FS	*142.65 FS
22	1		*ABRASION GUA	Not Necessary	2.55 FS	*- FS
23	1		*ABRASION GUA	Not Necessary	2.55 FS	*- FS
24	1		*ABRASION GUA	Not Necessary	2.55 FS	*- FS
25	1		*ABRASION GUA	Not Necessary	2.55 FS	*- FS
26	1		*REAR BUMPER PANEL PRIMED	Deformed	903.40 FS	*903.40 FS
27	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Deformed	265.65 FS	*265.65 FS
28	1		*REAR BUMPER TRIM BOTTOM (LINES)	Cracked	232.45 FS	*232.45 FS
29	2		*EMBLEM GROMMET	Necessary	1.70 FS	*1.70 FS
30	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	71.60 FS	*71.60 FS
31	1		*LETTERING X1	Necessary	64.45 FS	*64.45 FS
32	1		*RIVET 24pcs	Not Necessary	12.00 FS	*- FS
33	1		*STRIKER BOOT LID	Serviceable	59.80 FS	*- FS
34	2		*SPINDLE DRIVE	Serviceable	711.30 FS	*- FS
35	1		*LOCK TRUCK LID	Serviceable	229.10 FS	*- FS
36	1		*SOFT CLOSE AUTOMATIC	Serviceable	601.30 FS	*- FS
37	1		*LOCK PLATE	Serviceable	12.40 FS	*- FS
38	1		*BUMP STOP 12pcs	Necessary	45.00 FS	*37.50 FS
39	1		*REAR WINDOW (ESG)	Serviceable	851.00 FS	*- FS
40	10		*HOOK AND LOOP FASTENER	Serviceable	28.50 FS	*- FS
41	1		*LOADING SILL COVER	Serviceable	144.65 FS	*- FS
42	1		*RR SILENCER HEAT INSULATOR	Serviceable	63.50 FS	*- FS
43	1		*REAR BUMPER HEAT INSULATION	Bent	69.85 FS	*69.85 FS
44	1		*VIBRATION AB	Not Necessary	241.10 FS	*- FS
45	1		*BOOTLID SEALING	Not Necessary	166.50 FS	*- FS
46	1		*REAR LH REFLECTOR	Not Necessary	38.85 FS	*- FS
47	1		*REAR RH REFLECTOR	Cracked	38.85 FS	*38.85 FS
48	1		*ULTRASONIC SENSOR BLACK 4pcs	Not Working 2pcs Only	999.80 FS	*499.90 FS
49	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.40 FS	*- FS
50	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
51	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
52	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
53	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	6		*BLIND RIVET NUT M6	Necessary	16.20 FS	*16.20 FS
55	1		*SILENCER CLAMPING BUSH	Necessary	54.60 FS	*54.60 FS
56	1		*GASKET RING	Necessary	30.45 FS	*30.45 FS
57	1		*V BAND CLAMP	Necessary	43.05 FS	*43.05 FS
58	1		*FRONT SILENCER	Bent	1,020.75 FS	*1,020.75 FS
59	1		*EXCH. CATALYTIC CONVERTER CLOSE TO	Bent	2,118.50 FS	*2,118.50 FS
60	1		*STEERING BOX HEAT RESISTANT PLATE	Bent	61.55 FS	*61.55 FS
61	4		*EXPANDING NUT	Necessary	4.00 FS	*4.00 FS
62	20		*EXPANDING RIVET BLACK	Necessary	28.00 FS	*28.00 FS
63	10		*PLUG BLACK D=5MM	Necessary	9.50 FS	*9.50 FS
64	1		*SENSOR WIRE FOR SMART OPENER TOP	Cracked	46.30 FS	*46.30 FS
65	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Cracked	50.90 FS	*50.90 FS
66	1		*CONTROL UNIT SMART OPENER	Cracked	497.05 FS	*497.05 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,359.40 10,066.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR TAIL PAN, REAR BOOT LID, REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC AND KNOCK ON ACCIDENT DAMAGE AREA.	New	4,675.00	2,125.00
2	SPRAY PAINTING REAR TAIL PAN, REAR BOOT LID, REAR BUMPER, REAR FLOOR PAN AND BOTH REAR SIDE FENDER.	New	5,120.00	2,474.00
3	TO REPLACE REAR WINDSCREEN GLASS.	New	574.00	574.00
4	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	New	531.00	0.00
5	TO CONDUCT WATER LEAK TEST.	New	75.00	75.00
6	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	0.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (1 PANEL)	New	118.00	100.00
8	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
9	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.	New	271.00	230.00
10	TO REPLACE FRONT EXHAUST SILENCER INCLUDING TO ALIGN SYSTEM AND CHECK FOR LEAK.	New	451.00	451.00
11	TO REPLACE CATALYTIC CONVERTER AND CHECK FOR FUNCTION.	New	451.00	451.00
12	TO REPLACE BOOT LID SMART OPENER CONTROL UNIT AND TOP & BOTTOM SENSOR LINES INCLUDE PROGRAMMING AND CHECKS FOR FUNCTIONS.	New	562.00	562.00
Gross Labour Cost (\$)			13,890.00	7,493.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >