

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001132/QKA3N2

Date: 22/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SHB1426T **Insured Vehicle No :** SMA6440P

Date of Loss: 15/01/2020 **Nature of Claim:** TP **Claim No:** 2235064231SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB1426T	Engine No:	2ZR6106549
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U005747560
Reg. Date:	13/08/2014 (Man. Year: 2014)	Odometer:	420597 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,045.48	956.58	6,088.90	86.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,965.00	670.00	1,295.00	65.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,010.48	1,626.58	7,383.90	81.95
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	9,010.48	1,500.00	7,510.48	83.35
+ Car Rental (5.0 x S\$133.75/day) (S\$)		668.75		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,175.75		
Global Sum Settlement (S\$)		2,100.00		

INSPECTION

Date of Assignment: 16/01/2020

Date Inspected: 16/01/2020 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
3	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
4	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
5	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
6	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
7	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
8	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
9	1		*ANTENNA ,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
10	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
11	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
12	1		*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
13	1		*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
14	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
15	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
16	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
17	1		*UNDER COVER SUB-ASSY RR FLOOR	Serviceable	514.50 F	*- F
18	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
19	1		*END PANEL	Repair	602.10 F	*- F
20	1		*END PANEL COVER ,DECK TRIM HOLE	Serviceable	46.10 F	*- F
21	1		*END PANEL COVER ,DECK TRIM RR	Serviceable	121.10 F	*- F
22	1		*TAILGATE DOOR LOCK	Serviceable	444.10 F	*- F
23	1		*TAILGATE LOCK COVER	Serviceable	15.70 F	*- F
24	1		*STRIKER ,BACK DOOR	Serviceable	48.90 F	*- F
25	1		*TAILGATE OUTSIDE GARNISH	Serviceable	504.90 F	*- F
26	1		*NAME PLATE (PRUIS)	Serviceable	60.80 F	*- F
27	1		*NAME PLATE (TOYOTA)	Serviceable	51.90 F	*- F
28	1		*SMRT LOGO	Serviceable	7.80 F	*- F
29	1		*STICKER DECAL 65558888	Serviceable	21.60 F	*- F
30	1		*SPOILER REAR	Serviceable	953.70 F	*- F
31	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
32	1		*TAIL LAMP LH	Serviceable	548.40 F	*- F

F=Franchise part.

Total Parts (S\$) 7,045.48 956.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	507.00	300.00
2	SPRAY PAINT	New	1,098.00	300.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
4	TO REPLACE SUNDRY PARTS	New	100.00	20.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
6	TO WASH AND VACUUM	New	60.00	0.00
			Gross Labour Cost (\$)	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >