



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2004101
INV Date 22/05/2020
Reference CC6/CTI20001135/Db3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SH 7091Z
Insured Veh. SLC 1670B
Claim No. SNM20D200136
Policy No. DMPCSN1725921902
Accident Date 08/01/2020
Inspection Date 15/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20001135/Db a3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-05-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 1670B	Veh. Inspected	SH 7091Z
Policy No.	DMPCSN1725921902	Coverage (\$)	0.00
Claim No.	SNM20D200136	Excess (\$)	0.00
Assign From		Assign Date	15/01/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU087060	Colour	BLUE
Odometer	444948	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	5 mm
L/H Front Tyre	205/60 R16	HANKOOK	5 mm
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/01/2020	Inspection Date	15/01/2020
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7091Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED / BENT	2,174.90	2,174.90
1	BOOTLID RUBBER	DEFORMED	96.50	96.50
2	BOOTLID HINGE (LH/RH)	NOT NECESSARY	284.60	-
1	BOOTLID LOCK UPPER	SERVICEABLE	114.90	-
1	BOOTLID LOCK LOWER	NOT NECESSARY	23.20	-
1	BOOTLID SONATA PLATE	NOT FITTED	37.90	-
1	BOOTLID HYUNDAI PLATE	NOT FITTED	21.10	-
1	BOOTLID 'H' EMBLEM	NECESSARY	22.70	22.70
1	BOOTLID CRDI PLATE	NOT NECESSARY	27.90	-
1	BOOTLID TRIMBOARD	NOT NECESSARY	143.90	-
11	BOOTLID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOTLID MOULDING (I40)	NOT NECESSARY	85.00	-
1	BOOTLID I40 EMBLEM (I40)	NOT NECESSARY	27.90	-
1	BOOTLID LOWER GARNISH (I40)	NOT NECESSARY	227.90	-
1	REAR BUMPER	DENTED	1,106.00	1,106.00
1	REAR BUMPER REINFORCEMENT BRACKET	DENTED	160.60	160.60
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
1	REAR BUMPER CLIP	NECESSARY	19.00	19.00
1	REAR BUMPER SPONGE	TORN	119.50	119.50
1	REAR BUMPER UNDER COVER	DISTORTED / CRACKED	228.00	228.00
1	REAR BUMPER REFLECTOR LAMP (I40)	NOT NECESSARY	32.00	-
2	TAIL LAMP (LH/RH) @\$697.80	CRACKED	1,395.60	1,395.60
2	TAIL LAMP QUARTER PANEL (LH/RH)	NOT NECESSARY	453.00	-
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	MTG DEFORMED	57.70	57.70
1	SPARE TYRE HOLDER	NOT NECESSARY	223.10	-
2	TAIL LAMP PANEL TOP (LH/RH)	NOT NECESSARY	189.10	-
1	SPARE TYRE PANEL	NOT NECESSARY	852.80	-
1	SPARE TYRE PANEL CUSHION	NOT NECESSARY	223.10	-
1	REAR PANEL INNER PANEL (I40)	NOT NECESSARY	380.00	-

Report Ref No. CC6/CTI20001135/Db3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST PIPE INSULATOR	NOT NECESSARY	117.10	-
1	EXHAUST SILENCER	NOT NECESSARY	1,935.40	-
1	EXHAUST PIPE HANGER	NOT NECESSARY	117.10	-
1	BONNET	NOT NECESSARY	2,265.90	-
1	BONNET LOCK	NOT NECESSARY	42.40	-
1	BONNET SEAL	NOT NECESSARY	31.90	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	7.00	-
1	RADIATOR GRILLE H EMBLEM	NECESSARY	39.50	39.50
1	RADIATOR GRILLE	BROKEN	1,480.00	1,480.00
1	FRONT BUMPER COVER	DISTORTED / MTG CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	DENTED	438.40	438.40
2	FRONT BUMPER GRILLE (LH/RH) @\$49.20	NOT NECESSARY	98.40	-
2	FRONT BUMPER BRACKET TOP (LH/RH)	NOT NECESSARY	44.80	-
1	FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40)	NOT NECESSARY	32.00	-
2	FRONT BUMPER BRACKET (LH/RH)	NOT NECESSARY	49.20	-
1	FRONT BUMPER SIDE BRACKET	NOT NECESSARY	4.60	-
1	FRONT BUMPER RETAINER MOUNTING	NOT NECESSARY	8.00	-
1	HEADLAMP SUPPORT PANEL ASSY	BENT	907.40	907.40
2	HEADLAMP (LH/RH) @\$2776.00	MTG CRACKED	5,552.00	2,776.00
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
2	HEADLAMP HALOGEN BULB (LH/RH)	NOT NECESSARY	28.80	-
1	RADIATOR	NOT NECESSARY	708.50	-
1	RADIATOR GUARD	NOT NECESSARY	35.00	-
2	HORN UNIT (LH/RH)	NOT NECESSARY	72.30	-
1	HORN WIRE	NOT NECESSARY	156.60	-
1	AIRCON CONDENSER	BENT	947.80	947.80
2	BOOTLID LAMP (LH/RH) @\$565.60	MTG CRACKED	1,131.20	1,131.20
	LESS 20% DISCOUNT		-5,463.86	-3,041.46
			21,855.44	12,165.84
	<u>SPECIAL NETT ITEMS</u>			
1	BOOTLID COMFORT LOGO & TEL NO.STICKER (SN)	NECESSARY	16.60	16.60

Report Ref No. CC6/CTI20001135/Db3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN) }	CRACKED	30.00	45.00
1	FRONT NO PLATE TRIM COVER (SN) }	BENT	30.00	-
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	118.00	118.00
			244.60	229.60
	<u>LABOUR</u>			
	PANEL BEATING.		1,600.00	700.00
	SPRAY PAINTING CHARGE.		1,800.00	700.00
	WIRING CHARGE.		120.00	30.00
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-
	FRONT /FOUR WHEEL ALIGNMENT .	NOT NECESSARY	120.00	-
	REMOVE/REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
			4,260.00	1,590.00
GRAND TOTAL			26,360.04	13,985.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,100.00

Report Ref No. CC6/CTI20001135/Db3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.