ASSIGNMENT

From Date:	7/01/2020	Veh No:	SHBITTT	Yr Regn: US/1	1/2013
Estimated Cost:		Type: M.Car /	M.Cycle / Bus / Van / I	orry / (Taxi) Prime Mov	er/
OUT WS/TP RES/OD RES/EVA/INV/MV	1	Truck /	Trailer of		
To Inspect Vehicle No: SHB 177	T	Make:	Toyota Priv	U. c.c	798
at Workshop m/s SMRT		Colour	Marcon	A/G: Insured / S	td / NI / NA
woodlends Depo	+	Sp.Reading	748200	T/Radio: Insured / S	std / NI / NA
Insured: GBE H300H		Eng/No:	_		
Policy No. 5076186185-04 (11/12/2019	-10/12/2020)	C/No:	JTDKN3648	05704102	
Claims No. MT/1083391-00		Gen. Cond: G	ood / Fair Poor / Burn		
Sum Insured: Excess:		Steering: Inor	der / Jammed / Leaked	I/Burnt or	
(Client's Record)		Brake: (nor	der / Jammed / Leaked	I/Burnt or	
Make of Veh:		Modi: Nil /	(Rim) / STD A/Rim	or	
		Tyre Size:	F: 195	165 R15	
(Policy Condition)	*		R: 195	165 R15	
Remark. The veh had commenced its	N/S O/S	BS / DUN / E		/ MIC / OHTSU / PIR / S	SUM! /
repair at the time of inspection.		TOYO / YOF	(O or West	alce.	
Bal, or Market Value:		Front		Rear	
IDAC Accident Rport: Consistent? : Ye	es or No	R/Bal.	5 mm	R/Bal. 9	mm
GIA / PR Seen: Consistent? : Ye	es or No	L/Bal.	mm	L/Bal. 5	mm
Est. Repairs: days Res.: Ye	s or No	D.O.A. 15/	01/2020	D.O.I. 17/01	12020
Lum Sum: % 3 Val.: Ye	s or No	Survey held a	tS/	MRT.	
CA / REV / REP. / 24 HRS 140 P)		Des. of Dama	iges: Frt / Rear / O/S	I N/S / U/C / Roofto	p or
	Vehicle: IN / OUT		N/S Fro		
Date: Person Contacled:		The U/C	Chassis frame / Bo	dy Structure affected du	e to collision.
Date / Time Action / Instruction	LEGISTER DAG			TP	
SHB HATT COS AVAINGE				TAX/01/2	0/0071
Ship in the commission	2007 1 1-110,21, 0	an including	4.017		+300 H
Confirm with Poh Su	un	. 0	1 Lanz ca	7/0/\	
Finalize \$ 2,700 @ 3	days. (215)	(Keo	(\$4015-71)	16%)	
Date/Time, File Pass to? : Preli. Report	E.	ays Of Rep	pair: 3		
; Final Report	F	Resurvey No	o. of Trip: 2	Survey Fee:	160
Date/Time, File Return to?			1346	Transportation:	
1/2/20 Typist	Add Fee:	beautal	nsp (\$)_3+RSSI	
· ·	*	l-mark	riew (\$) Photos	
Report Format:			MAS (8	.) Chiners	
(mp 20)/1.B.1: 12 \$2700F		Wee	and (S		
				TOTAL	160

TP CI	aims against NTUC	TP Claims against NTUC Income: Follow-Through Survey					
Date:	0//02/2020						
S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	Σ	SMRT TAXIS PTE LTD	SHB177T	GBE4300H	15/01/2020	17:00	\$ 11,713.59
2							
3							
4							
2							
9							
7							
8							
6							
10							
11							

	70000000		V COLUMN		9			Distance.	9511511	lClaim
601						· Change I	Language	+ Change	e Password	· Log Ou
Polic	cy Query									
Policy N	lo.				Date	of Accident	15	/01/2020 09	:33	
Vehicle	No.(For Motor)	GBE43	GBE4300H			Certificate Number				
				1	Search					
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
0	5076186185- 04		ACTIVE VISUAL PTE LTD	200402540H	GCV	Comprehensive	GBE4300H	Description of the Control of the Co		10/12/2020
	Policy N Vehicle Select	Policy Query Policy No. Vehicle No.(For Motor) Select Policy No. 5076186185-	Policy Query Policy No. Vehicle No.(For Motor) Select Policy No. Certificate Number 5076186185-	Policy Query Policy No. Vehicle No.(For Motor) Select Policy No. Certificate Number Name 5076186185- 04 VISUAL PTE	Policy Query Policy No. Vehicle No.(For Motor) Select Policy No. Certificate Number Name Policyholder NRIC S076186185- 04 VISUAL PTE 200402540H	Policy Query Policy No. Date Vehicle No.(For Motor) GBE4300H Certificate Select Policy No. Certificate Policyholder NRIC Product So76186185- 04 ACTIVE ACTIVE VISUAL PTE 200402540H GCY	Policy Query Policy No. Vehicle No.(For Motor) Select Policy No. Certificate Number Select Policy No. Certificate Number Select Number Name Name NRIC So76186185- O4 VISUAL PTE 200402540H GCy Comprehensive	Policy Query Policy No. Date of Accident 15 Vehicle No.(For Motor) GBE4300H Certificate Number Search Select Policy No. Certificate Number Name Name NRIC So76186185- O4 VISUAL PTE 200402540H GCV Comprehensive GBE4300H	Policy Query Policy No. Date of Accident 15/01/2020 09 Vehicle No.(For Motor) GBE4300H Certificate Number Search Select Policy No. Certificate Number Number Name Name Name NRIC Product Cover Type No. Object ACTIVE VISUAL PTE 200402540H GCV Comprehensive GBE4300H GBE4300H	Policy Query Policy No. Date of Accident Certificate Number Search Select Policy No. Certificate Number Select Policy No. Certificate Number Number Name NRIC Product Cover Type Vehicle Insured Object Date ACTIVE NCTIVE OA VISUAL PTE 200402540H GCV Comprehensive GBE4300H GBE4300H 11/12/2019

Oi Sun Pin (LKK Auto)

From:

Oi Sun Pin (LKK Auto)

Sent:

Friday, 7 February, 2020 10:32 AM

To:

Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject:

RE: SHB177T

Hi Poh Suan,

Confirm the finalize amount \$2,700. Repair day 3 days under lump sum repair.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]

Sent: Friday, 31 January, 2020 2:57 PM

To: Oi Sun Pin (LKK Auto) Cc: SUR; CS A Team

Subject: SHB177T

Hi Sun Pin,

Attached herewith the repair estimate of SHB 177T having Case No: TAX/01/20/2071.

There is no change to the approved amount of \$2,700 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards Poh Suan

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Sent: Friday, 31 January 2020 1:20 PM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

CE LTD
THEFT

 Name of Driver
 TAN TECK KI

 NRIC No
 SXXXX997H

 Date Of Birth
 17/06/1967

 Occupation
 OUTDOOR

 Date Of Driving Pass
 16/04/1993

Driving Experience 26 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-80000000

Fax Number

Contact Number

EMail Address NOEMAIL

Address

11

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?

...

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I ALIGHTED A PASSENGER ALONG SIMS AVE AND SUDDENLY A VEHICLE GBE4300H FROM THE LEFT CUT TOWARDS MY LANE AS HE WANTED TO TURN RIGHT TOWARDS LOR 15 GEYLANG. AS SUCH COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBE4300H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

CHEW SHENG KIT

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAM

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- -3. Unformation provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law or administering, processing, bandling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law tirms, may/are permitted to collect, or a discloss and/or processing Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law introd, which may be sited entails of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (c) the information conflicted under (d) above any tie disperty declined
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature Date & Time:

Driver's Signature
(If driver is not the policyholder)

(If driver is not the policy)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sims A	/2 <u>D</u>	
A-SHB177TB-GBE4300H	4 15 15 15 15 15 15 15 15 15 15 15 15 15	N. 1
	Seylang	16/1/2020.

	manual manager of t	
1		
 	and the same of th	
A.		
	13	
The state of the s		

161/2020

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time:

16/1/2020

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	369K
Vehicle No.:	SHB177T
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5930872
Chassis No.:	JTDKN36U805704102
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	08 Nov 2013
First Registration Date:	08 Nov 2013
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$8,368.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Nov 2021
PARF Rebate Amount: Intended COE Rebate Details	\$5,439.00
COE Expiry Date:	07 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$63,297.00
COE Rebate Amount:	\$14,234.00
Total Rebate Amount: Message	\$19,673.00
Please note that the 8-year COE for this vehicle cannot	be further renewed. The vehicle must be de-registered upon COE expiry or when the

The information contained herein is correct as at 20 Jan 2020

vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

				SMRT Recon	nmen	fation						Sur	veyor Approval		
BÔM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give ▼	Xsvc	SN
One Time Key In	Main			BUMPER GRILLE SUB- ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give *	Xzv(
One Time Key	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0	Check *	Xsrc	10%
In One Time Key In	Main			LENS & BODY,FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace *	/ SCH	1 104
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give 7	XSY	10%
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check *	XIrc	
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give *	Xsvc	
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give •	Xsvc	
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	XIV	
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	XSV(
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	Xsvi	
One Time Key In	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Giv€	xsx	
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Giv€	XSV	
One Time Key In	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	0	0	Not Giv€	XIVC	
One Time Key In	Main			HOOD PANEL INSULATOR	1	390.50	390.50	25.00	292.88	Replace	0	0	Not Give	Xsvc	
One Time Key In	Main			HOOD HINRE LH	1	55.90	55,90	25.00	41.92	Replace	0	0	Not Give	.XSVc	

Total Spare Part Cost 11,210.74

Surveyor Total 1,955.32

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,968.59

Final Sur Total 1,564.26



Case Details

Case Reference Number :

TAX/01/20/2071

Type of Repair : Accident Repair

Vehicle Registration Number: SHB177T

Company Type: SMRT Taxis Pte Ltd

Estimation ID: EST-10174-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name: NTUC Income Insurance Co-operative

Surveyor Approval

Accident Date and Time: 15/01/2020 09:00 AM

Vehicle Age(In Months): 74

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

				SMRT Recor	mmeno	dation						Sur	veyor Approval
вом Туре	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(S)	Repair/Replace Remarks
One Time Key In	Main		1	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	.1	361.50	Replace , C U
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace / NEC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give *X 5vc
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give • X S V C
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	1	59.10	Replace · / CR VI
One Time Key In	Main			BUMPER REINFORCEMENT FRT	.1.	498.40	498.40	25.00	373.80	Replace	0	0	Not Give • X SV
One Time Key In	Main			ARM SUB- ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give • X 5 VC
One Time Key In	Main			ARM SUB- ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give ▼ ∑ S ∨ C
One Time Key In	Main			BRACKET, FR BUMPER	-1	110.40	110.40	25.00	82.80	Replace	0	0	Not Give ▼X 5 ℃
One Time Key	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give . X SVC SN

Total Spare Part Cost 11,210.74

Surveyor Total

Lump Sum Discount (%) 20.00

Lump Sum Dis (%)

Final Spare Part Cost 8,968.59

Final Sur Total 1,564.26

				SMIT HECOI		uation						Sui	veyor Approvar	
ВОМ Туре	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks	
One Time Key In	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.92	Replace	0	0	Not Give + XSVC	
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace / CRA	(0
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give • XSVC	16
One Time Key In	Main			WIPER WASHER INLET	1	36.90	36.90	25.00	27.67	Replace	0	0	Not Give XSVC	
One Time Key In	Main			WIPER WASHER JAR	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give *XSVC	
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give • XSVC	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give • XSVC	
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give • XSVC	
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49,30	25.00	36,97	Replace	0	0	Not Give • XSVC	
One Time Key In	Main			QUARTER GLASS FRT/RH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give • XSVC	
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give • XSVC	
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair X	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38,92	Replace	1	38.9¢ 3.	Replace · / NEC	
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Check · XSVC	
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check · XSVC	
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	1	128.7	Replace · / CRY	

4947

Total Spare Part Cost 11,210.74

Lump Sum Discount (%) 20.00

Surveyor Total 1,955.32

Lump Sum Dis (%) 20

Final Sur Total 1,564.26

Final Spare Part Cost 8,968.59

Surveyor Approval

Final Sur Total 1,564.26

				SMRT Recor	nmen	dation						Surv	eyor Approval	
BÒM Type	Costing Type	Portion	Material Number	Part Name	Oty	List Price Per Unit(S)	List Price(\$)	Dis(%)	Final Price(S)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remar	ks
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check X	(
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give • X 5	(gu
One Time Key In	Main			MIRROR ASSY,RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Give ▼ X ∫√	ζ.
One Time Key In	Main			MIRROR LAMP	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give • X S V (10%
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give *X { \(\)	C
One Time Key In	Main			TUBE & ACCESSORY	1	631.90	631.90	25.00	473.92	Replace	0	0	Check • X JV	(
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Not Give • X SV	(10%.
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	1	0.00	Replace *	PA 109
One Time Key In	Main			BRAKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	1	43.65	Replace •	PA
One Time Key In	Main			BRAKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give • XIV	
One Time Key In	Main			BRAKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give • XSV	S
One Time Key In	Main			MOTOR NO:1, WIPER WASHER JAR	1	239.00	239.00	10.00	215.10	Replace	0	0	Not Give ▼ XS∨	(10%
One Time Key In	Main			MOTOR NO:2, WIPER WASHER JAR	1	240.00	240.00	10.00	216.00	Replace	0	0	Not Give • XSV	(10%
						т	otal Spare	Part Cost	11,210.74			Surveyor Total	1,955.32	
						Lum	p Sum Dis	count (%)	20.00		Lum	p Sum Dis (%)	20	
						Lun	p outil bis	- Sunt (79)	20,00			,	20	
				7710 0	573									

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	400	

507.00

400.00

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Remarks Adjustment(\$)
19	Main	TO REPSRAY FRONT BUMPER	378.00	200
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0
3	Main	TO RESPRAY FRONT FENDER RH	378.00	0
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200
5	Main	TO REPSRAY FRONT HOOD	378.00	0
Total:			1,692.00	400.00

Other Cost Detail

1 Main TO REPLACE SUNDRY PARTS 100.00 20 2 Main TO CHECK WIRING AND SYSTEM FUNCTION 80.00 20 3 Main TO WASH AND VACUUM 60.00 0 4 Main TOWING CHARGE 56.00 0 5 Main TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) 125.00 0 6 Main TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) 125.00 0 Total:	S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
FUNCTION 20.00 20 3 Main TO WASH AND VACUUM 60.00 0 4 Main TOWING CHARGE 56.00 0 5 Main TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) 125.00 0 6 Main TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) 0	1		TO REPLACE SUNDRY PARTS	100.00	20	
4 Main TOWING CHARGE 56.00 0 5 Main TO PROVIDE LABOUR & MATERIAL FOR 125.00 0 6 Main TO PROVIDE LABOUR & MATERIAL FOR 125.00 0 SOLAR FILM (NET)	2	Main		80.00	20	
5 Main TO PROVIDE LABOUR & MATERIAL FOR 125.00 0 SOLAR FILM (NET) 6 Main TO PROVIDE LABOUR & MATERIAL FOR 125.00 0 SOLAR FILM (NET)	3	Main	TO WASH AND VACUUM	60.00	0	
SOLAR FILM (NET) TO PROVIDE LABOUR & MATERIAL FOR 125.00 0 SOLAR FILM (NET)	4	Main	TOWING CHARGE	56.00	0	
SOLAR FILM (NET)	5			125.00	0	
Total: 546.00 40.00	6			125.00	0	
	Total:			546.00	40.00	

17266.40

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,968.59	1,564.26
Total Labour Cost	507.00	400.00
Total Spray Painting	1,692.00	400.00
Other	546.00	40.00
Overall Total	11.713.59	2,404.26
Lump Sum Repair Option		*
Lump Sum Total	11,713.59	2,400.00
Surveyor Approved Amount		2,400.00

Estimator Assesment(\$)

Remarks

Surveyor Name

No of Repair Days*

Signature

Survey Date

17/01/2020

Surveyor Assesment(\$)

Lump Sum Repair, after paint photo.

Sun Pin (LKK)

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUESTFOR SUPPLYMENT PARTS

Contractor:	The state of the s	The second second	
Acoident Case Number	TAX OILO ZAT	Date of Collection :	1.1
Vehicle No	SHB 177-T	Date of Request	18 101/2020
Vehicle Model	TOTOIA PRIUS	Number of Days to Extend (If any)	20

S/N	Part Number	Part Description	Quantity	Unit Price
1		GRILLE RADIATOR	lac	
		Bumper LIP FROM	in:	MISS/NG+
				• • • •
				,

Please submit photographs for damaged paris>>>

I, (Name)			*			
-			 	-		 -
(Position)	7			•		
(FUSILIOIL)					10.3	
		i-			-	

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration [tobs signed in front of an authorised witness]

I asknowledge that this declaration is true and correct, and I make it with the understanding and bilef that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
. Approval By	Surveyor/In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22/PO/WOC/ Reservation/Number
Photo Submitted	YES/NO	Date of submission





SMRT Accident Vehicle Repair Estimates

SIART Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63985592 Estimator Telephone Number : 68652672 Accident Reporting Number : 68652672

-	Generale	30/01/2021
User	ID	PahSusa

	Section A - Accident Details
Registration Number	SHB177T
Case Reference Number	TAX/01/20/2071
Registration Date	8/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	ТОУОТА
Model	PRIUS
Name of Driver	TAN TECK KIM
Type of Accident	Side Swipe
Accident Date and Time	15/1/2020 5:00 PM
Accident Reported Date and Time	15/1/2020 11:49 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	15/1/2020 5:19 PM
Replacement Vehicle issued?	No
Job Card Number	24105341
Special Instruction to ARC, if any	BP / LEFT FRONT PORTION
Prepared Date and Time	17/1/2020 9:06 AM
Chassis Number	
Mileage	
Vork Shop	
Repair Completion Date and	





boths

	Section B - Summary of Repair E			
Summary of Repair Estimates				
The state of the s	Quotation from ARC	Adjusted by Surveyor, if applicable		
Total Labour Cost	\$507.00	\$400.00		
Total Spray Cost	\$1,692.00	\$400.00		
Total Spare Part Cost	\$11,548.39	\$2,545.08		
Total Other Cost	\$546.00	(\$645.08)		
TOTAL COST	\$14,293.39	\$2,700.00 (L/S)		
Lump Sum Total	\$0.00	\$0.00		
Number of Repair Days	5.0	3.0		
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC		
ARC / Surveyor Sign Off Date	20/01/2020 2:52 PM	20/01/2020 11:48 AM		
Signature				
Remarks	Total number of repair days = 3 days. SUP = 0 day.	Lump Sum Repair, after paint photo.		



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 50 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63665592 Estimater Telephone Number : 68662623 Accident Reporting Number : 68662672

Date Generated : 30/01/2020 User ID : PohSuan

1000年の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の	4.0.80克里斯斯斯斯特 1000 1000 1000 1000 1000 1000 1000	tion and Accident Invoice Details	医多种 医多种性
Quotation Number	QN-2001-0373	Invoice Number	
Quotation Date	30.01.2020	Invoice Date	
Invoice Amount		Prepared Date	

art 1 - Labour Works	Section D - Details of Repair Estimates	
ob Scope		
2014年1月1日 - 1906年1月1日 - 19	Quotation from AR	Adjusted by Surveyor, I
O REPAIR FRONT LH PORTION	\$507.00	applicable
otal Labour		\$400,00
	\$507.00	\$400.00

Job Scope		
	Quotation from ARC	Adjusted by Surveyor,
TO REPSRAY FRONT BUMPER	\$378.00	applicable
CO DECORATION OF THE PROPERTY	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	
O RESPRAY FRONT FENDER RH		\$0.00
O MEST TONT PENDER RH	\$378.00	\$0.00
O RESPRAY FRONT FENDER LH	0070	60.00
	\$378.00	\$200.00
O REPSRAY FRONT HOOD	\$378.00	
416	0070.00	\$0.00
otal Spray Painting & Panel Beating	\$1,692.00	\$400.00

Job Scope	(A) 10 10 11 11 11 11 11 11 11 11 11 11 11	
NULL SIZE OF SELECT SELECTION AS A SELECT	Quotation from ARC	Adjusted by Surveyor, if
Lump Sum Adjustment by Surveyor	\$0.00	applicable
	30.00	(\$685.08)
TO REPLACE SUNDRY PARTS	\$100.00	
	3100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	
CHICAR CANADA LES ESPASA MACIONA	555.55	\$20.00
TO WASH AND VACUUM	\$60.00	
COMMISSION OF THE PROPERTY OF	455,55	\$0.00
OWING CHARGE	\$56.00	
O BROUDE LABOUR AND		\$0.00
O PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	
O PROVIDE LABOUR & MATERIA		\$0.00
O PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
otal Other Costs		30.00
The Other Costs	\$546.00	(\$645.08)

Part Number	Portion	Stock Number	Part Name	Quantity	After Middle Asia Stockers and a final	Discount	Final Price	Estimator	Surveyor
		52119- 47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Approved Replace	Approved Replace
		52161- 16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52115- 47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	/
		52116- 47040	BUMPER SUPPORT FILH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52611- 47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace
		52021- 47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given
		57014- 47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		57013- 47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		52114- 47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00		Replace	Not Given V
			NUMBER PLATE FRAME	0.00	\$12.00	0.00		Replace	Not Given J



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 80 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592 Estimator Telephone Number : 68692623 Accident Reporting Number : 68692672

Date Generated: 30/01/2020

UserID : PohSuan

	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given
53102- 47020	BUMPER GRILLE SUB- ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given
82113- 47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check
81521- 47050	LENS & BODY,FR TURN LE	1.00	\$511.80	10.00	\$460.62	Replace	Replace
81511- 47050	LENS & BODY, FR TURN	0.00	\$511.80	0.00	\$0.00	Replace	Not Given
53289-	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check
47032 53111-	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	
47040 53113 -	GRILLE, RADIATOR	0.00	\$94.60	0.00		1000	Not Given
47040 76851-	LOWER NO.2 BUMPER LIP FRT	0.00			\$0.00	Replace	Not Given
47020 52618-	D254 00 10 10 10 10 10 10 10 10 10 10 10 10		\$139.60	0.00	\$0.00	Replace	Check
47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check
51410- 12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given
51444- 12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given
51443- 12080	UNDER COVER SIDE/RH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given
53301-	HOOD PANEL	0.00	\$748.10	0.00	\$0.00	Replace	Not Given
47060 53341-	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00)
47020 53420-	HOOD HINRE LH	0.00	MAN SELECTION	100000		Replace	Not Given
47070 53410-			\$55.90	0.00	\$0.00	Replace	Not Given
47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given
81170- 47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
81130- 47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given
65319- 47120	WIPER WASHER INLET	0.00	\$36.90	0.00	\$0.00	Replace	Not Given
85315-	WIPER WASHER JAR	0.00	\$180.10	0.00	\$0.00	Replace	Not Given V
47140 53801-	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given
47050 75374-	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given
47051 53875-	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	1 1 2	Х
47030 53851-	FENDER LINER PAD, FR	0.00				Replace	Not Given X
47040	WHEEL RH		\$49.30	0.00	\$0.00	Replace	Not Given X
62110- 47021	QUARTER GLASS FRT/RH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given X
62120- 47021		0.00	\$234.90	0.00	\$0.00	Replace	Not Given X
53802- 47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair 0
75374- 47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
53826- 47010		0.00	\$46.10	0.00	\$0.00	Replace	Check V
53828-		0.00	\$114.50	0.00	\$0.00	Replace	Check X
47060 53876-	FENDER SIDE PANEL LH FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	1
47030 53852-		0.00	\$49.30			I SENTAL III SEA	Replace
47020	WHEEL. LH			0.00	\$0.00	Replace	Check X
97040	Limbon	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
87910- 47330	MIRROR ASSY,RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given X
81730- 52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X
879157- 4010	COVER, OUTER MIRROR, I	0.00	\$107.40	0.00	\$0.00	Replace	Not Given X
88710- 47150	THE COURSE OF THE PARTY OF THE	0.00	\$631.90	0.00	\$0.00	Replace	Check V
81210-	FOG LAMP RH	.00	\$295.20	0.00	\$0.00	Replace	Not Given
12230 81220-	FOG LAMP LH 1	.00	\$280.10	10.00	\$252.09		
12230 81529-	D. D. L. Communication of the				1	Replace	Replace
47060	CENTER LH	.00	\$58.20	25.00	\$43,65	Replace	Replace /



47020

Total

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 00 Woodlands Industrial Park E4, Singapore 757705 FAX Number 63585592 Estimator Telephone Number : 68863833 Accident Reporting Number | 68662572

Date Generated - 30/01/2020

Jan. 11.	1000		****
leer 10)	\$17	PohSuan

		81529- 47040	BRAKET, FR TURN UPPER	0.00	\$24.40	0.00	\$0.00	Replace	Not Given 🗸
		81529- 47050	BRAKET, FR TURN LOWER	0.00	\$26.00	0.00	\$0.00	Replace	Not Given
		85330 47010	MOTOR NO:1, WIPER WASHER JAR	0.00	\$239.00	0.00	\$0.00	Replace	Not Given
Total		85330 60180	MOTOR NO:2, WIPER WASHER JAR	0.00	\$240.00	0.00	\$0.00	Replace	Not Given X
TOTAL					\$14,056.71		\$2,207.43		
Added Sp Part	Portion	Material Usa	ge After Surveyor Signed off						
Number	Fortion	Number		Quantity	List Price \$	Discount (%)	Final Price	ARC Check	
		53111-	00000		THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	11/01/2000		B CONTRACTOR	Check
		47040	GRILLE, RADIATOR	1.00	\$310.60	25.00	\$232.95	Replace	Replace /

450.20

25.00

\$104.70

337.65

Replace

Replace

Mil

2545.08/ + 400.00/ + 440.00/ + 385.08/ 2708.06/ 2700/-/ 43 dys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSUF	TUC INCOME INSURANCE CO-OPERATIVE LTD			10/Qyf3e2
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date:	10-02-2020	
	D-11 D-411	Code:	INC4	The second second second
1. Insured Veh.	Policy Particulars GBE 4300H	_	nspected	SHB 177T
	5076186185-04	-	age (\$)	0.00
Policy No. Claim No.	MT/1083391-001	Exces		0.00
	W171063391-001	_	n Date	17/01/2020
Assign From	Vehicle Parti			1770112020
2. Make & Model	TOYOTA PRIUS	c.c	Condition	1798
Engine No.	HIDDEN	-	of Reg.	2013
Chassis No.	JTDKN36U805704102	Colou		MAROON
Odometer	748200	-		IN ORDER
Brakes	IN ORDER	Steering Modification		SPORTS RIM
General	FAIR	Wiodii	ication	OI OI (TO TAIM
3.		ions of	Tyres	
	Size	Make	.,,	Balance
R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm
4.	Descripti	on of D	amages	
	STAINED DAMAGES AT THE N/S	S FRONT	PORTION.	
DAMAGES SEE D	ETAILS			
5.		I Inform	nation	
Accident Date	15/01/2020	Inspe	ction Date	17/01/2020
Survey held at	SMRT AUTOMOTIVE SERVICE			
	60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 757	705
5a.	R	emarks		
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, V	THOUT F	REJUDICE" BASIS NOT AUTHORISE	D REPAIRS.
5b.	Estimate	Days o	f Repair	
ESTIMATED NOR	MAL PERIOD FOR REPAIR:		3 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 177T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	сит	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRUMPLED	78.80	59.10
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	FENDER LINER FRT / LH (DISC 25%)	CRUMPLED	171.70	128.78
1	BRAKET, FR TURN CENTER LH (DISC 25%)	CRACKED	58.20	43.65
1	GRILLE, RADIATOR (DISC 25%)	CUT	310.60	232.95
1	BUMPER LIP FRT (DISC 25%)	MISSING	139.60	104.70
1	LENS & BODY, FR TURN LH (DISC 10%)	SCRATCHED	511.80	460.62
1	HEAD LAMP LH (DISC 10%)	CRACKED	945.20	850.68
1	FOG LAMP LH (DISC 10%)	CRACKED	280.10	252.09
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	,
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	1
1	NUMBER PLATE FRAME	SERVICEABLE	12.00	
1	NUMBER PLATE	SERVICEABLE	15.00	
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	
1	WIRE, ENGINE ROOM, NO.3	SERVICEABLE	242.00	
1	LENS & BODY, FR TURN RH	SERVICEABLE	511.80	
1	COVER, RADIATOR	SERVICEABLE	122.80	
1	GRILLE, RADIATOR	SERVICEABLE	310.60	
1	GRILLE, RADIATOR LOWER NO. 2	SERVICEABLE	94.60	
1	BUMPER LIP FRT	SERVICEABLE	139.60	
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	
1	UNDER COVER CENTER	SERVICEABLE	448.30	
1	UNDER COVER SIDE/LH	SERVICEABLE	46.10	
1	UNDER COVER SIDE/RH	SERVICEABLE	46.10	

Report Ref No. NS/INC20001140/Qyf3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HOOD PANEL	SERVICEABLE	748.10	
1	HOOD PANEL INSULATOR	SERVICEABLE	390.50	
1	HOOD HINGE LH	SERVICEABLE	55.90	
1	HOOD HINGE RH	SERVICEABLE	55.90	
1	HEAD LAMP RH	SERVICEABLE	945.20	
1	WIPER WASHER INLET	SERVICEABLE	36.90	
1	WIPER WASHER JAR	SERVICEABLE	180.10	,
1	FENDER FRT / RH	SERVICEABLE	723.40	
1	NAME PLATE (HYBRID)	SERVICEABLE	51.90	
1	FENDER LINER FRT / RH	SERVICEABLE	171.70	
1	FENDER LINER PAD, FR WHEEL. RH	SERVICEABLE	49.30	
1	QUARTER GLASS FRT / RH	SERVICEABLE	234.90	,
1	QUARTER GLASS FRT / LH	SERVICEABLE	234.90	
1	FENDER PROTECROR FRT / LH UPPER	SERVICEABLE	46.10	
1	PROTECTOR, FRONT FENDER SIDE PANEL LH	SERVICEABLE	114.50	
1	FENDER LINER PAD, FR WHEEL LH	SERVICEABLE	49.30	
1	SEALANT W/SCREEN	SERVICEABLE	37.00	,
1	MIRROR ASSY, RH	SERVICEABLE	1,307.10	
1	MIRROR LAMP RH	SERVICEABLE	65.30	
1	COVER, OUTER MIRROR, RH	SERVICEABLE	107.40	
1	TUBE & ACCESSORY	SERVICEABLE	631.90	,
1	FOG LAMP RH	SERVICEABLE	295.20	
1	BRAKET, FR TURN UPPER LH	SERVICEABLE	24.40	
1	BRAKET, FR TURN LOWER LH	SERVICEABLE	26.00	
1	MOTOR NO:1, WIPER WASHER JAR	SERVICEABLE	239.00	
1	MOTOR NO:2, WIPER WASHER JAR	SERVICEABLE	240.00	
1	FENDER FRT / LH	TO REPAIR SEE LABOUR	723.40	
			14,521.40	2,545.08
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER FRT / LH.		507.00	400.00
	SPRAY PAINT.		1,692.00	400.00

Report Ref No. NS/INC20001140/Qyf3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No :3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	
	TOWING CHARGE.	NOT NECESSARY	56.00	
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.	NOT NECESSARY	125.00	-
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.	NOT NECESSARY	125.00	-
			2,745.00	840.00
	GRAND TOTAL		17,266.40	3,385.08

RECOMMENDED COST OF LUMP SUM REPAIRS	2,700.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC20001140/Qyf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.