



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003249
INV Date 17/04/2020
Reference CC6/CTI20001146/Uea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SJP 3884T
Insured Veh. SJK 540G
Claim No. SNM20D200438C02/0
Policy No. DMHCSN1937231900
Accident Date 18/01/2020
Inspection Date 20/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20001146/Uea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 17-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 540G	Veh. Inspected	SJP 3884T
Policy No.	DMHCSN1937231900	Coverage (\$)	0.00
Claim No.	SNM20D200438C02/0	Excess (\$)	0.00
Assign From		Assign Date	20/01/2020

2. Vehicle Particulars & Condition

Make & Model	mitsubishi LANCER (A)	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JMYSTCS3A9U005292	Colour	SILVER
Odometer	68898	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	MICHELIN	6 mm
L/H Front Tyre	195/60 R15	MICHELIN	6 mm
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/01/2020	Inspection Date	20/01/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 3884T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	DENTED / BENT	788.00	684.00
1	BOOTLID OUTER GARNISH	NOT NECESSARY	245.00	-
1	BOOTLID INNER LOCK	TWISTED	149.00	149.00
1	BOOTLID WEATHERSTRIP	TWISTED	197.00	197.00
2	BOOTLID HINGES @\$105.00	NOT NECESSARY	210.00	-
1	BOOTLID REAR LOGO	NECESSARY	48.00	48.00
1	BOOTLID LOCK CABLE	NOT NECESSARY	102.00	-
1	REAR BUMPER	DEFORMED / TORN	781.00	781.00
1	REAR BUMPER BEAM	BENT	186.00	154.00
2	REAR BUMPER SIDE RETAINERS @\$45.00	BENT	90.00	90.00
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	REAR BUMPER LOWER SKIRTING	TORN	780.00	681.00
1	REAR END PANEL	BENT	545.00	442.00
1	REAR END PANEL TOP GARNISH	TWISTED	192.00	192.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	876.00	-
1	REAR FLOOR PANEL TOP BOARD	TORN	315.00	315.00
2	REAR FENDERS @\$745.00	TO REPAIR SEE LABOUR	1,490.00	-
2	REAR FENDER INNER TRIMS @\$242.00	O/S TORN	484.00	242.00
2	TAILLAMPS @\$406.00	CRACKED	812.00	812.00
1	REAR EXHAUST	BENT / TWISTED	525.00	525.00
2	REAR EXHAUST MOUNTINGS @\$60.00	NOT NECESSARY	120.00	-
2	TAILLAMP HOUSING PANELS @\$145.00	TO REPAIR SEE LABOUR	290.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	121.00	-
1	SET REAR FLOOR PANEL INSULATOR	NOT NECESSARY	180.00	-
1	REAR LICENCE PLATE W/HOLDER	NOT NECESSARY	50.00	-
1	REAR LICENCE PLATE W/HOLDER	NOT NECESSARY	50.00	-
	LESS 10% DISCOUNT		-	-535.70
			9,671.00	4,821.30

Report Ref No. CC6/CTI20001146/Uea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
			330.00	250.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.		80.00	60.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		150.00	60.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR FENDERS AND TAILLAMP HOUSING PANELS.		1,800.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,100.00
			4,460.00	2,040.00
	GRAND TOTAL		14,461.00	7,111.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,600.00

Report Ref No. CC6/CTI20001146/Uea3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.