

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001169/UEA3Q2

Date: 11/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994098

Claimant
Vehicle No : SLR5130M **Insured Vehicle No :** SJE8102S

Date of Loss: 19/01/2020 Nature of Claim: TP Claim No: 2968513976SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR5130M		
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Engine No:	P520463616
Reg. Date:	17/08/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0173409
Colour:	Silver	Odometer:	43664 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,445.00	3,236.96	8,208.04	71.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,780.00	2,250.00	55.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,475.00	5,016.96	10,458.04	67.58
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	15,475.00	4,000.00	11,475.00	74.15
+ GST 7.00/7.00% (S\$)	1,083.25	280.00	803.25	74.15
Nett Amount (S\$)	16,558.25	4,280.00	12,278.25	74.15
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,527.45		

INSPECTION

Date of Assignment: 20/01/2020

Date Inspected: 20/01/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,269.00 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	75.00 F	*- FL
3	1		*BOOTLID SKYACTIVE EMBLEM	Not Necessary	63.60 F	*- FL
4	1		*BOOTLID MAZDA EMBLEM	Not Necessary	64.00 F	*- FL
5	1		*BOOTLID 3 EMBLEM	Not Necessary	74.40 F	*- FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	225.00 F	*225.00 FL
7	1		*BOOTLID INNER LOCK	Not Necessary	271.00 F	*- FL
8	2		*BOOTLID REFLECTORS	Not Necessary	970.00 F	*- FL
9	2		*BOOTLID HINGES	Not Necessary	242.00 F	*- FL
10	1		*TAILLAMPS	O/S Cracked	2,100.00 F	*915.00 FL
11	2		*TAILLAMP GASKETS	Necessary	56.00 F	*41.80 FL
12	1		*REAR BUMPER	Dented / Deformed	1,074.00 F	*1,074.00 FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	300.00 F	*- FL
14	2		*REAR BUMPER TOWING COVERS	Missing	90.00 F	*90.00 FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	133.00 F	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Dented	741.00 F	*537.30 FL
18	1		*SET REAR BUMPER ULTRASONIC SENSORS	Shorted	740.00 FS	*200.00 FS
19	1		*REAR END PANEL	Dented	625.00 F	*505.10 FL
20	1		*REAR END PANEL TOP GARNISH	Twisted	288.00 F	*288.00 FL
21	2		*REAR FENDER INNER TRIMS	Not Necessary	770.00 F	*- FL
22	1		*REAR EXHAUST	Not Necessary	1,024.00 F	*- FL
23	2		*REAR EXHAUST MOUNTING	Not Necessary	130.00 F	*- FL
24	1		*REAR END PANEL SEALANT	Necessary	60.00 F	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,445.00	3,996.20
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	759.24
Total Parts (\$\$)	11,445.00	3,236.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	120.00	0.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	120.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
7	TO SPRAY RUST PROOFING	New	100.00	40.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	980.00
Gross Labour Cost (\$)			4,030.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >