

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20001173/QGA3Q2

**Date:** 04/05/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SJB5562H	<b>Insured Vehicle No :</b>	SHB6232C
Date of Loss: 13/01/2020	Nature of Claim: TP	Claim No: MCT20010298

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJB5562H</b>	Engine No:	1NZX678186
Make & Model:	TOYOTA VIOS, 1.5 J (A)	Chassis No:	MR053HY9305044349
Reg. Date:	16/01/2008 (Man. Year: 2007)	Odometer:	134469 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Kinforest 5 mm	Rear Left Side:	Kinforest 5 mm
Front Right Side:	Kinforest 5 mm	Rear Right Side:	Kinforest 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,990.00	777.50	1,212.50	60.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	690.00	720.00	51.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,400.00</b>	<b>1,467.50</b>	<b>1,932.50</b>	<b>56.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>(S\$)</b>	3,400.00	1,150.00	2,250.00	66.18
<b>+ GST 7.00/7.00% (S\$)</b>	238.00	80.50	157.50	66.18
<b>Nett Amount (S\$)</b>	<b>3,638.00</b>	<b>1,230.50</b>	<b>2,407.50</b>	<b>66.18</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>Nett Liability (S\$)</b>		<b>1,380.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,380.00</b>		

### INSPECTION

Date of Assignment:	20/01/2020	
Date Inspected:	20/01/2020 Inspected At:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18 Singapore 757700
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** OI SUN PIN**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 J (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJB5562H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	580.00 F	*580.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	40.00 F	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	40.00 F	*- FL
5	1		*REAR BUMPER LOWER SIDE RETAINER RH	Serviceable	40.00 F	*- FL
6	1		*REAR BUMPER LOWER SIDE RETAINER LH	Serviceable	40.00 F	*- FL
7	1		*REAR BUMPER SEAL BRACKET RH	Serviceable	40.00 F	*- FL
8	1		*REAR BUMPER SEAL BRACKET LH	Serviceable	40.00 F	*- FL
9	1		*REAR BUMPER SIDE EXTENSION LH	Crumpled	60.00 F	*60.00 FL
10	1		*REAR REINFORCEMENT BRACKET RH	Serviceable	70.00 F	*- FL
11	1		*REAR REINFORCEMENT BRACKET LH	Serviceable	70.00 F	*- FL
12	1		*REAR BUMPER REFLECTOR LH	Crumpled	100.00 F	*100.00 FL
13	1		*REAR END PANEL GARNISH	Serviceable	220.00 F	*- FL
14	1		*END PANEL	Serviceable	400.00 F	*- FL
15	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,990.00</b>	<b>970.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	192.50
<b>Total Parts (\$\$)</b>	<b>1,990.00</b>	<b>777.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	SPRAY PAINTING REAR BUMPER ,REAR FENDER LH AND INNER PANEL	New	600.00	300.00
2	REPAIR AND REPLACE AFFECTED ACCIDENT PARTS	New	600.00	300.00
3	APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL	New	100.00	30.00
4	REMOVE AND REPLACE REAR REVERSE SENSOR	New	80.00	30.00
5	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,410.00</b>	<b>690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >