

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20001189/UGS3Q2

Date: 28/07/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00014514

Claimant
Vehicle No : SKA9159G **Insured Vehicle No :** SME5632M

Date of Loss: 18/01/2020 Nature of Claim: TP Claim No: 1202000003213

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA9159G		
Make & Model:	MERCEDES-BENZ C200, 1.8 CGI (A)	Engine No:	27186030194183
Reg. Date:	13/04/2011 (Man. Year: 2010)	Chassis No:	WDD2040482A504845
Colour:	Grey	Odometer:	86328 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,073.30	5,740.96	8,332.34	59.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,770.00	1,630.00	47.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,473.30	7,510.96	9,962.34	57.01
Approved Total (Overridden) (\$\$)		6,000.00		
Nett Amount (\$\$)	17,473.30	6,000.00	11,473.30	65.66
+ Car Rental (5.0 x S\$160.50/day) (\$\$)		802.50		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		6,838.95		
Global Sum Settlement (\$\$)		6,800.00		

INSPECTION

Date of Assignment: 20/01/2020

Date Inspected: 20/01/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
130 Bedok Reservoir Road, Eunos
Spring, #08-1339
Singapore 470130

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2020)
Parts:	143	MERCEDES-BENZ C200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA9159G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Badly Dented	2,200.00 FL	*1,675.12 FL
2	2		*REAR BOOT HINGES	Not Necessary	270.00 FL	*- FL
3	1		*REAR BOOT INNER TRIM	Not fitted	385.00 FL	*- FL
4	1		*REAR BOOT INNER LOCK	Twisted	295.00 FL	*295.00 FL
5	1		*REAR BOOT LOGO	Necessary	58.00 FL	*58.00 FL
6	1		*REAR BOOT WEATHERSTRIP	Twisted	185.00 FL	*185.00 FL
7	1		*REAR BOOT CGI EMBLEM	Necessary	58.00 FL	*58.00 FL
8	1		*REAR BOOT C200 EMBLEM	Necessary	62.00 FL	*62.00 FL
9	1		*REAR BOOT C&C EMBLEM	Necessary	68.00 FL	*68.00 FL
10	1		*REAR TAILLAMPS	O/S Cracked	1,670.00 FL	*635.10 FL
11	2		*REAR TAILLAMP SIDE GARNISHES	Not Necessary	250.00 FL	*- FL
12	1		*REAR END PANEL	Repair	1,248.00 FL	*- FL
13	1		*REAR END PANEL INNER GARNISH	Serviceable	165.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	1,885.00 FL	*1,461.32 FL
15	2		*REAR BUMPER BRACKETS	Cracked	172.00 FL	*172.00 FL
16	1		*SET REAR BUMPER CLIP	Necessary	80.00 FL	*50.00 FL
17	1		*REAR BUMPER INNER SPONGE	No such part	162.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	817.00 FL	*615.00 FL
19	2		*REAR BUMPER STAYS	Not Necessary	136.00 FL	*- FL
20	2		*REAR BUMPER SIDE RETAINERS	Cracked	170.00 FL	*170.00 FL
21	4		*REAR BUMPER PDC SENSORS	Shorted	1,540.00 FL	*470.00 FL
22	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.00 FL	*- FL
23	1		*REAR BUMPER CENTRE CHROME MOULDING	Necessary	325.00 FL	*168.30 FL
24	2		*REAR BUMPER SIDE CHROME MOULDINGS	Necessary	392.00 FL	*236.00 FL
25	1		*REAR BUMPER INNER FRAME PAD	Not Necessary	285.00 FL	*- FL
26	1		*CONTROL MODULE FOR PARK ASSISTANK KIT	No such part	345.00 FL	*- FL
27	1		*REAR FLOOR BOARD	Not Necessary	310.00 FL	*- FL
28	1		*REAR EXHAUST SILENCER	Not Necessary	1,655.00 FL	*- FL
29	2		*REAR EXHAUST MOUNTINGS	Not Necessary	136.00 FL	*- FL
30	1		*REAR EXHAUST CHROME TAIL PIPE	Serviceable	285.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	15,637.00	6,378.84
- List Item Discount on L Items 10.00/10.00% (S\$)	1,563.70	637.88
Total Parts (S\$)	14,073.30	5,740.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
6	TO APPLY UNDERCOATING	New	150.00	50.00
7	PANEL BEATING	New	1,400.00	700.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,400.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >