

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20001206/QES3Q2  
**Date:** 10/09/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800079322
<b>Claimant</b>		
<b>Vehicle No :</b> SLL1193P	<b>Insured Vehicle No :</b>	SMC5266Y
Date of Loss: 18/01/2020	Nature of Claim: TP	Claim No: 8922210206SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLL1193P</b>	
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No: 3A92UDN8987
Reg. Date:	14/02/2017 (Man. Year: 2016)	Chassis No: MMBSTA13AHH003525
Colour:	Blue	Odometer: 235928 km
Engine Capacity:	1193 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,169.60	1,632.00	537.60	24.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,350.00	550.00	28.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,069.60</b>	<b>2,982.00</b>	<b>1,087.60</b>	<b>26.72</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>284.87</b>	<b>208.74</b>	<b>76.13</b>	<b>26.72</b>
<b>Nett Amount (S\$)</b>	<b>4,354.47</b>	<b>3,190.74</b>	<b>1,163.73</b>	<b>26.72</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,442.74</b>		

#### INSPECTION

Date of Assignment:	20/01/2020	
Date Inspected:	20/01/2020 Inspected At:	Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-01 Carros Centre Singapore 737869
Estimated Period of Repair:	4.0 days	

**Adjuster:** OI SUN PIN

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*F/R DOOR	Dented	1,400.00 FL	*986.00 FL	
2	1		*F/R FENDER	Dented	532.00 FL	*400.00 FL	
3	1		*F/R HEADLAMP ASSY	Scratched	780.00 FL	*654.00 FL	
					<b>Sub Total (\$)</b>	<b>2,712.00</b>	<b>2,040.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	542.40	408.00
					<b>Total Parts (\$)</b>	<b>2,169.60</b>	<b>1,632.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR REMOVING OUT R/R DOOR OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	900.00	600.00
2	TO RESPRAY F/R DOOR ,F/R FENDER AND FRONT BUMPER ,RIM SPRAY	New	1,000.00	750.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >