

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001207/AES3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900141213

Claimant
Vehicle No : SBA3113J **Insured Vehicle No :** SGK671Y

Date of Loss: 16/01/2020 **Nature of Claim:** TP **Claim No:** 7474823852SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBA3113J	Engine No:	CHZC27505
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA1KA040615
Reg. Date:	26/03/2019 (Man. Year: 2019)	Odometer:	16428 km
Colour:	Yellow		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,723.00	1,356.40	1,366.60	50.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,672.00	1,522.00	1,150.00	43.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,395.00	2,878.40	2,516.60	46.65
+ GST 7.00/7.00% (\$\$)	377.65	201.49	176.16	46.65
Nett Amount (\$\$)	5,772.65	3,079.89	2,692.76	46.65
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,261.89		

INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 21/01/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,108.00 FS	*886.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	73.00 FS	*- FS
3	1		*REAR BUMPER SPOILER -LH	Deformed	268.00 FS	*214.00 FS
4	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	41.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	56.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	517.00 FS	*- FS
7	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	24.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	102.00 FS	*- FS
9	2		*REAR PARKING AIR SENSOR -INNER (NPA)	Not Necessary	0.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
11	2		*REAR WHEEL COVER -LH/RH	Necessary	320.00 FS	*256.00 FS
12	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 2,723.00 1,356.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,672.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >