

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



## PREMIER APPRAISER SERVICES

Insurance Loss Adjusters and Qualified Appraisers

16 Sin Ming Walk, #03-02 Singapore 575568

Tel: 6554-2269 Fax: 6685-1399

Regn. No: 52864369W

Our Ref : PT1911001-L

Date : 19th Nov 2019

Mr. Lee Kah Jing  
c/o Blk 9002 Tampines Street 93  
#01-74 Tampines Ind Park A  
Singapore 528836

**WITHOUT PREJUDICE**

Dear Sir,

**Re: Third Party Claim / Workshop :- Chip Soon Auto Supply Pte Ltd**  
**Vehicle Regn. No. : SLU 5339 M**

We refer to your instruction to appraise the above-mentioned vehicle on 04th Nov 2019 .

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by the repairer for **SS 20,359.00** as per our attached schedule have been scrutinized and revised by us against the actual damages found on the vehicle and we recommend the replacements and rectification accordingly.

The repairer has agreed to undertake the repairs at our adjusted amount of **SS 9,950.00 lump sum** corresponding to supply of parts, labour charges and spraypainting. However, we have not given instruction to authorize.

Under normal circumstances the estimated period of repairs is **SEVEN ( 7 ) days**. The estimated period of repairs given above is based on **Working Day (s)** only.


Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are leaving the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services always.

Very truly yours  
**PREMIER APPRAISER SERVICES**

  
**LESLIE K C LIM CAE (UK), MIMI (UK)**  
MSAAA, Automotive Appraiser  
Dip. MTM, Automotive Engineer

## PREMIER APPRAISER SERVICES

Insurance Loss Adjusters and Qualified Appraisers

16 Sin Ming Walk, #03-02 Singapore 575568

Tel: 6554-2269 Fax: 6685-1399

Regn. No: 52864369W

Our Ref : PT1911001-L

Date : 19th Nov 2019

Mr. Lee Kah Jing  
c/o Blk 9002 Tampines Street 93  
#01-74 Tampines Ind Park A  
Singapore 528836

**WITHOUT PREJUDICE**

Dear Sir,

**Re: Third Party Claim / Workshop :- Chip Soon Auto Supply Pte Ltd**  
**Vehicle Regn. No. : SLU 5339 M**

We refer to your instruction to appraise the above-mentioned vehicle on 04th Nov 2019 .

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by the repairer for **S\$ 20,359.00** as per our attached schedule have been scrutinized and revised by us against the actual damages found on the vehicle and we recommend the replacements and rectification accordingly.

The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 9,950.00 lump sum** corresponding to supply of parts, labour charges and spraypainting. However, we have not given instruction to authorize.

Under normal circumstances the estimated period of repairs is **SEVEN ( 7 ) days**.  
The estimated period of repairs given above is based on **Working Day (s)** only.

Photographs of the damaged vehicle taken by us during our inspection are enclosed.


We are leaving the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services always.

Very truly yours

**PREMIER APPRAISER SERVICES**

  
**LESLIE K C LIM CAE (UK), MIMI (UK)**  
MSAAA, Automotive Appraiser  
Dip.MTM, Automotive Engineer

# PREMIER APPRAISER SERVICES

## VEHICLE INSPECTION REPORT

To: Mr. Lee Kah Jing  
c/o Blk 9002 Tampines Street 93  
#01-74 Tampines Ind Park A  
Singapore 528836

Our Ref. : PT1911001-L  
Policy No. : -  
Claim No. : -  
Sum Insured : -  
Type of Claims : T/P Claim  
Date : 19th Nov 2019

Assigned By : Mr. Lee Kah Jing  
Date of Assignment : 04th Nov 2019  
Date of Accident : 03rd Nov 2019  
Date of Inspection : 04th Nov 2019 Follow up inspections were also conducted.  
Name of Workshop : Chip Soon Auto Supply Pte Ltd  
Place of Inspection : Blk 9002 Tampines Street 93 #01-74  
Singapore 528836

### PARTICULARS OF VEHICLE

Registration No.	: SLU 5339 M	Odometer/km	: 132552
Make/Model	: Mercedes Benz E250 CGI	Chassis No.	: WDD2074472F051785
Type Of Body	: 2 Door Cabriolet/ Convertible	Engine No.	: 27186030071545
Year of Manuf./Regn.	: 2010	Engine Cap.	: 1796 cc
Colour	: Black	Carrying Cap.	: 3 Passengers

### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good	Market Value	: -
Footbrake	: Serviceable	Paint Work	: Good	Salvage Value	: -
Steering	: Serviceable	Modifications	: None	CTL (Loss)	: -

### CONDITION OF TYRES

	Size	N/s - Tread Depth/Make	O/s - Tread Depth/Make
Front Tread	: 235/35 - ZR19	5mm - Pirelli	5mm - Pirelli
Rear Tread (inner)	:		
Rear Tread (outer)	: 265/30 - ZR19	6mm - Pirelli	6mm - Pirelli

The above represent an estimated remaining life of the tyre treads in mm.

### POINT OF IMPACT/GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained an impact on the rear portion.

The boot lid, rear end panel, rear bumper, bumper reinforcement were dented/ chafed/ damaged.

For details of damages please refer to our schedule attached.

### REMARKS :

This survey was conducted strictly without prejudice.



# PREMIER APPRAISER SERVICES

Our Ref : PT1911001-L

Vehicle No : SLU 5339 M

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
NETT ITEMS:				
1	boot lid	dented - repair	S\$ 2,170.00	S\$ -
1	boot lid inner trim	serviceable	584.00	-
1	boot lid weatherstrip	damaged	245.00	245.00
1	boot lid lock	stiffened	386.00	386.00
1	boot lid lock garnish	chafed	258.00	258.00
1	boot lid lock striler	serviceable	78.50	-
1	boot lid remote sensor	serviceable	374.10	-
1	boot lid outer chromed mldg	serviceable	369.00	-
1	boot lid number plate garnish	chafed/distorted	354.00	354.00
1	boot lid badge	damaged	84.60	84.60
1	boot lid " E250 " emblem	damaged	87.00	87.00
1	boot lid " CGI " emblem	damaged	86.60	86.60
1	boot lid o/s lamp	chafed	651.00	651.00
1	o/s tail lamp	serviceable	775.00	-
1	o/s tail lamp side garnish	chafed	189.00	189.00
1	o/s tail lamp bracket	serviceable	87.00	-
1	rear end panel	dented - repair	1,452.00	-
1	rear end panel top garnish	serviceable	186.00	-
1	rear bumper	chafed/distorted	1,910.00	1,910.00
1	rear bumper lower diffuser	chafed/distorted	845.00	845.00
1	rear bumper chromed mldg - ctr	damaged	193.20	193.20
1	rear bumper chromed mldg - n/s	damaged	143.40	143.40
1	rear bumper chromed mldg - o/s	damaged	143.40	143.40
1	rear bumper tow cover	chafed	79.00	79.00
1	rear bumper reinforcement	dented/bent	878.00	878.00
1	rear bumper centre bracket (plastic)	damaged	254.00	254.00
2	rear bumper side brackets (plastic)	damaged	256.00	256.00
2	rear bumper lower side brackets	damaged	220.00	220.00
4	rear bumper reverse/parking sensors	damaged	1,424.00	1,424.00
4	rear bumper sensor holders	damaged	224.00	224.00
1	rear bumper sensor wire harness	damaged	1,426.00	1,426.00
			S\$ 16,412.80	S\$ 10,337.20
LESS 0%			-	5%
			16,412.80	9,820.34
S/NETT ITEMS:				
1	boot lid sealant	not required	60.00	-
12	boot lid inner trim clips	necessary	78.00	78.00
4	tail lamp clips	necessary	27.20	27.20
4	rear end panel top garnish clips	necessary	26.00	26.00
1	rear end panel joint sealant	not required	60.00	-
10	rear bumper clips	necessary	65.00	65.00
1	rear number plate w casing	serviceable	60.00	-
1	reverse camera	serviceable	450.00	-
TOTAL S/PARTS			S\$ 17,239.00	S\$ 10,016.54
To remove/refit luggage trims and garnish to facilitate repairs.			120.00	80.00

# PREMIER APPRAISER SERVICES


Our Ref : PT1911001-L

Vehicle No : SLU 5339 M

	Repairer's Est.	Our Revised
Balance b/f	S\$ 17,239.00	S\$ 10,016.54
Labour charges to repair, panel beat and straighten damaged parts and replace the above-mentioned parts.	1,200.00	1,000.00
To transfer boot lid fittings.	90.00	-
To replace parking sensors.	100.00	- 60.00
To replace reverse camera.	100.00	- -
To check wiring functions.	80.00	50.00
To carry out on board diagnostic check, clear and reset fault codes.	250.00	220.00
To putty, apply primer & spray-paint the affected areas.	1,200.00	1,050.00
To apply rust-proofing on repaired/replaced panels.	100.00	70.00
<b>TOTAL</b>	<b>S\$ <u>20,359.00</u></b>	<b>S\$ <u>12,466.54</u></b>

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 9,950.00 lump sum** corresponding to supply of parts, labour and spray painting charges.  
The estimated period of repairs is **SEVEN ( 7 )** days.  
Pursuant to your instruction we have **not** authorised repairs on your behalf.

PREMIER APPRAISER SERVICES

  
LESLIE K C LIM CAE (UK), MIMI (UK)  
MSAAA, Automotive Appraiser  
10p.MTM. Automotive Engineer

# PREMIER APPRAISER SERVICES

## VEHICLE INSPECTION REPORT

To : Mr. Lee Kah Jing  
c/o Blk 9002 Tampines Street 93  
#01-74 Tampines Ind Park A  
Singapore 528836

Our Ref. : PT1911001-L  
Policy No. : -  
Claim No. : -  
Sum Insured : -  
Type of Claims : T/P Claim  
Date : 19th Nov 2019

Assigned By : Mr. Lee Kah Jing  
Date of Assignment : 04th Nov 2019  
Date of Accident : 03rd Nov 2019  
Date of Inspection : 04th Nov 2019 Follow up inspections were also conducted.  
Name of Workshop : Chip Soon Auto Supply Pte Ltd  
Place of Inspection : Blk 9002 Tampines Street 93 #01-74  
Singapore 528836

### PARTICULARS OF VEHICLE

Registration No.	: SLU 5339 M	Odometer/km	: 132552
Make/Model	: Mercedes Benz E250 CGI	Chassis No.	: WDD2074472F051785
Type Of Body	: 2 Door Cabriolet/ Convertible	Engine No.	: 27186030071545
Year of Manuf./Regn.	: 2010	Engine Cap.	: 1796 cc
Colour	: Black	Carrying Cap.	: 3 Passengers

### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good	Market Value	: -
Footbrake	: Serviceable	Paint Work	: Good	Salvage Value	: -
Steering	: Serviceable	Modifications	: None	CTL (Loss)	: -

### CONDITION OF TYRES

	Size	N/s - Tread Depth/Make	O/s - Tread Depth/Make
Front Tread	: 235/35 - ZR19	5mm - Pirelli	5mm - Pirelli
Rear Tread (inner)	:		
Rear Tread (outer)	: 265/30 - ZR19	6mm - Pirelli	6mm - Pirelli

*The above represent an estimated remaining life of the tyre treads in mm.*

### POINT OF IMPACT/GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained an impact on the rear portion.

The boot lid, rear end panel, rear bumper, bumper reinforcement were dented/ chafed/ damaged.

For details of damages please refer to our schedule attached.

### REMARKS :

This survey was conducted strictly without prejudice.

# PREMIER APPRAISER SERVICES

Our Ref: PT1911001-L

Vehicle No: SLU 5339 M

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
NETT ITEMS:				
1	boot lid X (R)	dented - repair	S\$ 2,170.00	S\$ -
1	boot lid inner trim X (SVC)	serviceable	584.00	-
1	boot lid weatherstrip X (SVC)	damaged	245.00	245.00
1	boot lid lock X (SVC)	stiffened	386.00	386.00
1	boot lid lock garnish X (SVC)	chafed	258.00	258.00
1	boot lid lock striler X (SVC)	serviceable	78.50	-
1	boot lid remote sensor X (SVC)	serviceable	374.10	-
1	boot lid outer chromed mldg X (SVC)	serviceable	369.00	-
1	boot lid number plate garnish X (R)	chafed/distorted	354.00	354.00
1	boot lid badge ✓ nice	damaged	84.60	84.60 64.80 ✓
1	boot lid "E250" emblem ✓ nice	damaged	87.00	87.00 48.80 ✓
1	boot lid "CGI" emblem ✓ nice	damaged	86.60	86.60 45.80 ✓
1	boot lid o/s lamp X (SVC)	chafed	651.00	651.00
1	o/s tail lamp X (SVC)	serviceable	775.00	-
1	o/s tail lamp side garnish X (SVC)	chafed	189.00	189.00
1	o/s tail lamp bracket X (SVC)	serviceable	87.00	-
1	rear end panel X (R)	dented - repair	1,452.00	-
1	rear end panel top garnish X (SVC)	serviceable	186.00	-
1	rear bumper ✓ BR	chafed/distorted	1,910.00	1,910.00/377.50 ✓
1	rear bumper lower diffuser ✓ SVC	chafed/distorted	845.00	845.00 580.80 ✓
1	rear bumper chromed mldg - ctr ✓ nice	damaged	193.20	193.20 97.80 ✓
1	rear bumper chromed mldg - n/s ✓ nice	damaged	143.40	143.40 97.80 ✓
1	rear bumper chromed mldg - o/s ✓ nice	damaged	143.40	143.40 17.80 ✓
1	rear bumper tow cover X (SVC)	chafed	79.00	79.00
1	rear bumper reinforcement ✓ B+T	dented/bent	878.00	878.00 680.30 ✓
1	rear bumper centre bracket (plastic) ✓ nice	damaged	254.00	254.00/24.80 ✓
2	rear bumper side brackets (plastic) X (SVC)	damaged	256.00	256.00
2	rear bumper lower side brackets X (SVC)	damaged	220.00	220.00
2	rear bumper reverse/parking sensors ✓ nice	damaged	1,424.00	1,424.00 500 ✓
4	rear bumper sensor holders ✓ nice	damaged	224.00	224.00 100 ✓
1	rear bumper sensor wire harness X (SVC)	damaged	1,426.00	1,426.00
			S\$ 16,412.80	S\$ 10,337.20
LESS 0%			-	516.86
			16,412.80	9,820.34

## S/NETT ITEMS:

1	boot lid sealant X NN	not required	60.00	-
12	boot lid inner trim clips ✓ nice	necessary	78.00	78.00 20 ✓
4	tail lamp clips X (SVC)	necessary	27.20	27.20
4	rear end panel top garnish clips ✓ nice	necessary	26.00	26.00 10 ✓
1	rear end panel joint sealant X (SVC)	not required	60.00	-
10	rear bumper clips ✓ nice	necessary	65.00	65.00 30 ✓
1	rear number plate w casing X (SVC)	serviceable	60.00	-
1	reverse camera X (SVC)	serviceable	450.00	-
TOTAL S/PARTS			S\$ 17,239.00	S\$ 10,016.54

To remove/refit luggage trims and garnish to facilitate repairs.

120.00

80.00

# PREMIER APPRAISER SERVICES

Our Ref: PT1911001-L

Vehicle No: SLU 5339 M

	Repairer's Est.	Our Revised
Balance b/f	S\$ 17,239.00	S\$ 10,016.54
Labour charges to repair, panel beat and straighten damaged parts and replace the above-mentioned parts. ✓	1,200.00	1,000.00 600 ✓
To transfer boot lid fittings. X	90.00	-
To replace parking sensors. ✓	100.00	60.00 30 ✓
To replace reverse camera. X	100.00	-
To check wiring functions. ✓	80.00	50.00 30 ✓
To carry out on board diagnostic check, clear and reset fault codes. ✓	250.00	220.00 150 ✓
To putty, apply primer & spray-paint the affected areas. ✓	1,200.00	1,050.00 600 ✓
To apply rust-proofing on repaired/replaced panels. ✓	100.00	70.00 20 ✓
<b>TOTAL</b>	<b>S\$ 20,359.00</b>	<b>S\$ 12,466.54</b>

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 9,950.00** lump sum corresponding to supply of parts, labour and spray painting charges.  
The estimated period of repairs is **SEVEN (7) days**. Pursuant to your instruction we have **not** authorised repairs on your behalf.

parts	3816.20
parts less	10%
	3434.58
spray	60
labour	1430
	4924.58
L/s less	20%
	3939.66
Total	↓
L/s A* →	\$ 3950 A

Paper survey  
marked on 5/2/20  
11.00 AM  
without pre-approval  
L/s spray  
Rough after paint  
11. AM  
4 day

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**PREMIER APPRAISER SERVICES**

**LESLIE K C LIM CAE (UK), MIMI (UK)**  
**MSAAA, Automotive Appraiser**  
**15p.MTM. Automotive Engineer**

Acknowledged by Repairer

Signature:


Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS3/FWD19019549/Hvd3s2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986			Date : 06-02-2020	
			Code : FWD	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGS 3703C	Veh. Inspected	SLU 5339M	
Policy No.	PNPV2018-00000958-01	Coverage (\$)	0.00	
Claim No.	1201900040944	Excess (\$)	0.00	
Assign From	EILEEN BAY	Assign Date	20/01/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ E250 CGI	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2074472F051785	Colour	BLACK	
Odometer	132552	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/35 R19	PIRELLI	5 mm	
L/H Front Tyre	235/35 R19	PIRELLI	5 mm	
R/H Rear Tyre	265/30 R19	PIRELLI	5 mm	
L/H Rear Tyre	265/30 R19	PIRELLI	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/11/2019	Inspection Date	05/11/2019	
Survey held at	CHIP SOON AUTO SUPPLY CO. BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5339M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BOOT LID (N)	TO REPAIR SEE LABOUR	2,170.00	-
1	BOOT LID INNER TRIM (N)	SERVICEABLE	584.00	-
1	BOOT LID WEATHERSTRIP (N)	SERVICEABLE	245.00	-
1	BOOT LID LOCK (N)	SERVICEABLE	386.00	-
1	BOOT LID LOCK GARNISH (N)	SERVICEABLE	258.00	-
1	BOOT LID LOCK STRIKER (N)	SERVICEABLE	78.50	-
1	BOOT LID REMOTE SENSOR (N)	SERVICEABLE	374.10	-
1	BOOT LID OUTER CHROMED MLDG (N)	SERVICEABLE	369.00	-
1	BOOT LID NUMBER PLATE GARNISH (N)	TO REPAIR SEE LABOUR	354.00	-
1	BOOT LID BADGE (N)	NECESSARY	84.60	64.80
1	BOOT LID "E250" EMBLEM (N)	NECESSARY	87.00	48.80
1	BOOT LID "CGI" EMBLEM (N)	NECESSARY	86.60	45.80
1	BOOT LID O/S LAMP (N)	SERVICEABLE	651.00	-
1	O/S TAIL LAMP (N)	SERVICEABLE	775.00	-
1	O/S TAIL LAMP SIDE GARNISH (N)	SERVICEABLE	189.00	-
1	O/S TAIL LAMP BRACKET (N)	SERVICEABLE	87.00	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	1,452.00	-
1	REAR END PANEL TOP GARNISH (N)	SERVICEABLE	186.00	-
1	REAR BUMPER (N)	BROKEN	1,910.00	1,377.50
1	REAR BUMPER LOWER DIFFUSER (N)	SCRATCHED	845.00	580.80
1	REAR BUMPER CHROMED MLDG - CTR (N)	NECESSARY	193.20	97.80
1	REAR BUMPER CHROMED MLDG - N/S (N)	NECESSARY	143.40	97.80
1	REAR BUMPER CHROMED MLDG - O/S (N)	NECESSARY	143.40	97.80
1	REAR BUMPER TOW COVER (N)	SERVICEABLE	79.00	-
1	REAR BUMPER REINFORCEMENT (N)	BENT	878.00	680.30
1	REAR BUMPER CENTRE BRACKET (PLASTIC) (N)	CRUSHED	254.00	124.80
2	REAR BUMPER SIDE BRACKETS (PLASTIC) (N)	SERVICEABLE	256.00	-
2	REAR BUMPER LOWER SIDE BRACKETS (N)	SERVICEABLE	220.00	-

Report Ref No. CS3/FWD19019549/Hvd3s2-1





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR BUMPER REVERSE / PARKING SENSORS (N)	SHORTED 2PCS ONLY	1,424.00	500.00
4	REAR BUMPER SENSOR HOLDERS (N)	NECESSARY	224.00	100.00
1	REAR BUMPER SENSOR WIRE HARNESS (N)	SERVICEABLE	1,426.00	-
	LESS 10% DISCOUNT		-	-381.62
			16,412.80	3,434.58
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BOOT LID SEALANT (SN)	NOT NECESSARY	60.00	-
12	BOOT LID INNER TRIM CLIPS (SN)	NECESSARY 8PCS ONLY	78.00	20.00
4	TAIL LAMP CLIPS (SN)	SERVICEABLE	27.20	-
4	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	26.00	10.00
1	REAR END PANEL JOINT SEALANT (SN)	SERVICEABLE	60.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	65.00	30.00
1	REAR NUMBER PLATE W CASING (SN)	SERVICEABLE	60.00	-
1	REVERSE CAMERA (SN)	SERVICEABLE	450.00	-
			826.20	60.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE-MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID, BOOT LID NUMBER PLATE GARNISH AND REAR END PANEL.		1,200.00	600.00
	TO TRANSFER BOOT LID FITTINGS.	NOT NECESSARY	90.00	-
	TO REPLACE PARKING SENSORS.		100.00	30.00
	TO REPLACE REVERSE CAMERA.	NOT NECESSARY	100.00	-
	TO CHECK WIRING FUNCTIONS.		80.00	30.00
	TO CARRY OUT ON BOARD DIAGNOSTIC CHECK, CLEAR AND RESET FAULT CODES.		250.00	150.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		1,200.00	600.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.		100.00	20.00
			3,120.00	1,430.00
	<b>GRAND TOTAL</b>		<b>20,359.00</b>	<b>4,924.58</b>





RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,950.00
---	--	--	----------

Report Ref No. CS3/FWD19019549/Hvd3s2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.