

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120**Our File No:** CC3/AIG20001247/AVF3E2**Date:** 30/04/2020REFERENCE

Insured/Claimant: M/S PINN BROKERAGE PTE LTD

Policy No:

Date of Loss: 10/01/2020

Nature of Claim: OD Claim No: 8285104584SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKA9788R**

Make & Model: AUDI Q7, 2.0 TFSI QU (A)

Engine No: CYR046187

Reg. Date: 12/12/2017 (Man. Year: 2017)

Chassis No: WAUZZZ4M3JD002167

Colour: Bronze

Odometer: 57055 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$200,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R19

Rear Tyre Size: 255/55 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,507.00	5,629.20	14,877.80	72.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,922.00	2,272.00	4,650.00	67.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,429.00	7,901.20	19,527.80	71.19
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	26,429.00	6,901.20	19,527.80	73.89
+ GST 7.00/7.00% (S\$)	1,850.03	483.08	1,366.95	73.89
Nett Amount (S\$)	28,279.03	7,384.28	20,894.75	73.89

INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 21/01/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,317.00 FS	*1,853.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	420.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	63.00 FS	*- FS
4	1		*FRONT BUMPER END CAP - LH	Not Necessary	34.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	261.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Deformed	194.00 FS	*154.80 FS
7	1		*FRONT BUMPER UNDERRUN BAR	Deformed	759.00 FS	*607.20 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	198.00 FS	*- FS
9	1		*FRONT SPOILER - LH	Repair	199.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER - LH OUTER	Repair	41.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	2,327.00 FS	*1,861.60 FS
12	1		*RADIATOR GRILLE COVER	Not Necessary	65.00 FS	*- FS
13	1		*RADIATOR GRILLE INNER COVER	Not Necessary	58.00 FS	*- FS
14	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	280.00 FS	*224.00 FS
15	1		*FRONT BUMPER END CAP - LH	Not Necessary	31.00 FS	*- FS
16	1		*FRONT DEFLECTOR - LH INNER	Not Necessary	56.00 FS	*- FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	161.00 FS	*- FS
18	1		*FRONT BUMPER CARRIER	Not Necessary	817.00 FS	*- FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	68.00 FS	*- FS
20	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
21	1		*SIGHT SHIELD	Not Necessary	123.00 FS	*- FS
22	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
23	1		*HORN BRACKET - LH LOW TONE	Not Necessary	213.00 FS	*- FS
24	3		*FRONT PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
25	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
26	1		*HEADLIGHT MOUNTING - LH	Not Necessary	112.00 FS	*- FS
27	1		*LED HEADLIGHT - LH	Not Necessary	9,356.00 FS	*- FS
28	2		*LIFT CYLINDER - LH / RH	Not Necessary	374.00 FS	*- FS
29	1		*HEADLIGHT HOSE	Not Necessary	92.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE - LH OUTER	Not Necessary	43.00 FS	*- FS
31	1		*ADDITIONAL RADIATOR BRACKET	Not Necessary	123.00 FS	*- FS
32	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	54.00 FS	*- FS
33	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	80.00 FS	*- FS
34	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,080.00 FS	*863.20 FS
35	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
36	1		*SUNDRIES	Necessary	400.00 FS	*24.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **20,507.00** **5,629.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, FRONT BUMPER SPOILER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,250.00	600.00
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	1,000.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,922.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >