

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20001253/ASD3E2

Date: 13/08/2020

REFERENCE

Insured/Claimant:	CHOO WENG TANG KEITH	Policy No:	1900260525
Date of Loss:	18/01/2020	Nature of Claim:	OD Claim No: 2090339314SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR2173Y	Engine No:	CVK086728
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF40KA108608
Reg. Date:	24/12/2019 (Man. Year: 2019)	Odometer:	913 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,949.00	1,043.20	4,905.80	82.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,622.00	1,722.00	900.00	34.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,571.00	2,765.20	5,805.80	67.74
- Excess (S\$)	100.00	100.00	0.00	0.00
(S\$)	8,471.00	2,665.20	5,805.80	68.54
+ GST 7.00/7.00% (S\$)	592.97	186.56	406.41	68.54
Nett Amount (S\$)	9,063.97	2,851.76	6,212.21	68.54

INSPECTION

Date of Assignment:	21/01/2020		
Date Inspected:	21/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	2,068.00 FS	*- FS	
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS	
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	185.00 FS	*- FS	
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	198.00 FS	*- FS	
5	1		*RADIATOR GRILLE	Cracked	1,254.00 FS	*1,003.20 FS	
6	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	127.00 FS	*- FS	
7	1		*FRONT BUMPER CARRIER	Not Necessary	757.00 FS	*- FS	
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	117.00 FS	*- FS	
9	1		*FRONT BUMPER COVER	Not Necessary	120.00 FS	*- FS	
10	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS	
11	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS	
12	1		*LOCK CARRIER BRACKET - LH	Not Necessary	129.00 FS	*- FS	
13	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	54.00 FS	*- FS	
14	2		*FRONT PARKING AIR SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS	
15	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS	
16	1		*HORN - LH HIGH TONE	Not Necessary	38.00 FS	*- FS	
17	1		*RADIATOR AIR GUIDE - LH	Not Necessary	27.00 FS	*- FS	
18	1		*RADIATOR INNER DUCT - LH	Not Necessary	12.00 FS	*- FS	
19	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	15.00 FS	*- FS	
20	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	21.00 FS	*- FS	
21	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS	
22	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS	
					Total Parts (\$\$)	5,949.00	1,043.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			2,622.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >