

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2020 Edit Reg		20 Jan 2020 00:00 Edit Adj Rpt	S\$6,800.00 Edit Estimates	S\$6,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN AH KEONG , Co. Reg. No.: -									
Main Claimant: NG KAH HWEE CAROLINE									
Vehicle Reg. No.: SLR3315K		Date of Loss: 17/01/2020 13:00 - :59 [29 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6583665048SG		Policy/Cover Note No.: (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): SLD847K		Policy No. (Claimant):							
		Excess:							
Repairer: Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 31/01/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG_EXPRESS (02/07/2020): Alert - Adj Mandate Approved (S\$3612.00) - SLR3315K - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR3315K (6583665048SG)**
[SLD847K]

TP

NG KAH HWEE CAROLINE

Jan 17 2020 1:00PM

[TAN AH KEONG]

Sm Automotive - Kaki Bukit

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/05/20 22:40	Adjuster Immediate Advice		Load HTM	
2	21/05/20 22:55	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/03/20 16:13	General View		Load JPG	☒
2	06/03/20 16:13	General View		Load JPG	☒
3	06/03/20 16:13	General View		Load JPG	☒
4	06/03/20 16:13	General View		Load JPG	☒
5	06/03/20 16:13	General View		Load JPG	☒
6	06/03/20 16:13	General View		Load JPG	☒
7	06/03/20 16:13	General View		Load JPG	☒
8	06/03/20 16:13	General View		Load JPG	☒
9	06/03/20 16:13	General View		Load JPG	☒
10	06/03/20 16:13	General View		Load JPG	☒
11	06/03/20 16:13	General View		Load JPG	☒
12	06/03/20 16:13	General View		Load JPG	☒
13	06/03/20 16:13	General View		Load JPG	☒
14	06/03/20 16:13	General View		Load JPG	☒
15	06/03/20 16:13	General View		Load JPG	☒
16	06/03/20 16:13	General View		Load JPG	☒
17	06/03/20 16:13	General View		Load JPG	☒
18	06/03/20 16:13	General View		Load JPG	☒
19	06/03/20 16:13	General View		Load JPG	☒
20	06/03/20 16:13	General View		Load JPG	☒
21	06/03/20 16:14	Reinspection Photo		Load JPG	☒
22	06/03/20 16:14	Reinspection Photo		Load JPG	☒
23	06/03/20 16:14	Reinspection Photo		Load JPG	☒
24	06/03/20 16:14	Reinspection Photo		Load JPG	☒
25	06/03/20 16:14	Reinspection Photo		Load JPG	☒
26	06/03/20 16:14	Reinspection Photo		Load JPG	☒
27	06/03/20 16:14	Reinspection Photo		Load JPG	☒
28	06/03/20 16:14	Reinspection Photo		Load JPG	☒
29	06/03/20 16:14	Reinspection Photo		Load JPG	☒
30	06/03/20 16:14	Reinspection Photo		Load JPG	☒
31	06/03/20 16:14	Reinspection Photo		Load JPG	☒
32	06/03/20 16:14	Reinspection Photo		Load JPG	☒
33	06/03/20 16:14	Reinspection Photo		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
34	06/03/20 16:14	Reinspection Photo		Load JPG	☒
35	06/03/20 16:14	Reinspection Photo		Load JPG	☒
36	06/03/20 16:14	Reinspection Photo		Load JPG	☒
37	06/03/20 16:14	Reinspection Photo		Load JPG	☒
38	06/03/20 16:14	Reinspection Photo		Load JPG	☒
39	06/03/20 16:14	Reinspection Photo		Load JPG	☒
40	06/03/20 16:14	Reinspection Photo		Load JPG	☒
41	06/03/20 16:14	Reinspection Photo		Load JPG	☒
42	06/03/20 16:14	Reinspection Photo		Load JPG	☒
43	06/03/20 16:14	Reinspection Photo		Load JPG	☒
44	06/03/20 16:14	Reinspection Photo		Load JPG	☒
45	06/03/20 16:14	Reinspection Photo		Load JPG	☒
46	06/03/20 16:14	Reinspection Photo		Load JPG	☒
47	06/03/20 16:14	Reinspection Photo		Load JPG	☒
48	06/03/20 16:14	Reinspection Photo		Load JPG	☒
49	06/03/20 16:14	Reinspection Photo		Load JPG	☒
50	06/03/20 16:14	Reinspection Photo		Load JPG	☒
51	06/03/20 16:14	Reinspection Photo		Load JPG	☒
52	06/03/20 16:14	Reinspection Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/01/20 16:24	TP GIA REPORT		Load PDF	
2	14/05/20 09:48	LETTER TO OI		Load PDF	
3	21/05/20 22:26	LOD, AUTHORISATION LETTER, REPAIR BILL, GIA SEARCH		Load PDF	
4	21/05/20 22:27	MARKED ESTIMATE FINALISED		Load PDF	
5	17/07/20 11:39	Authorisation to Act		Load PDF	
6	17/07/20 11:39	GIA SEARCH		Load PDF	
7	17/07/20 11:39	LETTER TO OI		Load PDF	
8	17/07/20 11:39	LOD		Load PDF	
9	17/07/20 11:39	Release Voucher		Load PDF	
10	17/07/20 11:39	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/02/20 09:19	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLD847K (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT (A)
	SLR3315K (TP veh)		
Date of Accident:	17/01/2020		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	: \$			20,496.80
Final Repair Cost	: \$			3,500.00
Loss of Use	: \$			7.00 days at \$60.00 per day
Rental (if any)	: \$			days
LTA / GIA Search Fee	: \$			
Others:	: \$			
	: \$			
Final Settlement Sum (GLOBAL SUM)	: \$			3,500.00
Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u>: Agreed Liability _____ 50 _____ (%)				
B) For <u>GIA Registered Workshop</u>: BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)				
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown				
1)	SM Automotive	: \$		3,500.00
2)		: \$		
3)		: \$		

NUR SHAQILAH BTE ABDOL WAHAB

17 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20001265/AKS3S2**Date:** 17/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLR3315K**Insured Vehicle No :** SLD847K

Date of Loss: 17/01/2020

Nature of Claim: TP

Claim No: 6583665048SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLR3315K**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4035725

Reg. Date: 10/08/2017 (Man. Year: 2016)

Chassis No: RU11115721

Colour: White

Odometer: 35221 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,486.80	6,935.60	9,551.20	57.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,010.00	1,610.00	2,400.00	59.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,496.80	8,545.60	11,951.20	58.31
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	20,496.80	6,800.00	13,696.80	66.82
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
(S\$)		7,220.00		
Liabe Amount (50.00%) (S\$)		3,610.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,612.00		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment: 20/01/2020

Date Inspected: 20/01/2020 Inspected At:

Sm Automotive - Kaki Bukit (HQ)
BLOCK C - 1, KAKI BUKIT AVE 6, #01-43
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

7/17/2020

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	801.70 F	*801.70 FL
2	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
3	1		*FRONT BUMPER LOWER	Not Necessary	351.00 F	*- FL
4	1		*FRONT R/H BUMPER SIDE RETAINER	Necessary	27.10 F	*27.10 FL
5	1		*FRONT R/H BUMPER FOG LAMP	Not Necessary	327.70 F	*- FL
6	1		*FRONT R/H BUMPER FOG LAMP COVER	Not Necessary	45.00 F	*- FL
7	1		*FRONT R/H HEAD LAMP	Cracked	1,820.90 F	*1,820.90 FL
8	1		*FRONT R/H HEAD LAMP LOWER BRACKET	Not Necessary	65.00 F	*- FL
9	1		*FRONT R/H FENDER	Dented	589.00 F	*589.00 FL
10	1		*FRONT R/H FENDER ARCH PROTECTOR	Cut	193.00 F	*193.00 FL
11	1		*FRONT GRILLE OUTER	Not Necessary	386.00 F	*- FL
12	1		*FRONT GRILLE INNER	Not Necessary	351.80 F	*- FL
13	1		*FRONT GRILLE EMBLEM LOGO	Not Necessary	34.70 F	*- FL
14	8		*FRONT GRILLE CLIP	Not Necessary	52.00 F	*- FL
15	1		*FRONT R/H TYRE	Not Necessary	450.00 F	*- FL
16	1		*FRONT R/H LOWER ARM	Bent	350.10 F	*350.10 FL
17	1		*FRONT R/H KNUCKLE ARM	Damaged	390.70 F	*390.70 FL
18	1		*FRONT R/H KNUCKLE ARM BEARING	Necessary	161.90 F	*161.90 FL
19	1		*FRONT R/H SHOCK ABSORBER	Bent	430.10 F	*430.10 FL
20	1		*FRONT R/H DRIVE SHAFT	Not Necessary	1,019.20 F	*- FL
21	1		*FRONT STEERING RACK	Not Necessary	1,801.70 F	*- FL
22	1		*FRONT R/H SIDE MIRROR ASSY	Cut	794.50 F	*794.50 FL
23	1		*FRONT R/H DOOR	Dented	1,080.50 F	*1,080.50 FL
24	2		*FRONT R/H DOOR HINGE	Not Necessary	91.60 F	*- FL
25	1		*FRONT R/H DOOR INNER LOCK	Not Necessary	262.20 F	*- FL
26	1		*FRONT R/H DOOR WEATHERSTRIP	Not Necessary	195.80 F	*- FL
27	1		*FRONT R/H DOOR INNER TRIM BOARD	Not Necessary	650.70 F	*- FL
28	10		*FRONT R/H DOOR INNER TRIM BOARD CLIP	Not Necessary	65.00 F	*- FL
29	1		*FRONT R/H DOOR WINDOW MOTOR & REGULATOR ASSY	Not Necessary	382.90 F	*- FL
30	1		*FRONT R/H RIM	Cut	850.00 FS	*400.00 FS
31	1		*SET CAR VINYL WRAP	Necessary	2,400.00 FS	*1,200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,486.80	8,269.50
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,333.90
Total Parts (\$)	16,486.80	6,935.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT R/H DOOR, GLASS, LOCK, WEATHERSTRIP, TRIM BOARD, FRAME STICKER & WINDOW MOTOR REGULATOR ASSY.	New	280.00	80.00
2	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE, DRIVE SHAFT & STEERING RACK.	New	380.00	220.00
3	TO CHECK WHEEL ALIGNMENT.	New	150.00	80.00
4	TO CHECK WIRING.	New	100.00	30.00
5	TUFF KOTE.	New	150.00	0.00
6	TOWING FEE.	New	150.00	0.00
7	PANEL BEATING.	New	1,400.00	600.00
8	SPRAY PAINTING.	New	1,400.00	600.00
Gross Labour Cost (\$)			4,010.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >