



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 3378K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RHS REAR SLIDING DOOR	BADLY DENTED	1,725.00	1,665.10
1	RHS REAR SLIDING DOOR EDGE WEATHERSTRIP	NOT NECESSARY	182.00	-
1	RHS REAR SLIDING DOOR SIDE TAPE GARNISH	NECESSARY	128.00	128.00
1	RHS REAR SLIDING DOOR GLASS CHANNEL	NOT NECESSARY	215.00	-
1	RHS REAR SLIDING DOOR OPEN/CLOSE MOTOR ASSY	NOT NECESSARY	780.00	-
1	RHS REAR SLIDING DOOR LOCK ASSY	NOT NECESSARY	450.00	-
1	RHS REAR SLIDING DOOR LOWER MOULDING	NOT FITTED	142.00	-
1	RHS REAR SLIDING DOOR UPPER MOULDING	NOT FITTED	122.00	-
1	RHS REAR SLIDING DOOR LOWER SKIRTING	SCRATCHED	250.00	250.00
1	RHS REAR SLIDING DOOR INNER TRIM BOARD (NPA)	NOT NECESSARY	-	-
1	RHS REAR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	RHS REAR FENDER LOWER SKIRTING	SCRATCHED	110.00	110.00
1	RHS REAR FENDER INNER SHIELD	NOT NECESSARY	298.00	-
1	REAR BUMPER	CUT / TORN	1,580.00	781.10
1	SET REAR BUMPER SIDE RETAINERS	NOT NECESSARY	220.00	-
2	REAR BUMPER REFLECTORS (NPA)	NOT NECESSARY	-	-
1	RHS REAR HUB BEARING	NOT NECESSARY	341.00	-
	LESS 25% DISCOUNT		-1,635.75	-733.55
			4,907.25	2,200.65
<b><u>SPECIAL NETT ITEMS</u></b>				
1	RHS REAR SPORT RIM (SN)	CUT	980.00	450.00
1	SET RHS REAR DOOR SUN VISOR (SN)	NECESSARY	125.00	60.00
1	SET RHS REAR SLIDING DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	150.00	-
1	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	60.00	-
			1,315.00	510.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b> TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS,REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF RHS REAR FENDER. TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESRPAY PAINT ON PARTS REPLACED. TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS. TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS. TO CARRY OUT COMPUTERISED WHEEL ALIGNMENT. TO REMOVE AND REFIX DOOR COMPONENTS.		1,200.00          2,860.00	400.00          1,180.00
<b>GRAND TOTAL</b>			<b>9,082.25</b>	<b>3,890.65</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,100.00</b>

Report Ref No. CC4/FCI20001268/Uda3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.