

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20001283/DPA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00004201

Claimant
Vehicle No : SHA3468P **Insured Vehicle No :** SLB3769T

Date of Loss: 18/01/2020 Nature of Claim: TP Claim No: 1202000003210

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3468P	Engine No:	G4LEKU411472
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU188979
Reg. Date:	14/11/2019 (Man. Year: 2019)	Odometer:	33480 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,404.32	12,399.04	8,005.28	39.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,970.00	1,460.00	3,510.00	70.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,374.32	13,859.04	11,515.28	45.38
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	25,374.32	11,000.00	14,374.32	56.65
+ GST 7.00/7.00% (S\$)	1,776.20	770.00	1,006.20	56.65
Nett Amount (S\$)	27,150.52	11,770.00	15,380.52	56.65
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Car Rental (10.0 x S\$125.19/day) (S\$)		1,251.90		
+ Other Costs (S\$)		40.00		
Nett Liability (S\$)		13,561.90		
Global Sum Settlement (S\$)		13,550.00		

INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 21/01/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming
Industrial Estate
Singapore 575644

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2020)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3468P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Mtg Cracked	1,227.50 FL	*1,227.50 FL
2	1		*FRONT BUMPER COVER	Distorted / Mtg Broken	418.30 FL	*418.30 FL
3	1		*FRONT BUMPER SPONGE /ABSORBER	Not Necessary	86.90 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,075.10 FL	*- FL
5	2		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	373.80 FL	*- FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	70.00 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	56.00 FL	*- FL
8	2		*FRONT BUMPER SIDE BRACKET SUPPORT	Not Necessary	24.00 FL	*- FL
9	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
10	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	318.80 FL	*- FL
11	1		*HEADLAMP SUPPORT PANEL ASSY	Not Necessary	949.30 FL	*- FL
12	1		*HEADLAMP	Not Necessary	1,198.80 FL	*- FL
13	1		*BOOT LID	Dented / Bent	2,480.40 FL	*2,480.40 FL
14	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
15	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
16	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
17	1		*BOOT LID GLASS ,LOWER	Not Necessary	384.90 FL	*- FL
18	1		*REAR BUMPER	Distorted / Broken	459.40 FL	*459.40 FL
19	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
20	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent / Dented	276.20 FL	*276.20 FL
21	1		*REAR BUMPER CENTRE MOULDING ASSY	Distorted / Cut	451.25 FL	*451.25 FL
22	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	47.50 FL	*- FL
23	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
24	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	111.60 FL	*- FL
25	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
26	1		*REAR BUMPER UNDER CENTRE	Not Necessary	53.85 FL	*- FL
27	2		*REAR BUMPER SIDE UNDER (LH/RH)	Not Necessary	66.20 FL	*- FL
28	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	63.80 FL	*- FL
29	1		*REAR BUMPER FOG LAMP	Scratched / Broken	201.50 FL	*201.50 FL
30	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Not Necessary	257.10 FL	*- FL
31	2		*TAIL LAMP (LH/RH)	Not Necessary	1,740.80 FL	*- FL
32	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	417.80 FL	*- FL
33	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
34	1		*REAR PANEL LOWER PANEL	Not Necessary	39.40 FL	*- FL
35	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
36	1		*SPARE TYRE PANEL	Not Necessary	892.50 FL	*- FL
37	1		*SPARE TYRE FLIP BOARD	Not Necessary	338.80 FL	*- FL
38	1		*EXHAUST PIPE INSULATOR	Not Necessary	35.00 FL	*- FL
39	1		*EXHAUST SILENCER	Not Necessary	943.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
41	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
42	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
43	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
44	1		*BOOT LID COMFORT LOGO STICKER	Necessary	8.60 FS	*8.60 FS
45	1		*BOOT LID COMFORT CABLINK TEL NO.STICKER	Not Necessary	9.00 FS	*- FS
46	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
47	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
48	1		*FRONT BUMPER CENTRE MOULDING	Cut	680.00 FL	*680.00 FL
49	2		*HEADLAMP (LH/RH)	Cracked	7,973.60 FL	*7,973.60 FL
50	1		*REAR NO PLATE +TRIM COVER	Cracked	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,416.00	15,419.15
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,011.68	3,020.11
Total Parts (\$\$)	20,404.32	12,399.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	600.00
2	SPRAY PAINTING CHARGE	New	1,600.00	700.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	120.00	40.00
5	TOWING CHARGE	New	60.00	0.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	150.00	0.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	0.00
10	4 WHEEL ALIGNMENT	New	120.00	0.00
11	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
Gross Labour Cost (\$\$)			4,970.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >