

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001286/UGA3Q2

Date: 02/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLS7372M	Insured Vehicle No :	SHD3173Z
Date of Loss: 18/01/2020	Nature of Claim: TP	Claim No: MCT20010436

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS7372M		
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Engine No:	L15B72454968
Reg. Date:	02/10/2017 (Man. Year: 2017)	Chassis No:	MRHFC1660HT000348
Colour:	Blue	Odometer:	49360 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	801.56	707.15	94.41	11.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,630.00	1,610.00	49.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,041.56	2,337.15	1,704.41	42.17
+ GST 7.00/7.00% (S\$)	282.91	163.60	119.31	42.17
Nett Amount (S\$)	4,324.47	2,500.75	1,823.72	42.17
+ Car Rental (2.0 x S\$107.00/day) (S\$)		214.00		
Nett Liability (S\$)		2,714.75		

INSPECTION

Date of Assignment:	20/01/2020	
Date Inspected:	03/02/2020	Inspected At: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2020)
Parts:	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS7372M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY ,RR BUMPER	Dented / Deformed	462.90 FS	*462.90 FS
2	1		*BEAM COMPRR.BUMPER	Dented	135.00 FS	*135.00 FS
3	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
4	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
5	1		*GARNISH ,RR.BUMPER LOWER	Cut	29.85 FS	*29.85 FS
6	1		*CLIP .BUMPER (8 PCS)	Necessary	13.80 FS	*13.80 FS
7	1		*ANTENNA ASSYL.F	Cracked	45.60 FS	*45.60 FS
8	1		*BUZZER ASSYSMART	Not Necessary	47.17 FS	*- FS
9	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	801.56 707.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	120.00
2	REMOVE & INSTALL REVERSE SENSORS	New	180.00	120.00
3	RESET VEHICLE SMART ENTRY SYSTEM	New	480.00	380.00
4	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	1,300.00	560.00
5	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,100.00	450.00
Gross Labour Cost (\$\$)			3,240.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >