

**Adjuster Letter/DV not verified.**  
**This claim is to be authorized on the insurer's behalf.**  
**Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.**  
**Click on 'View Letter/DV' to verify the offer.**

**You cannot authorize this offer because**  
**Adjuster Letter/DV not verified.**  
**File to be authorized by your superior.**

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20001292/EGA3Q2  
**Date:** 17/04/2020

#### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SKF6600S	<b>Insured Vehicle No :</b>	SHA4161S
Date of Loss:	18/01/2020	Nature of Claim:	TP
		Claim No:	MCT20010442

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKF6600S</b>	Engine No:	KR20030317A
Make & Model:	INFINITI QX50, 2.0 T SENSORY (A)	Chassis No:	3PCMANJ55Z0551218
Reg. Date:	16/04/2019 (Man. Year: 2018)	Odometer:	8113 km
Colour:	Blue		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,300.50	1,413.36	887.14	38.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,805.00	2,105.00	1,700.00	44.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,105.50</b>	<b>3,518.36</b>	<b>2,587.14</b>	<b>42.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	427.39	246.29	181.10	42.37
<b>Nett Amount (S\$)</b>	<b>6,532.89</b>	<b>3,764.65</b>	<b>2,768.24</b>	<b>42.37</b>
<b>+ Car Rental (3.0 x S\$139.10/day) (S\$)</b>		417.30		
<b>Nett Liability (S\$)</b>		<b>4,181.95</b>		

#### INSPECTION

Date of Assignment:	21/01/2020	Inspected At:	Wearnes Automotive Pte Ltd (alexandra) (HQ)
Date Inspected:	22/01/2020		249 ALEXANDRA ROAD
			Singapore 159935
Estimated Period of Repair:	3.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)
<b>Parts:</b>	M1-SUV	INFINITI QX50 2.0 T SENSORY (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKF6600S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*BUMPER SET -RR</b>	Cut	942.30 FS	*848.07 FS
2	1		<b>*REINF-BUMPER RR</b>	Not Necessary	672.40 FS	*- FS
3	1		<b>*FASCIA -REAR BUMPER</b>	Cut	628.10 FS	*565.29 FS
4	1		<b>*BRKT -RR BUMPER</b>	Not Necessary	57.70 FS	*- FS
<b>Total Parts (S\$)</b>					<b>2,300.50</b>	<b>1,413.36</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items****There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE REAR BUMPER	New	1,800.00	900.00
2	TO PUTTY SPRAYPAINT ON REAR BUMPER	New	1,600.00	800.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	405.00	405.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,805.00</b>	<b>2,105.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;