

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20001295/QGA3Q2

**Date:** 30/07/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHB1870T	<b>Insured Vehicle No :</b>	SHA5271B
Date of Loss: 18/01/2020	Nature of Claim: TP	Claim No: MCT20010432

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB1870T</b>		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR5892550
Reg. Date:	16/07/2014 (Man. Year: 2014)	Chassis No:	JTDKN36U605747093
Colour:	Maroon	Odometer:	883031 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 5 mm	Rear Left Side:	Neuton 5 mm
Front Right Side:	Neuton 5 mm	Rear Right Side:	Neuton 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,868.28	2,091.51	4,776.77	69.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,355.00	1,420.00	1,935.00	57.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,223.28</b>	<b>3,511.51</b>	<b>6,711.77</b>	<b>65.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,223.28</b>	<b>3,150.00</b>	<b>7,073.28</b>	<b>69.19</b>
<b>+ Loss of Use (10.0 x S\$40.00/day) (S\$)</b>		400.00		
<b>+ Car Rental (10.0 x S\$104.86/day) (S\$)</b>		1,048.60		
<b>Nett Liability (S\$)</b>		<b>4,598.60</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,550.00</b>		

### INSPECTION

Date of Assignment:	21/01/2020	
Date Inspected:	21/01/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

**Adjuster:** OI SUN PIN**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)
<b>Parts:</b>	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB1870T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
2	1		*TAIL LAMP BRACKET ,LH (DISC 25%)	Missing	30.70 F	*23.03 F
3	1		*FENDER LINER RR/LH (DISC 25%)	Cut	141.30 F	*105.98 F
4	1		*DUCT ASSY ,QUARTER (DISC 25%)	Crumpled	70.40 F	*52.80 F
5	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
6	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
7	1		*BUMPER LIP COVER RR/LH (DISC 25%)	Crumpled	72.20 F	*54.15 F
8	1		*END PANEL (DISC 25%)	Dented	602.10 F	*451.58 F
9	1		*TAIL LAMP LH (DISC 10%)	Cracked	548.40 F	*493.56 F
10	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
11	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
12	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
13	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
14	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
15	1		*SOLAR FILM	Not Necessary	125.00 F	*- F
16	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
17	1		*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
18	1		*UNDER COVER CENTER REAR	Serviceable	514.50 F	*- F
19	1		*REINFORCEMENT ,RR	Serviceable	34.60 F	*- F
20	1		*BOX ,DECK FLOOR ,COVER LH	Serviceable	230.10 F	*- F
21	1		*BOX ,DECK FLOOR ,LH	Serviceable	196.80 F	*- F
22	1		*QUARTER GLASS RR/LH	Serviceable	168.10 F	*- F
23	1		*SEALANT W/SCREEN	Serviceable	37.00 F	*- F
24	1		*TROUGH BACK DOOR LH	Serviceable	110.90 F	*- F
25	1		*FLOOR PANEL RR/LH	Serviceable	102.00 F	*- F
26	1		*WHEEL HOUSE ,OUTER LH REAR	Serviceable	326.10 F	*- F
27	1		*PANEL SUB-ASSY ,QTR WHEEL HOUSE	Serviceable	588.40 F	*- F
28	1		*PANEL ASSY ,DECK LH	Serviceable	307.00 F	*- F
29	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
30	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
31	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
32	1		*FENDER RR/LH	Repair	766.80 F	*- F

F=Franchise part.

**Total Parts (\$\$)**      **6,868.28**      **2,091.51**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	1,183.00	800.00
2	SPRAY PAINT	New	1,476.00	500.00
3	TOWING CHARGE	New	56.00	40.00
4	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	60.00
5	TO INSPECT RR LIGHTING ,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
6	TO REMOVE/REFIT SEAT	New	120.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	20.00
8	TO WASH AND VACUUM	New	60.00	0.00
9	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,355.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >