

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20001303/T1TD3E2

Date: 27/11/2020

REFERENCE

Insured/Claimant:	SEE CHYE KIM	Policy No:	1800111779	
Date of Loss:	16/01/2020	Nature of Claim:	OD	Claim No: 3621556978SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME1081D			
Make & Model:	AUDI A4, 2.0 TFSI Limited Edition (A)	Engine No:	CVK065298	
Reg. Date:	18/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF40JA202860	
Colour:	Bronze	Odometer:	22660 km	
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$125,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,304.00	1,317.60	4,986.40	79.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,252.00	3,802.00	3,450.00	47.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,556.00	5,119.60	8,436.40	62.23
- Excess (\$\$)	900.00	900.00	0.00	0.00
(\$\$)	12,656.00	4,219.60	8,436.40	66.66
+ GST 7.00/7.00% (\$\$)	885.92	295.37	590.55	66.66
Nett Amount (\$\$)	13,541.92	4,514.97	9,026.95	66.66

INSPECTION

Date of Assignment:	22/01/2020	
Date Inspected:	21/01/2020	Inspected At: 281 ALEXANDRA ROAD
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,068.00 F	*- F
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 F	*- F
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	34.00 F	*- F
4	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	59.00 F	*- F
5	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	127.00 F	*- F
6	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 F	*- F
7	1		*FRONT FENDER - RH	Dented	722.00 F	*577.60 F
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 F	*- F
9	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	47.00 F	*- F
10	1		*FRONT FENDER BRACKET - RH	Not Necessary	33.00 F	*- F
11	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	46.00 F	*- F
12	1		*FRONT FENDER BRACE - RH	Not Necessary	112.00 F	*- F
13	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	228.00 F	*- F
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 F	*- F
15	1		*WHEEL SPOILER	Not Necessary	69.00 F	*- F
16	1		*WHEEL SPOILER TRIM - RH	Not Necessary	34.00 F	*- F
17	1		*STONE CHIP GUARD - RH	Not Necessary	48.00 F	*- F
18	1		*FENDER LEDGE COVER - RH	Necessary	29.00 F	*23.20 F
19	1		*FENDER LEDGE TOP COVER - RH	Necessary	21.00 F	*16.72 F
20	1		*EXTERIOR MIRROR MOUNTING - RH	Cut	845.00 F	*675.60 F
21	1		*MIRROR CAP - RH	Repair	249.00 F	*- F
22	1		*FRONT ALUMINIUM RIM - RH	Not Necessary	652.00 F	*- F
23	1		*SUNDRIES	Necessary	300.00 F	*24.48 F

F=Franchise part.

Total Parts (\$\$) **6,304.00** **1,317.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR MOUNTING	New	350.00	280.00
3	TO DISMANTLE FRONT BUMPER AND RHS FRONT FENDER. TO RENEW RHS FRONT FENDER. TO REPAIR RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS WING MIRROR COVER	New	3,500.00	1,850.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,252.00	3,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >