

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2020		22 Jan 2020 11:37 Edit Adj Rpt	S\$12,300.00 Edit Estimates	S\$12,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	TOH CHIO TEE , ID: S0121190J, Tel: +6596464184								
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHF724T	Date of Loss:	19/01/2020 23:00 - :59 [60 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 617965	Policy/Cover Note No.:	28615893QMX (Comprehensive) Coverage: 28/09/2019 - 27/09/2020						
Vehicle Reg. No. (Insured):	SGY5427E	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/02/2020]								
Driver/Custodian (Insured):	SI TIANG PENG (77 / Male) , NRIC: S0308772G, Tel: +6597877867 Email: VICTOR168@SINGNET.COM.SG								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 22/01/2020. Liab: unclear. Contact: Candy @ 6213 0998.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHF724T (617965)**
[SGY5427E]
TP
TRANS-CAB SERVICES PTE LTD
Jan 19 2020 11:00PM
[TOH CHIO TEE]
Trans-Cab Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ☐

Assessment Reports

1 per page ☐

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/02/20 20:25	Adjuster Immediate Advice		Load HTML	

Photos/Images

3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/07/20 14:18	General View		Load PDF	
2	24/07/20 14:19	Reinspection Photo		Load PDF	

Documentation

1 per page ☐

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/20 11:18	TPD SHF724T GIA REPORT From:SC - Reg. No: SGY5427E, Claimant: TOH CHIO TEE		Load PDF	
2	22/01/20 11:19	TPD SHF724T - PRI		Load PDF	
3	22/01/20 11:24	Arrange Survey		Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	22/01/20 11:36	Survey Request - Manual Assigned		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20001311/KYF3S2**Date:** 24/07/2020**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28615893QMX
Claimant Vehicle No :	SHF724T	Insured Vehicle No :	SGY5427E
Date of Loss:	19/01/2020	Nature of Claim:	TP
		Claim No:	617965

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF724T		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002400
Reg. Date:	31/12/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC281169
Colour:	Metallic White/Red	Odometer:	406654 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	85,486.83	22,890.90	62,595.93	73.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,210.00	2,820.00	22,390.00	88.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	110,696.83	25,710.90	84,985.93	76.77
Approved Total (Overridden) (S\$)		12,300.00		
(S\$)	110,696.83	12,300.00	98,396.83	88.89
+ GST 7.00/7.00% (S\$)	7,748.78	861.00	6,887.78	88.89
Nett Amount (S\$)	118,445.61	13,161.00	105,284.61	88.89

INSPECTION

Date of Assignment:	22/01/2020	
Date Inspected:	22/01/2020	Inspected At: Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	11.0 days	

Adjuster: KENNETH KONG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jul 2020)

Parts: 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF724T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Bent / Cracked	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Missing	344.70 FL	*344.70 FL
3	1		*BUMPER ABSORBER FRT	Cracked	394.68 FL	*394.68 FL
4	1		*BUMPER RETAINER FRT LH	Distorted	101.40 FL	*101.40 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	*101.40 FL
7	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Cracked	292.50 FL	*292.50 FL
9	1		*BUMPER GRILLE LOWER FRT	Missing	147.00 FL	*147.00 FL
10	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
11	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
12	1		*BUMPER BEAM FRT	Bent	663.70 FL	*663.70 FL
13	2		*BUMPER BEAM PAD FRT	Serviceable	24.50 FL	*- FL
14	1		*HEADLAMP RH	Broken	743.60 FL	*743.60 FL
15	1		*HEADLAMP PANEL FRT RH	Bent	128.30 FL	*128.30 FL
16	1		*HEADLAMP LH	Mtg Broken	743.60 FL	*743.60 FL
17	1		*HEADLAMP PANEL FRT LH	Bent	127.70 FL	*127.70 FL
18	1		*HEADLAMP HARNESS	Serviceable	556.10 FL	*- FL
19	2		*HEADLAMP ADJUST MOTOR	Serviceable	313.90 FL	*- FL
20	1		*HORN	Cracked	449.90 FL	*449.90 FL
21	1		*HORN BRACKET	Bent	21.90 FL	*21.90 FL
22	1		*FENDER PANEL FRT RH	Buckled	437.10 FL	*437.10 FL
23	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
24	1		*FENDER BRACKET FRT RH	Repair	106.40 FL	*- FL
25	1		*FENDER BRACKET LOWER RH	Repair	11.80 FL	*- FL
26	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	*- FL
27	1		*CHASSIS PANEL FRT RH	Repair	592.90 FL	*- FL
28	1		*CHASSIS PANEL SUPPORT FRT RH	Repair	431.70 FL	*- FL
29	1		*FENDER PANEL INNER FRT RH L70Y	Repair	838.40 FL	*- FL
30	1		*FENDER PANEL SUPPORT FRT RH L70Y	Repair	432.00 FL	*- FL
31	1		*WHEEL HOUSING PANEL FRT RH	Repair	2,698.60 FL	*- FL
32	1		*FENDER PANEL FRT LH	Buckled	414.40 FL	*414.40 FL
33	1		*WHEELARCH FRT LH	Serviceable	112.30 FL	*- FL
34	1		*FENDER BRACKET LOWER LH	Serviceable	11.80 FL	*- FL
35	1		*FENDER INSULATOR LH	Serviceable	65.50 FL	*- FL
36	1		*FENDER BRACKET FRT LH	Repair	59.00 FL	*- FL
37	1		*TOW COVER FRT	Serviceable	60.90 FL	*- FL
38	1		*FRONT BRACE PANEL	Bent	177.22 FL	*177.22 FL
39	1		*RADIATOR GRILLE	Cracked	969.90 FL	*969.90 FL
40	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
41	1		*RADIATOR GRILLE FRAME	Broken	686.00 FL	*686.00 FL
42	1		*FRAME FULL SUPPORT PANEL	Cracked	592.70 FL	*592.70 FL
43	1		*FRAME FULL SUPPORT BACKET	Bent	41.60 FL	*41.60 FL
44	1		*BONNET	Bent	1,312.70 FL	*1,312.70 FL
45	1		*BONNET INSULATOR	Cracked	294.30 FL	*294.30 FL
46	1		*BONNET STRUT RH	Serviceable	53.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BONNET HINGE RH	Distorted	237.40 FL	*237.40 FL
48	1		*BONNET STRUT LH	Serviceable	53.30 FL	*- FL
49	1		*BONNET HINGE LH	Repair	236.50 FL	*- FL
50	1		*BONNET LOCK	Bent	152.80 FL	*152.80 FL
51	1		*BONNET CABLE	Serviceable	55.20 FL	*- FL
52	1		*BONNET CABLE COVER	Serviceable	80.60 FL	*- FL
53	1		*BONNET SEAL OUTER	Serviceable	83.20 FL	*- FL
54	1		*BONNET SEAL INNER	Serviceable	70.10 FL	*- FL
55	2		*BONNET BUFFER	Serviceable	26.80 FL	*- FL
56	1		*LOWER ARM LH L70Y	Serviceable	192.70 FL	*- FL
57	1		*KNUCKLE ARM LH L70Y	Serviceable	481.50 FL	*- FL
58	1		*ABSORBER FRT LH L70Y	Serviceable	274.10 FL	*- FL
59	1		*DRIVESHAFT LH	Repair	1,355.70 FL	*- FL
60	1		*STABILIZER BAR FRT	Serviceable	427.90 FL	*- FL
61	1		*KNUCKLE HUB + BEARING LH / RH L70Y	Not Necessary	272.30 FL	*- FL
62	1		*LOWER ARM RH L70Y	Serviceable	192.70 FL	*- FL
63	1		*KNUCKLE ARM RH L70Y	Not Necessary	481.50 FL	*- FL
64	1		*ABSORBER FRT RH L70Y	Serviceable	274.10 FL	*- FL
65	1		*DRIVESHAFT RH	Repair	1,355.70 FL	*- FL
66	1		*STEERING PINION RACK L70Y	Repair	3,765.30 FL	*- FL
67	1		*AUTO COMPUTER	Serviceable	1,287.30 FL	*- FL
68	1		*INJECTION COMPUTER	Serviceable	2,706.30 FL	*- FL
69	1		*STEERING PUMP ELECTRIC L70Y	Serviceable	2,026.70 FL	*- FL
70	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*- FL
71	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
72	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*- FL
73	1		*SUBFRAME OUTER FRT	Serviceable	1,094.20 FL	*- FL
74	1		*SUBFRAME BRACKET OUTER LH	Serviceable	49.00 FL	*- FL
75	1		*SUBFRAME BRACKET OUTER RH	Serviceable	49.00 FL	*- FL
76	1		*A/C CONDENSER	Bent	1,537.80 FL	*1,537.80 FL
77	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	187.20 FL	*- FL
78	1		*A/C PIPE CONDENSER TO EXPANSION VALVE	Serviceable	380.20 FL	*- FL
79	1		*A/C PIPE COMPRESSOR	Serviceable	222.70 FL	*- FL
80	1		*A/C PIPE	Serviceable	486.50 FL	*- FL
81	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	57.30 FL	*- FL
82	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	56.70 FL	*- FL
83	1		*A/C CONDENSER GARNISH LH	Serviceable	67.90 FL	*- FL
84	1		*A/C CONDENSER GARNISH RH	Serviceable	67.70 FL	*- FL
85	1		*A/C COMPRESSOR	Serviceable	2,142.30 FL	*- FL
86	1		*AIR COOLER	Serviceable	598.90 FL	*- FL
87	1		*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
88	1		*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
89	1		*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
90	1		*TRANSMISSION COOLER PAD	Serviceable	9.50 FL	*- FL
91	1		*RADIATOR	Serviceable	871.20 FL	*- FL
92	2		*RADIATOR STUD UPPER	Serviceable	11.10 FL	*- FL
93	2		*RADIATOR BUSH UPPER	Serviceable	11.10 FL	*- FL
94	2		*RADIATOR MTG LOWER	Serviceable	30.10 FL	*- FL
95	1		*RADIATOR FAN COWLING	Cracked	417.00 FL	*417.00 FL
96	1		*RADIATOR FAN MOTOR LH	Serviceable	826.70 FL	*- FL
97	1		*RADIATOR FAN MOTOR RH	Serviceable	821.20 FL	*- FL
98	1		*RADIATOR TANK	Serviceable	174.80 FL	*- FL
99	1		*RADIATOR HOSE UPPER	Serviceable	97.50 FL	*- FL
100	1		*RADIATOR HOSE LOWER	Serviceable	254.10 FL	*- FL
101	1		*RADIATOR TANK HOSE	Serviceable	56.20 FL	*- FL
102	1		*FUSE BOX	Serviceable	987.39 FL	*- FL
103	1		*ENGINE MOUNTING UPPER	Serviceable	592.02 FL	*- FL
104	1		*ENGINE MOUNTING LOWER	Serviceable	149.20 FL	*- FL
105	1		*A/C HEATER VALVE	Serviceable	484.50 FL	*- FL
106	1		*TURBO DUCT	Serviceable	1,027.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*BASE BATTERY TRAY	Serviceable	363.40 FL	*- FL
108	1		*ENGINE MOUNTING RH	Serviceable	153.50 FL	*- FL
109	1		*ALTERNATOR	Serviceable	1,442.30 FL	*- FL
110	1		*ENGINE HARNESS	Serviceable	1,501.60 FL	*- FL
111	1		*BATTERY COVER	Serviceable	363.40 FL	*- FL
112	1		*BATTERY	Serviceable	350.00 FL	*- FL
113	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
114	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
115	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
116	1		*SUBFRAME INNER FRT	Repair	746.00 FL	*- FL
117	1		*SUBFRAME BRACKET INNER LH	Repair	101.00 FL	*- FL
118	1		*SUBFRAME BRACKET INNER RH	Repair	101.00 FL	*- FL
119	1		*SUBFRAME SUPPORT INNER	Repair	69.50 FL	*- FL
120	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
121	1		*DOOR HARNESS LH	Serviceable	2,640.00 FL	*- FL
122	1		*DOOR MIRROR ASSY LH	Serviceable	727.90 FL	*- FL
123	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
124	1		*DOOR HARNESS RH	Serviceable	2,640.00 FL	*- FL
125	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
126	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*- FL
127	1		*DOOR HINGE LOWER	Repair	300.55 FL	*- FL
128	1		*DOOR CHECK FRT LH/RH	Serviceable	194.77 FL	*- FL
129	1		*DOOR FINISHER FRT RH	Serviceable	515.06 FL	*- FL
130	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
131	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
132	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
133	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
134	1		*SEATBELT LH L70Y	Jammed	1,488.70 FL	*1,488.70 FL
135	1		*SEATBELT RH L70Y	Jammed	1,553.10 FL	*1,553.10 FL
136	1		*SEATBELT BUCKLE LH L70Y	Serviceable	498.70 FL	*- FL
137	1		*SEATBELT BUCKLE RH L70Y	Serviceable	498.70 FL	*- FL
138	1		*PASSENGER AIRBAG L70Y	Burst	2,093.60 FL	*2,093.60 FL
139	1		*STEERING AIRBAG L70Y	Burst	1,592.90 FL	*1,592.90 FL
140	1		*AIRBAG COMPUTER L70Y	Necessary	1,213.90 FL	*1,213.90 FL
141	1		*AIRBAG SENSOR L70Y	Necessary	502.90 FL	*502.90 FL
142	1		*AIRBAG SENSOR L70Y	Necessary	172.90 FL	*172.90 FL
143	1		*ROTARY SWITCH L70Y	Necessary	812.90 FL	*812.90 FL
144	1		*DASHBOARD	Torn	3,102.00 FL	*3,102.00 FL
145	1		*GLOVE BOX	Serviceable	526.90 FL	*- FL
146	1		*GLOVE BOX FLAP	Serviceable	648.10 FL	*- FL
147	1		*FACE CONSOLE	Serviceable	949.60 FL	*- FL
148	1		*DIESEL FILTER	Serviceable	839.78 FL	*- FL
149	1		*COVER HYDR DISTRIBUTOR	Serviceable	493.35 FL	*- FL
150	1		*ENGINE OIL SUMP	Serviceable	97.70 FL	*- FL
151	1		*SUPPORT ENGINE UPPER	Serviceable	610.37 FL	*- FL
152	1		*ENGINE TOP COVER 2.0	Cracked	139.80 FL	*139.80 FL
153	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
154	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
155	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
156	1		*BUMPER GRILLE LOWER CLIP	Necessary	69.00 FS	*69.00 FS
157	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
158	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
159	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
160	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
161	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
162	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
163	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
164	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
165	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
166	1		*SET FRONT LICENCE PLATE WITH HOLDER	Missing	80.00 FS	*45.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
167	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
168	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
169	1		*WINDSCREEN SEALANT	Not Necessary	109.20 FS	*- FS
170	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
171	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
172	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	3.80 FS	*- FS
173	2		*BONNET CABLE CLIP L70Y	Not Necessary	4.20 FS	*- FS
174	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	5.00 FS	*- FS
175	1		*FRONT LH DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
176	1		*FRONT LH DOOR STICKER CLASSIC	Not Necessary	80.00 FS	*- FS
177	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
178	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
179	1		*SET HEADLAMP SCREW	Not Necessary	4.70 FS	*- FS
180	1		*FRONT RH DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
181	1		*FRONT RH DOOR STICKER CLASSIC	Not Necessary	80.00 FS	*- FS
182	1		*SET BUMPER BEAM SCREW	Serviceable	24.50 FS	*- FS
183	2		*BONNET LOCK NUT	Serviceable	13.22 FS	*- FS
184	1		*SET FENDER SCREW	Serviceable	20.00 FS	*- FS
185	1		*SET FENDER NUT	Serviceable	5.90 FS	*- FS
186	1		*SET DASHBOARD SCREW	Serviceable	5.50 FS	*- FS
187	1		*SET BONNET HINGE BOLT	Serviceable	2.80 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	94,695.61	25,408.56
- List Item Discount on L Items 10.00/10.00% (\$)	9,208.78	2,517.66
Total Parts (\$)	85,486.83	22,890.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
2	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	9,000.00	800.00
4	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	350.00	0.00
5	TO RUST-PROOFING PF THE AFFECTED AREAS.	New	170.00	120.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	9,000.00	1,320.00
7	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	New	380.00	0.00
8	TO CHECKING STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
9	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
10	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
12	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
15	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER. }	New	380.00	100.00
16	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS. }	New	380.00	0.00
17	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	New	440.00	0.00
18	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	350.00	0.00
19	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	New	380.00	0.00
20	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	New	380.00	0.00
21	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	New	440.00	0.00
22	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING.	New	380.00	0.00
23	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	50.00
24	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS.	New	480.00	250.00
25	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	50.00
26	TOWING FEES.	New	150.00	50.00
Gross Labour Cost (\$\$)			25,210.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >