

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001315/UDS3Q2

Date: 26/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800130276

Claimant
Vehicle No : FBK4037L **Insured Vehicle No :** SMF4493Z

Date of Loss: 12/01/2020 Nature of Claim: TP Claim No: 8876493030SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK4037L		
Make & Model:	YAMAHA MT-09, 847cc	Engine No:	N701E042476
Reg. Date:	03/08/2015 (Man. Year: 2015)	Chassis No:	JYARN29K000000390
Colour:	Red	Odometer:	0 km
Engine Capacity:	847 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	180/55Z R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,086.00	5,346.10	2,739.90	33.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	400.00	860.00	68.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,346.00	5,746.10	3,599.90	38.52
Approved Total (Overridden) (\$\$)		4,550.00		
(\$\$)	9,346.00	4,550.00	4,796.00	51.32
+ GST 7.00/7.00% (\$\$)	654.22	318.50	335.72	51.32
Nett Amount (\$\$)	10,000.22	4,868.50	5,131.72	51.32
+ Loss of Use (4.0 x S\$20.00/day) (\$\$)		80.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,950.50		

INSPECTION

Date of Assignment: 22/01/2020

Date Inspected: 22/01/2020 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER SET MT-09	Scratched	63.00 F	*63.00 FL
2	1		*BAR HANDLE (RIZOMA)MT-09	Serviceable	252.00 F	*- FL
3	1		*BEARING STEERING CONE LOWER	Not Necessary	82.00 F	*- FL
4	1		*BEARING STEERING CONE UPPER	Not Necessary	56.00 F	*- FL
5	1		*BOLT	Necessary	3.00 F	*3.00 FL
6	1		*BOLT	Necessary	8.00 F	*8.00 FL
7	1		*BOTTLE BRAKE OIL	Necessary	35.00 F	*35.00 FL
8	1		*BOX REAR KAPPA K58L	Serviceable	1,050.00 F	*- FL
9	1		*BRACKET MASTER CYLINDER (DMV)	Cracked	105.00 F	*105.00 FL
10	1		*BRACKET 5	Bent	97.00 F	*97.00 FL
11	1		*BRACKET MASTER CYLINDER	Bent	38.00 F	*38.00 FL
12	1		*BRACKET UNDER FORK	Repair	667.00 F	*- FL
13	1		*CABLE THROTTLE	Cut	56.00 F	*56.00 FL
14	1		*CAP GRIP	Torn	19.00 F	*19.00 FL
15	4		*COLLAR	Necessary	24.00 F	*24.00 FL
16	1		*COVER 1	Cut	119.00 F	*119.00 FL
17	1		*COVER 1	Cut	149.00 F	*149.00 FL
18	1		*COVER 2	Cut	119.00 F	*119.00 FL
19	1		*COVER COOLANT	Necessary	28.00 F	*28.00 FL
20	1		*COVER GRIP (GRAB ON)	Necessary	29.00 F	*29.00 FL
21	1		*COVER HEADLAMP (R&G)	Cut	110.00 F	*110.00 FL
22	1		*COVER PANEL INNER 3	Cut	20.00 F	*20.00 FL
23	1		*COVER SIDE 2	Cut	90.00 F	*90.00 FL
24	1		*COVER TANK	Cut	31.00 F	*31.00 FL
25	1		*CRASH BAR (GIVI)	Bent	356.00 F	*356.00 FL
26	1		*DAMPER	Necessary	2.00 F	*2.00 FL
27	1		*DAMPER	Necessary	2.00 F	*2.00 FL
28	2		*DAMPER	Necessary	6.00 F	*6.00 FL
29	1		*DAMPER HEADLIGHT 1	Necessary	12.00 F	*12.00 FL
30	1		*DAMPER HEADLIGHT 2	Necessary	12.00 F	*12.00 FL
31	1		*EMBLEM	Necessary	26.00 F	*26.00 FL
32	1		*EMBLEM	Necessary	26.00 F	*26.00 FL
33	1		*EMBLEM 3D	Necessary	38.00 F	*38.00 FL
34	1		*EMBLEM 3D	Necessary	38.00 F	*38.00 FL
35	1		*EMBLEM YAMAHA	Necessary	16.00 F	*16.00 FL
36	1		*FOOTREST FRONT LH	Cut	45.00 F	*45.00 FL
37	2		*GASKET HOSE BRAKE	Necessary	6.00 F	*6.00 FL
38	1		*GRAPHIC 1	Necessary	16.00 F	*16.00 FL
39	1		*HEADLIGHT ASSY	Cracked	1,199.00 F	*1,199.00 FL
40	1		*LABEL CAUTION	Necessary	7.00 F	*7.00 FL
41	1		*LABEL FUEL	Necessary	7.00 F	*7.00 FL
42	1		*SET LIGHT TOUREX WITH BRACKET	Damaged	259.00 F	*259.00 FL
43	1		*METER ASSY	Cracked	829.00 F	*829.00 FL
44	1		*MIRROR RH	Broken	61.00 F	*61.00 FL
45	4		*NUT (WINDSCREEN)	Necessary	20.00 F	*20.00 FL
46	6		*NUT SPRING	Necessary	12.00 F	*12.00 FL
47	6		*NUT SPRING	Necessary	12.00 F	*12.00 FL
48	3		*NUT SPRING	Necessary	6.00 F	*6.00 FL
49	1		*OIL BRAKE (MOTUL) RBF 600	Necessary	37.00 F	*37.00 FL
50	1		*PANEL 1	Warped	105.00 F	*105.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*PANEL 2	Warped	103.00 F	*103.00 FL
52	1		*PANEL INNER RH	Cracked	194.00 F	*194.00 FL
53	1		*PIN COTTER	Necessary	5.00 F	*5.00 FL
54	2		*PLUG ,SPECL SHAPE	Necessary	4.00 F	*4.00 FL
55	1		*SET PUMP MASTER CYCLINDER R3	Necessary	363.00 F	*363.00 FL
56	1		*RUBBER COVER 4 LED TOUREX LIGHT	Necessary	28.00 F	*28.00 FL
57	1		*RUBBER FOOTREST FRONT	Torn	21.00 F	*21.00 FL
58	4		*SCREW (VISOR)	Necessary	20.00 F	*20.00 FL
59	1		*SCREW PAN	Necessary	2.00 F	*2.00 FL
60	1		*SEAL STEERING CONE	Not Necessary	31.00 F	*- FL
61	1		*SHIFT PEDAL ASSY	Bent	89.00 F	*89.00 FL
62	1		*SIDE STAND FOOT (SWMOTECH) MT-09 TRACER	Cut	149.00 F	*149.00 FL
63	1		*SIGNAL FRONT ASSY LH	Broken	38.00 F	*38.00 FL
64	1		*SIGNAL FRONT RH	Cut	38.00 F	*38.00 FL
65	1		*STAY	Bent	180.00 F	*180.00 FL
66	1		*STAY SIDE 1	Necessary	31.00 F	*31.00 FL
67	1		*STAY SIDE 1	Necessary	31.00 F	*31.00 FL
68	1		*STAY ,FLASHER 1	Necessary	3.00 F	*3.00 FL
69	1		*STAY ,SUPPORT 1	Necessary	24.00 F	*24.00 FL
70	1		*STICKER GRAPHIC 2	Necessary	16.00 F	*16.00 FL
71	1		*WASHER PLATE	Necessary	5.00 F	*5.00 FL
72	1		*WINDSHIELD (MRA) MT-09	Broken	210.00 F	*210.00 FL
73	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	19.00 FS	*10.00 FS
74	1		*LEVER BRAKE	Scratched	77.00 F	*77.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,086.00	5,939.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	592.90
Total Parts (\$\$)	8,086.00	5,346.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-FOR DISMANTLING & ASSEMBLING OF PARTS QUOTED	New	1,260.00	400.00
Gross Labour Cost (\$\$)			1,260.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >