

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001341/EPS3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SML4757G	Insured Vehicle No :	SHD3405E
Date of Loss: 15/01/2020	Nature of Claim: TP	Claim No: MCT20010338

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML4757G		
Make & Model:	SUBARU XV, 2.0 I-S EYESIGHT AWD CVT (A)	Engine No:	FB20CE20703
Reg. Date:	23/05/2019 (Man. Year: 2018)	Chassis No:	JF1GT7KL5KG062709
Colour:	Grey	Odometer:	17401 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,503.07	2,036.00	467.07	18.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,050.00	1,700.00	61.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,253.07	3,086.00	2,167.07	41.25
+ GST 7.00/7.00% (\$\$)	367.71	216.02	151.69	41.25
Nett Amount (\$\$)	5,620.78	3,302.02	2,318.76	41.25
+ Loss of Use (3.0 x S\$80.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,549.47		

INSPECTION

Date of Assignment:	22/01/2020	
Date Inspected:	23/01/2020 Inspected At:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road Singapore 159097
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2020)
Parts:	M1-SUV	SUBARU XV 2.0 I-S EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML4757G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER PUNCHING F	Repair	446.40 FN	*- FN
2	1		*BRKT SD F XUV RH	Serviceable	7.20 FN	*- FN
3	1		*BRKT SD F XUV LH	Serviceable	7.20 FN	*- FN
4	1		*LAMP ASSY HEAD	Broken	2,520.00 FN	*2,520.00 FN
5	2		*CLIP	Serviceable	23.04 FN	*- FN
6	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	3,103.84	2,540.00
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	600.77	504.00
Total Parts (\$\$)	2,503.07	2,036.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/ REPLACE FRONT BUMPER AND BRACKET LH/RH	New	1,740.00	560.00
2	RESPRAY FRONT BUMPER ASSY AND RHS FENDER	New	960.00	440.00
3	CONDUCT FRONT LIGHTING TEST	New	50.00	50.00
Gross Labour Cost (\$)			2,750.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >