



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: CPW/jc/1904010

Date: 04th Feb 2020

Our Ref: CS1/LAW20001344/Eqd3e2

M/s Wong Thomas & Leong

133 New Bridge Road #10-01

Chinatown Point

Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FU 1852U

INSURED VEHICLE: JSK 7438

ACCIDENT DATE: 25/12/2017

We thank you for your instruction on 22/01/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FU 1852U from M/s Oh Appraisal Services.
- b) Final Repair Bill of FU 1852U from M/s Hua Chin (2000) Trading Motor Service Centre.
- c) Police Report of Vehicle FU 1852U and JSK 7438.
- d) Colour damaged vehicle photographs of FU 1852U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|----------------|
| Registration Number | : FU 1852U |
| Make & Model | : Honda TA 200 |
| Chassis Number | : TA2000005009 |
| Year of Registration | : 2001 |

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.