

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001352/GRS3Q2
Date: 19/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900233750
Claimant Vehicle No :	SML5607A	Insured Vehicle No :	SLT1522G
Date of Loss:	16/01/2020	Nature of Claim:	TP
		Claim No:	7606218511SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5607A	Engine No:	3ZRB898925
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600090831
Reg. Date:	27/05/2019 (Man. Year: 2016)	Odometer:	15406 km
Colour:	Brown		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,677.50	3,119.15	558.35	15.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	860.00	970.00	53.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,507.50	3,979.15	1,528.35	27.75
+ GST 7.00/7.00% (S\$)	385.53	278.54	106.99	27.75

Nett Amount (S\$)	5,893.03	4,257.69	1,635.34	27.75
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,158.49		

INSPECTION

Date of Assignment: 22/01/2020

Date Inspected: 22/01/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Jack Cars Enterprise Pte Ltd (HQ)
 61 Ubi Avenue 2, #01-20 Automobile Megamart
 Singapore 408898

Adjuster: XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	980.00 FL	*881.00 FL
2	1		*FRONT BUMPER BRACKET -RIGHT	Bent	75.00 FL	*56.20 FL
3	1		*FRONT BUMPER INNER SPONGE	Not Necessary	120.00 FL	*- FL
4	1		*HEADLAMP -RIGHT	Broken	1,950.00 FL	*1,950.00 FL
5	1		*HEADLAMP LOWER BRACKET -RIGHT	Repair	95.00 FL	*- FL
6	1		*FRONT FENDER -RIGHT	Buckled	750.00 FL	*750.00 FL
7	1		*MUDGUARD -RIGHT	Deformed	180.00 FL	*180.00 FL
8	1		*BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
9	1		*RIM -RIGHT (LOCAL REPAIR)	Cut	350.00 FS	*100.00 FS
10	1		*SPARE TANK	Deformed	180.00 FL	*155.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,760.00	4,112.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,082.50	993.05
Total Parts (\$\$)	3,677.50	3,119.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	800.00	400.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	700.00	400.00
3	TO REMOVE AND REINSTALL FRONT BUMPER	New	150.00	0.00
4	WHEEL BALANCING & ALIGNMENT	New	180.00	60.00
Gross Labour Cost (\$\$)			1,830.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >