

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20001355/KES3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800057172

**Claimant**  
**Vehicle No :** SHD123M **Insured Vehicle No :** SKA6619R

Date of Loss: 18/01/2020 Nature of Claim: TP Claim No: 8335839480SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD123M</b>	Engine No:	M9R8839C002944
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC282689
Reg. Date:	22/03/2016 (Man. Year: 2015)	Odometer:	429712 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,561.20	4,739.44	12,821.76	73.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,230.00	1,520.00	16,710.00	91.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>35,791.20</b>	<b>6,259.44</b>	<b>29,531.76</b>	<b>82.51</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,000.00</b>		
<b>(\$\$)</b>	35,791.20	5,000.00	30,791.20	86.03
<b>+ GST 7.00/7.00% (\$\$)</b>	2,505.38	350.00	2,155.38	86.03
<b>Nett Amount (\$\$)</b>	<b>38,296.58</b>	<b>5,350.00</b>	<b>32,946.58</b>	<b>86.03</b>
<b>+ Car Rental (7.0 x S\$99.13/day) (\$\$)</b>		693.91		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>6,051.40</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>6,050.00</b>		

### INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 21/01/2020 Inspected At: Trans-Cab Services Pte Ltd (HQ)  
2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Dented	404.56 FL	*404.56 FL
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
19	1		*BOOT REAR	Buckled	1,677.20 FL	*1,677.20 FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
24	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
25	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
26	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
28	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
29	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.90 FL	*- FL
31	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
32	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- FL
33	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
34	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*- FL
35	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
36	1		*BOOT LOCK	Repair	246.60 FL	*- FL
37	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
38	1		*EXHAUT CAP REAR	Repair	125.40 FL	*- FL
39	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
40	1		*SPARE WHEEL PANEL	Repair	1,229.40 FL	*- FL
41	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
42	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
43	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
44	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
45	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
46	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
47	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
48	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
49	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
50	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
51	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
52	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
53	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
55	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
56	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
57	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
58	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
59	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
60	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
61	1		*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	*- FS
62	1		*EXHAUST BRACKET REAR	Repair	24.80 FS	*- FS
63	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,336.67</b>	<b>5,192.16</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,775.47</b>	<b>452.72</b>
<b>Total Parts (\$\$)</b>	<b>17,561.20</b>	<b>4,739.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	7,500.00	600.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
10	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
12	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
15	TO TRANSFER OF REAR LUGGAGE FLOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
16	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
17	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>18,230.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >