

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20001364/ATF3E2

Date: 01/07/2020

REFERENCE

Insured/Claimant: BASAVARAJAIAH AJAY MUDDUBASAPPALA Policy No: 1800149214-01

Date of Loss: 18/01/2020

Nature of Claim: OD

Claim No: 9214608523SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK9841S		
Make & Model:	AUDI Q2, 1.4 (A)	Engine No:	CZE847441
Reg. Date:	31/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZGA2KA014606
Colour:	Grey	Odometer:	20413 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$103,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,948.00	4,097.04	13,850.96	77.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,692.00	4,412.00	6,280.00	58.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,640.00	8,509.04	20,130.96	70.29
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	28,240.00	8,109.04	20,130.96	71.29
+ GST 7.00/7.00% (\$\$)	1,976.80	567.63	1,409.17	71.29
Nett Amount (\$\$)	30,216.80	8,676.67	21,540.13	71.29

INSPECTION

Date of Assignment: 22/01/2020

Date Inspected: 22/01/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,763.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	326.00 FS	*- FS
3	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	159.00 FS	*- FS
4	2		*FRONT BUMPER END CAP - LH / RH	Not Necessary	32.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	282.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	147.00 FS	*- FS
7	1		*WHEEL SPOILER - LH	Not Necessary	32.00 FS	*- FS
8	1		*FRONT BUMPER ADAPTER - LH	Not Necessary	34.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	34.00 FS	*- FS
10	1		*HEADLIGHT MOUNTING - LH	Not Necessary	112.00 FS	*- FS
11	1		*LED HEADLIGHT - LH	Not Necessary	4,627.00 FS	*- FS
12	1		*FRONT FENDER - LH	Dented	1,079.00 FS	*863.20 FS
13	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	38.00 FS	*- FS
14	1		*FRONT FENDER BRACKET - LH	Not Necessary	45.00 FS	*- FS
15	1		*FRONT FENDER BRACKET - LH	Not Necessary	15.00 FS	*- FS
16	1		*FRONT FENDER BRACKET - LH	Not Necessary	15.00 FS	*- FS
17	1		*FRONT FENDER BRACE - LH	Not Necessary	35.00 FS	*- FS
18	1		*WHEEL HOUSING LINER - LH	Not Necessary	185.00 FS	*- FS
19	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	54.00 FS	*- FS
20	2		*FRONT WHEEL COVER - LH / RH	Necessary	606.00 FS	*484.00 FS
21	1		*FRONT DOOR - LH	Dented	2,380.00 FS	*1,904.00 FS
22	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
23	1		*FRONT DOOR CATCH	Not Necessary	113.00 FS	*- FS
24	1		*EXTERIOR MIRROR MOUNTING	Not Necessary	964.00 FS	*- FS
25	1		*MIRROR CAP - LH	Repair	159.00 FS	*- FS
26	1		*FRONT DOOR COVER - LH	Cut	242.00 FS	*193.20 FS
27	1		*REAR DOOR - LH	Repair	2,380.00 FS	*- FS
28	1		*REAR DOOR OUTER SEAL	Not Necessary	127.00 FS	*- FS
29	1		*BONDING AGENT	Not Necessary	46.00 FS	*- FS
30	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
31	1		*REAR DOOR CATCH	Not Necessary	113.00 FS	*- FS
32	1		*REAR DOOR COVER - LH	Cut	213.00 FS	*170.00 FS
33	1		*FRONT DOOR WINDOW GUIDE - LH	Not Necessary	389.00 FS	*- FS
34	1		*FRONT DOOR WINDOW APERTURE SEAL - LH	Not Necessary	127.00 FS	*- FS
35	1		*CORNER TRIM - LH	Not Necessary	43.00 FS	*- FS
36	1		*FRONT ALUMINIUM RIM - LH	Cut	579.00 FS	*462.80 FS
37	1		*SUNDRIES	Necessary	300.00 FS	*19.84 FS
					Total Parts (\$\$)	17,948.00 4,097.04

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK AND POWER WINDOW DEVICES	New	560.00	280.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO RENEW LHS WING MIRROR ASSY	New	400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	1,500.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLE AND LHS WING MIRROR COVER	New	4,900.00	1,800.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,692.00	4,412.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >