

INS. CASE OWNER

Survivor:

ADRIAN

DOI: 20/01/2020

Date / Time : 20/01/2020

Registered in Merimex

Pre-assign / CCU / FTE



Insured Vehicle No : GBJ 28U

Claim No. _____

Name of Insured

Policy No.

Insured Tel No.

HP:

Make / Model :

Excess Sec II :SS

D.O.A: 20/01/2020 06:45

Place of Accident : BKE TWDS PIE B4 PIE(CHANGI) NEAR ERP

Is driver the owner?

(YES ☒ NO)

Nature of Accident :

If **NO**, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(VL: YES / NO)

Insured Liability :	%	Final ? Yes / No
---------------------	---	------------------

GZ 7162A



INRS:
WSP: NHT
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	GZ 7162A - CC8/AIG18005793/M1za3q2; DOA: 28.03.2018 GBJ 28U - NA/MSG20001214/h4; DOA: 20.01.2020		STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☒
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☒
			LTA / GIA :	☒
			Medical Bill:	☒
			PIR:	☒
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☒
			Post-Repair Photos:	☒
			Others:	☒
PRELIMINARY ADVICE Date/Time: Sent By: Confirm by: Email ☐ Call ☐				
FINALIZATION Date/Time: Confirm with: Confirm by: Email ☐ Call ☐				
Repair Cost:	\$5 72001	(10 days) Reduction: 400.00	% 93	
FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐				
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. :	28	
Repair Cost:	\$5 7434.00			
Loss of Rental (LOR):	\$5 (days)			
Loss of Use (LOU):	\$5 900.00 (\$ 60 x 15 days)			
Loss of Income (LOI):	\$5 (\$ x days)			
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	\$5 7.40			
Medical:	\$5			
Disbursement:	\$5	(e.g. Tow/ Independent)		
Legal Cost	\$5			
Total:	\$5 9301.40	Global Sum \$5:	4370.00	
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐				
Payee 1:	\$5 4370.00	Name 1:	New Hock Teck Motor Pte Ltd	
Payee 2: (Strike if N.A.)	\$5	Name 2:		
Payee 3: (Strike if N.A.)	\$5	Name 3:		

1365 / Ag.

ASSIGNMENT

Estimated Cost
 (Q / TP / WS / TP RES / OD RES / EVA / INV / MV)
 To Inspect Vehicle No.
 at Workshop no.
 of
 Insured
 Policy No.
 Claims No.
 Sum Insured. Excess
 (Client's Record)
 Make of Veh:

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value
 IDAC Accident Report Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repair: 10 days Res. Yes or No
 Loss Sum: 70 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted: Vehicle IN / OUT

N/S	O/S

OUTER: G27162A. 2006 August.
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mit Canter 2835
 Colour: White AK Insured / Sid / NA / NA
 Sp Reading: 410903 T/Eater: Insured / Sid / NA / NA
 Engine:
 Cifer: F370AB40044
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: Nil / SRim / STD A/Rim or
 Tyre Size F: 155 R14 Yokohama
 R: 165 R13 Greenmax
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A. D.O.I 20/01/20
 Survey held at NHT.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Front N/S, Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	TPEO
	COE Expiry: 31/07/21
	1/6 \$3200/- (Red = \$40,717 / 93%)
	MV: 10K
	PV: 6.8K
	Nett: 3.2K
	* 10 repair days + 1 PRS + 2 PH + 2 SUM = 15 days

Date/Time File Path 4/7 ☐ : Prel. Report ☐ : Final Report
 II
 Date/Time File Path 4/7
 Days Of Repair:
 Resurvey No. of Trip:
 Survey Fee
 Compensation
 3rd Party
 Site Ins. IS
 Ins. Ins. AS
 Tech. Ins. AS
 Ins. Ins. AS



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

20/01/2020

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPEQ

FB70ABA00444

cracked

Accident date: 20/01/2020

Estimated repair cost for vehicle no: GZ7162A MITSUBISHI FB70ABOSRDEB 2.8 M '06

CHASSIS: FB70ABA00444

S/n	Qty	Items	U/price	Amount
1	1	Front Wiper Garnish <i>cracked</i>		\$430.00 ✓
3	1	Front Windscreen Moulding <i>New</i>		\$330.00 ✓
4	1	Front Panel <i>Dented</i>		\$1,175.00 ✓
5	1	Front L/H Side Panel <i>Distorted</i>		\$590.00 ✓
6	1	Front Grille <i>cracked</i>		\$530.00 ✓
7	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 ✓
8	1	Front Grille Emblem Logo <i>New</i>		\$59.00 ✓
9	1	Front Bumper <i>Repair</i>		\$980.00 ✓
10	1	Front L/H Headlamp <i>Smashed</i>		\$590.00 ✓
11	1	Front L/H Side Lamp <i>Smashed</i>		\$195.00 ✓
12	1	Front L/H Signal Lamp Upper <i>Smashed</i>		\$240.00 ✓
13	1	Front L/H Side Mirror Top Cover <i>2M</i>		\$105.00 ✓
14	1	Front L/H Side Mirror Round Cover <i>1M</i>		\$86.00 ✓
15	1	Front L/H Side Mirror Lower Garnish <i>cracked</i>		\$85.00 ✓
16	1	Front L/H Side Mirror Stay <i>New</i>		\$422.00 ✓
17	1	Front L/H Door <i>Distorted</i>		\$2,271.00 ✓ <i>180</i>
18	2	Front L/H Door Hinge <i>Best</i>	\$140.00	\$280.00 ✓
19	1	Front L/H Door Outer Moulding <i>New</i>		\$140.00 ✓
20	1	Front L/H Door Lock <i>new</i>		\$695.00 ✓
21	1	Front L/H Door Weatherstrip <i>New</i>		\$320.00 ✓
22	1	Front L/H Door Inner Trim Board <i>New</i>		\$620.00 ✓
23	1	Front L/H Door Window Motor & Regulator Assy <i>new</i>		\$1,712.00 ✓
24	1	Front L/H Door Company Sticker <i>new</i>		\$55.00 ✓ <i>20/01</i>
25	1	Front L/H Door Pillar <i>Repair</i>		\$1,270.00 ✓
26	1	Rear TailGate <i>Dented</i>		\$2,900.00 ✓ <i>2378</i>
27	2	Rear Tailgate Top Side Handle <i>new</i>	\$350.00	\$700.00 ✓

28	2	Rear Tailgate Lower Side Lock	RH Bent	\$320.00	\$640.00	320
29	3	Rear Tailgate Lower Side Hinges	RH Bent	\$95.00	\$285.00	95
30	2	Rear Tailgate Lower Side Bracket	Bent	\$340.00	\$680.00	340
31	1	Rear Tailgate Lower Member	Distorted		\$550.00	✓
32	1	Rear Tailgate Aluminium Cover	Not New		\$450.00	x
33	1	Rear Tailgate 70 Km/h Sticker	for New		\$30.00	15 (SN)
34	1	Rear Tailgate 13 Pax Sticker	✓		\$30.00	15 (SN)
35	1	Rear Tailgate STA Sticker	New		\$20.00	10 (SN)
36	1	Rear R/H Side Tailgate	Repair		\$4,000.00	x
37	4	Rear R/H Side Tailgate Lower Hinge	Not New	\$90.00	\$360.00	+
38	1	Rear R/H Side Tailgate Aluminium Cover	Not New		\$850.00	+
39	1	Rear R/H Tail Lamp	Smashed		\$240.00	✓
40	1	Rear R/H Tail Lamp Bracket	Distorted		\$140.00	✓
41	1	Rear Step Bracket	for Repair		\$250.00	+
42	1	Rear Floor Panel			\$10,000.00	+
43	1	Rear Floor Panel Plywood	?		\$650.00	+
44	1	Rear Exhaust	Not New		\$540.00	+
45	2	Rear Exhaust Mounting	New	\$55.00	\$110.00	+
46	1	Rear Center Exhaust			\$850.00	+

10478 SN-70

9430.20.

Subtotal :- \$37,507.00

Labour charges

To remove & refit cushion & trim board	\$280.00 X
To remove & refit dashboard	\$450.00 X
To remove & refit front L/H door, glass, lock, weatherstrip, trim board, window motor & regulator assy	\$280.00 80.
To remove & refit front windscreen	\$160.00 120
Gum	\$60.00 X NN
To remove & refit rear & centre exhaust	\$380.00 X
To check wiring	\$100.00 60
Tuff kote	\$150.00 80
Towing fee	\$150.00 X
Panel beating	\$2,000.00 1600
Spray painting	\$2,400.00 1400

3340

Subtotal :- \$6,410.00

Total:- \$43,917.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 17840.20

4/5: 3.2K (Nett Value)

10 Days

3.2K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Business
Owner ID:	600E
Vehicle Details	
Vehicle No.:	GZ7162A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Jan 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	FB70ABOSRDEB
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	4M40HB8324
Chassis No.:	FB70ABA00444
Maximum Power Output:	-
Open Market Value:	\$18,136.00
Original Registration Date:	08 Aug 2006
First Registration Date:	08 Aug 2006
Transfer Count:	1
Actual ARF Paid:	\$907.00

Importation/Exportation Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Importation/Exportation Details	
COE Expiry Date:	31 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,247.00
COE Rebate Amount:	\$6,793.00
Total Rebate Amount:	\$6,793.00

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 21 Jan 2020

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

SEARCH Fuso Canter FB70

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

— Comparing 2 Vehicles —

Mitsubishi Fuso Canter FB70 (COE till 08/2021)



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Mitsubishi Fuso Canter FB70 (COE till 08/2022)



Add to Shortlist



NO IMAGE AVAILABLE

Use search bar above to select whether car to compare.



NO IMAGE AV

Use search bar above to select whether car to compare.

CAR DETAILS

Price	\$14,800	\$23,700	-	-
Instalment	N.A.	N.A.	-	-
Registration Date	21-Sep-2006	26-Nov-2007	-	-
Manufactured	2006	2007	-	-
Mileage	-	-	-	-
Transmission	Manual	Manual	-	-
Engine Cap	2,835 cc	2,977 cc	-	-
Road Tax	-	-	-	-
Power	-	-	-	-
Curb Weight	1,480 kg	1,800 kg	-	-
Features	-	-	-	-
Accessories	-	-	-	-
Description	Vehicle Is In Good Condition, Feel Free To Contact For More Details Or Arrange For Viewing Of Vehicle!	Vehicle Comes With Power Tailgate, Vehicle Is In Good And Well Maintained Working Condition, Perfect Commercial Vehicle To Sell, And Vehicle Comes With 1-month Warranty, Please Contact Us For More Detail,	-	-
COE	\$23,127	\$17,920	-	-
OMV	\$17,886	\$22,282	-	-
ARF	\$895	-	-	-
Depreciation	\$9,190 /yr	\$9,080 /yr	-	-
No. of Owners	4	5	-	-
Type of Vehicle	Truck	Truck	-	-
Category	COE Car, Direct Owner Sale	COE Car, Premium Ad Car	-	-
Availability	Available	Available	-	-
Remarks	Fuel type Diesel COE expiry date 2022-08-31	Fuel type Diesel COE expiry date 2022-08-31	-	-

SELLER INFORMATION

Seller	Direct Owner	A&L Automobile Pte Ltd	-	-
Address	-	11 Mandai Estate #05-09	-	-

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. Gz7162A and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 20 day of 01 2020.

Signature :

✓

Name :

ID No. :

Address :

Wing Lian Engineering Construction
51238600 E

Witness Signature :

Witness Name :

Witness ID :

Witness Address :

Chew Yue Yin

S8826618H

1 Kaki Bukit Avenue 6 #01-43
Singapore 417883



Mei Kwan (LKKAuto)

From: Janice Goh <janice.goh@eqinsurance.com.sg>
Sent: Thursday, 23 January, 2020 10:12 AM
To: Mei Kwan (LKKAuto)
Cc: Cecilia Chong (LKK Auto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBJ28U (OI : EQI - DM20HO00186/SG) AND GZ7162A (TP : LKK REF - CC6/EQI20001365/Aga3) on 20/01/2020
Attachments: GBJ28U.PDF

Dear Mei Kwan

Attached insured's accident report for your attention.

Thank you.


Janice Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, January 22, 2020 6:52 PM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Cc: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBJ28U (OI : EQI - TBA) AND GZ7162A (TP : LKK REF - CC6/EQI20001365/Aga3) on 20/01/2020

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GZ 7162A at M/s New Hock Teck Motor Pte Ltd - Kaki Bukit on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of insured's accident report for our necessary action.

Cecilia Chong (LKK Auto)

From: Admin nht <admin@nhtmotor.com>
Sent: Friday, 13 March 2020 1:08 PM
To: Cecilia Chong (LKK Auto)
Cc: Chloe; Mei Kwan (LKKAuto); Admin A
Subject: Re: GZ7162A CLAIMING AGAINST GBJ28U DOA:20.01.2020 *** LKK REF: CC6/EQI20001365/Aga3

Without Prejudice

Hi Cecilia

We accept your offer as \$4,330, please prepare necessary to EQ process the payment , thanks.

*** Please highlight to EQ,payment under "New Hock Teck Motor Pte Ltd" ***


Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Fri, Mar 13, 2020 at 11:52 AM Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Sukyi,

We are pleased to offer G/S \$4330.00 (all-in).



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 06/04/2020

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBJ 28U	(Insd Veh)	Your Ref. No. : DM20HO00186/SG
	GZ 7162A	(TP Veh)	Our Ref. No. : CC6/EQI20001365/Aga3q2
Date of Accident	20/1/2020		

Liability	100%	
Final Repair Cost	: \$ 3,424.00	
Loss of Use	: \$ 900.00	15 days
Rental (If any)	: \$	days
Others:	: \$ 7.45	
	: \$	
	4,331.45	
Final Settlement Sum	: \$ 4,330.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	NEW HOCK TECK MOTOR PTE.LTD.	: \$ 4,330.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI20001365/Aga3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 06-04-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 28U	Veh. Inspected	GZ 7162A
Policy No.	DMCPHQ19-005231	Coverage (\$)	0.00
Claim No.	DM20HO00186/SG	Excess (\$)	0.00
Assign From		Assign Date	20/01/2020

2. Vehicle Particulars & Condition

Make & Model	mitsubishi canter	c.c	2835
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	FB70ABA00444	Colour	WHITE
Odometer	410903	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R14	YOKOHAMA	6 mm
L/H Front Tyre	195 R14	YOKOHAMA	6 mm
R/H Rear Tyre	165 R13	GREEN MAX	6 mm
L/H Rear Tyre	165 R13	GREEN MAX	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/01/2020	Inspection Date	20/01/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 7162A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WIPER GARNISH	CRACKED	430.00	430.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	330.00	330.00
1	FRONT PANEL	DENTED	1,175.00	1,175.00
1	FRONT L/H SIDE PANEL	DISTORTED	590.00	590.00
1	FRONT GRILLE	CRACKED	530.00	530.00
8	FRONT GRILLE CLIP @\$6.50	NECESSARY	52.00	10.00
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	59.00	59.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	980.00	-
1	FRONT L/H HEADLAMP	SMASHED	590.00	590.00
1	FRONT L/H SIDE LAMP	SMASHED	195.00	195.00
1	FRONT L/H SIGNAL LAMP UPPER	SMASHED	240.00	240.00
1	FRONT L/H SIDE MIRROR TOP COVER	NOT NECESSARY	105.00	-
1	FRONT L/H SIDE MIRROR ROUND COVER	NOT NECESSARY	86.00	-
1	FRONT L/H SIDE MIRROR LOWER GARNISH	CRACKED	85.00	85.00
1	FRONT L/H SIDE MIRROR STAY	NOT NECESSARY	422.00	-
1	FRONT L/H DOOR	DISTORTED	2,271.00	1,881.00
2	FRONT L/H DOOR HINGE @\$140.00	BENT	280.00	280.00
1	FRONT L/H DOOR OUTER MOULDING	NOT NECESSARY	140.00	-
1	FRONT L/H DOOR LOCK	NOT NECESSARY	695.00	-
1	FRONT L/H DOOR WEATHERSTRIP	NOT NECESSARY	320.00	-
1	FRONT L/H DOOR INNER TRIM BOARD	NOT NECESSARY	620.00	-
1	FRONT L/H DOOR WINDOW MOTOR & REGULATOR ASSY	NOT NECESSARY	1,712.00	-
1	FRONT L/H DOOR PILLAR	TO REPAIR SEE LABOUR	1,270.00	-
1	REAR TAILGATE	DENTED	2,900.00	2,398.00
2	REAR TAILGATE TOP SIDE HANDLE @\$350.00	NOT NECESSARY	700.00	-
2	REAR TAILGATE LOWER SIDE LOCK @\$320.00	O/S BENT	640.00	320.00
3	REAR TAILGATE LOWER SIDE HINGES @\$95.00	O/S BENT	285.00	95.00
2	REAR TAILGATE LOWER SIDE BRACKET @\$340.00	BENT	680.00	340.00
1	REAR TAILGATE LOWER MEMBER	DISTORTED	550.00	550.00

Report Ref No. CC6/EQI20001365/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE ALUMINIUM COVER	NOT NECESSARY	450.00	-
1	REAR R/H SIDE TAILGATE	TO REPAIR SEE LABOUR	4,000.00	-
4	REAR R/H SIDE TAILGATE LOWER HINGE @\$90.00	NOT NECESSARY	360.00	-
1	REAR R/H SIDE TAILGATE ALUMINIUM COVER	NOT NECESSARY	850.00	-
1	REAR R/H TAIL LAMP	SMASHED	240.00	240.00
1	REAR R/H TAIL LAMP BRACKET	DISTORTED	140.00	140.00
1	REAR STEP BRACKET	TO REPAIR SEE LABOUR	250.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	10,000.00	-
1	REAR FLOOR PANEL PLYWOOD	NOT NECESSARY	650.00	-
1	REAR EXHAUST	NOT NECESSARY	540.00	-
2	REAR EXHAUST MOUNTING @\$55.00	NOT NECESSARY	110.00	-
1	REAR CENTER EXHAUST	NOT NECESSARY	850.00	-
	LESS 10% DISCOUNT		-	-1,047.80
			37,372.00	9,430.20
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT L/H DOOR COMPANY STICKER (SN)	NECESSARY	55.00	30.00
1	REAR TAILGATE 70KM/H STICKER (SN)	NECESSARY	30.00	15.00
1	REAR TAILGATE 13 PAX STICKER (SN)	NECESSARY	30.00	15.00
1	REAR TAILGATE STA STICKER (SN)	NECESSARY	20.00	10.00
			135.00	70.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION & TRIM BOARD .	NOT NECESSARY	280.00	-
	TO REMOVE & REFIT DASHBOARD .	NOT NECESSARY	450.00	-
	TO REMOVE & REFIT FRONT L/H DOOR ,GLASS ,LOCK ,WEATHERSTRIP ,TRIM BOARD ,WINDOW MOTOR & REGULATOR ASSY .		280.00	80.00
	TO REMOVE & REFIT FRONT WINDSCREEN.		160.00	120.00
	GUM.	NOT NECESSARY	60.00	-
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .	NOT NECESSARY	380.00	-
	TO CHECK WIRING .		100.00	60.00
	TUFF KOTE.		150.00	80.00

Report Ref No. CC6/EQI20001365/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEE.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT L/H DOOR PILLAR,REAR R/H SIDE TAILGATE ,REAR STEP BRACKET AND REAR FLOOR PANEL.		2,000.00	1,600.00
	SPRAY PAINTING.		2,400.00	1,400.00
			6,410.00	3,340.00
GRAND TOTAL			43,917.00	12,840.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CC6/EQI20001365/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.