

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001370/QPA3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : SHC4786D	Insured Vehicle No :	SH6222U	
Date of Loss: 16/01/2020	Nature of Claim:	TP	Claim No: MCT20010515

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4786D		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6585116
Reg. Date:	11/03/2010 (Man. Year: 2015)	Chassis No:	JTDKN36U605767618
Colour:	Maroon	Odometer:	315105 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,149.04	2,946.45	4,202.59	58.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,339.00	1,550.00	1,789.00	53.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,488.04	4,496.45	5,991.59	57.13
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	10,488.04	4,100.00	6,388.04	60.91
+ Loss of Use (9.0 x S\$40.00/day) (S\$)		360.00		
+ Car Rental (9.0 x S\$114.49/day) (S\$)		1,030.41		
Nett Liability (S\$)		5,490.41		
Global Sum Settlement (S\$)		5,450.00		

INSPECTION

Date of Assignment:	20/01/2020	
Date Inspected:	20/01/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2020)
Parts: 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4786D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*DOOR RR/LH (DISC 25%)	Dented	954.50 F	*715.88 F	
2	1		*MOULDING BODY LH (DISC 25%)	Cracked	673.60 F	*505.20 F	
3	1		*FENDER RR/LH (DISC 25%)	Dented	766.80 F	*575.10 F	
4	1		*QUARTER GLASS RR/LH (DISC 25%)	Necessary	168.10 F	*126.07 F	
5	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F	
6	1		*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F	
7	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F	
8	1		*SOLAR FILM (SN)	Necessary	125.00 F	*125.00 F	
9	1		*DOOR LOCK RR/LH	Serviceable	709.30 F	*- F	
10	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F	
11	1		*FENDER LINER RR/LH	Serviceable	141.30 F	*- F	
12	1		*SILL MEMBER PLATE RR/LH	Serviceable	57.50 F	*- F	
13	1		*TYRE	Serviceable	126.74 F	*- F	
14	1		*WHEEL HUB REAR	Serviceable	489.40 F	*- F	
15	1		*WHEEL DISC	Repair	1,484.20 F	*- F	
16	1		*BUMPER REAR	Repair	458.60 F	*- F	
17	1		*ADVERTISEMENT STICKER (SN)	Necessary	742.20 F	*742.20 F	
					Total Parts (S\$)	7,149.04	2,946.45

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	500.00
2	SPRAY PAINT	New	1,494.00	730.00
3	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
4	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
5	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
6	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	60.00
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	60.00
8	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
9	TO REMOVE/REFIT SEAT	New	120.00	40.00
10	TO REPLACE SUNDRY PARTS	New	100.00	20.00
11	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			3,339.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >