



Case Details

Case Reference Number : TAX/01/20/2070
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4786D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-10173-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 15/01/2020 05:45 PM
 Vehicle Age(In Months) : 46

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main		6505487	DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace	h
Standard	Main		6505493	DOOR LOCK RR/LH	1	709.30	709.30	25.00	531.97	Replace	0	0	Check	X SVC
Standard	Main		6505658	WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	X R
Standard	Main		6505607	MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	1	505.20	Replace	X CRA
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	X R
Standard	Main		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	X SVC
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	X Nec
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	X PD
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace	X Nec
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	X Nec
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	X SVC
One Time Key In	Main			SILL MEMBER PLATE RR/LH	1	57.50	57.50	25.00	43.13	Replace	0	0	Check	X SVC
Total Spare Part Cost									4,782.32	Surveyor Total		2,079.25		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,825.86	Final Sur Total		1,663.40		

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X SVC
One Time Key In	Main			WHEEL HUB REAR	1	489.40	489.40	25.00	367.05	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NAC
Total Spare Part Cost									4,782.32	Surveyor Total		2,079.25		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,825.86	Final Sur Total		1,663.40		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH REAR PORTION	845.00	500	
Total:			845.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR DOOR LH	378.00	200	
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	80	
3	Main	TO RESPRAY REAR FENDER LH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	50	
5	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			1,494.00	730.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	742.20	742.20	
2	Main	TO TRANSFER DOOR MECHANISM	120.00	60	
Total:			1,867.20	1,187.20	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	/
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	/
5	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	60	/
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00	/
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60	/
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	Main	TO REMOVE / REFIT SEAT	120.00	40	/
10	Main	TO REPLACE SUNDRY PARTS	100.00	20	/
11	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,867.20	1,187.20	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,825.86	1,663.40
Total Labour Cost	845.00	500.00
Total Spray Painting	1,494.00	730.00
Other	1,867.20	1,187.20
Overall Total	8,032.06	4,496.45
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	8,050.00	4,500.00
Surveyor Approved Amount		4,500.00
No of Repair Days*	6	4 <i>4 days</i>
Remarks	-	Lump Sum repair, take after paint photo.
Surveyor Name		Sun Pin (LKK)

Signature

Estimator Assesment(\$)

Surveyor Assesment(\$)



Save Clear

Survey Date

20/01/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____