

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001373/UPA3Q2

Date: 27/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLN2038M	Insured Vehicle No :	SHC1133H
Date of Loss: 18/01/2020	Nature of Claim: TP	Claim No: MCT20010439

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN2038M		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRY342164
Reg. Date:	26/04/2017 (Man. Year: 2016)	Chassis No:	MR053REH104561042
Colour:	Black	Odometer:	52027 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,346.95	2,745.60	2,601.35	48.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,800.00	1,360.00	43.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,506.95	4,545.60	3,961.35	46.57
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	8,506.95	3,600.00	4,906.95	57.68
+ GST 7.00/7.00% (\$\$)	595.49	252.00	343.49	57.68
Nett Amount (\$\$)	9,102.44	3,852.00	5,250.44	57.68
+ Loss of Use (4.0 x S\$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,099.45		

INSPECTION

Date of Assignment:	22/01/2020	
Date Inspected:	23/01/2020 Inspected At:	23 KAKI BUKIT AVE 5 #04-01 Repairer: Automobile Integrated Management Pte Ltd (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN2038M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent / Buckled	589.10 FL	*589.10 FL
2	1		*REAR BOOT LID HINGE LH	Not Necessary	86.10 FL	*- FL
3	1		*REAR BOOT LID HINGE RH	Not Necessary	86.10 FL	*- FL
4	1		*REAR BOOT LID EMBLEM	Necessary	58.40 FL	*58.40 FL
5	1		*REAR BOOT LID ALTIS WORDING	Necessary	58.40 FL	*58.40 FL
6	1		*REAR BOOT LID WEATHERSTRIP	Twisted	284.30 FL	*284.30 FL
7	1		*REAR BOOT LID LAMP LH	Not Necessary	364.10 FL	*- FL
8	1		*REAR BOOT LID LAMP RH	Not Necessary	364.10 FL	*- FL
9	1		*REAR TAIL LAMP LH	Cracked	378.10 FL	*378.10 FL
10	1		*REAR TAIL LAMP RH	Not Necessary	378.10 FL	*- FL
11	1		*REAR BOOT LID LOCK	Twisted	284.70 FL	*284.70 FL
12	1		*REAR FENDER LH	Repair	824.50 FL	*- FL
13	1		*REAR FENDER RH	Repair	824.50 FL	*- FL
14	1		*REAR BUMPER	Dented / Deformed	564.80 FL	*564.80 FL
15	1		*REAR BUMPER SIDE RETAINER LH	Bent	79.30 FL	*79.30 FL
16	1		*REAR BUMPER SIDE RETAINER RH	Bent	79.30 FL	*79.30 FL
17	1		*REAR BUMPER SPONGE	Not fitted	125.70 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	268.30 FL	*268.30 FL
19	1		*REAR END PANEL	Badly Dented	398.40 FL	*398.40 FL
20	1		*REAR END PANEL LOCK SENSOR	Shorted	179.40 FL	*179.40 FL
21	1		*REAR END PANEL GARNISH	Twisted	198.30 FL	*198.30 FL
22	1		*REAR SPARE TYRE PANEL	Repair	348.60 FL	*- FL
23	1		*SET REAR REVERSE SENSOR	Shorted	180.00 FS	*180.00 FS
24	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,052.60	3,600.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,705.65	855.20

Total Parts (\$\$)	5,346.95	2,745.60
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING CHARGE	New	1,500.00	1,000.00
3	WIRING CHARGE	New	80.00	20.00
4	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	160.00	80.00
5	TUFF KOTE	New	100.00	50.00
6	REMOVE/REFIX REVERSE SENSOR	New	120.00	50.00
Gross Labour Cost (\$)			3,160.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >