

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/CTI20001387/HSD3S2**Date:** 14/02/2020REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19199619000	
<b>Claimant Vehicle No :</b>	GBC4853P	<b>Insured Vehicle No :</b>	GBH3613X	
Date of Loss:	19/01/2020	Nature of Claim:	TP	Claim No: SNM20D200435C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBC4853P</b>		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Turbo (A)	Engine No:	ZD30306879K
Reg. Date:	30/10/2012 (Man. Year: 2012)	Chassis No:	JN1SC2F24Z0850535
Colour:	White	Odometer:	192155 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/R15C	Rear Tyre Size:	155 R13
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	23/01/2020	
Date Inspected:	04/02/2020	Inspected At: Hup Ley Huat Motor Spray Painting Services BLK 1 KAKI BUKIT AVE 6 #01-35 Singapore 409793
Estimated Period of Repair:	6.0 days	

**Adjuster:** LEE HOCK ANN**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

2/14/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 14 Feb 2020)

**Parts:** N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD Turbo (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBC4853P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**