

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jan 2020		24 Jan 2020 09:36 Edit Adj Rpt	S\$13,892.32 Edit Estimates	S\$13,892.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: OSCR PTE LTD , Co. Reg. No.: 201806082N									
Main Claimant: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Vehicle Reg. No.: SHD9480Y		Date of Loss: 20/01/2020 00:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / M2000641		Policy/Cover Note No.: MK000770 (Comprehensive) Coverage: 10/09/2019 - 09/09/2020							
Vehicle Reg. No. (Insured): SMQ9794P		Policy No. (Claimant): Excess: S\$2,500.00							
Repairer: Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:									
Handling Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ong Chin Kiat]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/02/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD9480Y (M2000641)**
[SMQ9794P]
TP
TRANS-CAB SERVICES PTE LTD
Jan 20 2020 12:00AM
[OSCR PTE LTD]
Trans-cab Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#) ▼

Photos/Images					
3 per page ▼					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/04/20 17:00	General View		Load JPG	☒
2	27/04/20 17:00	General View		Load JPG	☒
3	27/04/20 17:00	General View		Load JPG	☒
4	27/04/20 17:00	General View		Load JPG	☒
5	27/04/20 17:00	General View		Load JPG	☒
6	27/04/20 17:00	General View		Load JPG	☒
7	27/04/20 17:00	General View		Load JPG	☒
8	27/04/20 17:00	General View		Load JPG	☒
9	27/04/20 17:00	General View		Load JPG	☒
10	27/04/20 17:00	General View		Load JPG	☒
11	27/04/20 17:00	General View		Load JPG	☒
12	27/04/20 17:00	General View		Load JPG	☒
13	27/04/20 17:00	General View		Load JPG	☒
14	27/04/20 17:00	General View		Load JPG	☒
15	27/04/20 17:00	General View		Load JPG	☒
16	27/04/20 17:00	General View		Load JPG	☒
17	27/04/20 17:00	General View		Load JPG	☒
18	27/04/20 17:00	General View		Load JPG	☒
19	27/04/20 17:00	General View		Load JPG	☒
20	27/04/20 17:00	General View		Load JPG	☒
21	27/04/20 17:00	General View		Load JPG	☒
22	27/04/20 17:00	General View		Load JPG	☒
23	27/04/20 17:00	General View		Load JPG	☒
24	27/04/20 17:00	General View		Load JPG	☒
25	27/04/20 17:00	General View		Load JPG	☒
26	27/04/20 17:00	General View		Load JPG	☒
27	27/04/20 17:00	General View		Load JPG	☒
28	27/04/20 17:00	General View		Load JPG	☒
29	27/04/20 17:00	General View		Load JPG	☒
30	27/04/20 17:00	General View		Load JPG	☒
31	27/04/20 17:00	General View		Load JPG	☒
32	27/04/20 17:00	General View		Load JPG	☒
33	27/04/20 17:01	Reinspection Photo		Load JPG	☒
34	27/04/20 17:01	Reinspection Photo		Load JPG	☒
35	27/04/20 17:01	Reinspection Photo		Load JPG	☒
36	27/04/20 17:01	Reinspection Photo		Load JPG	☒
37	27/04/20 17:01	Reinspection Photo		Load JPG	☒
38	27/04/20 17:01	Reinspection Photo		Load JPG	☒
39	27/04/20 17:01	Reinspection Photo		Load JPG	☒
40	27/04/20 17:01	Reinspection Photo		Load JPG	☒

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	27/04/20 17:01	Reinspection Photo		Load JPG	☒
42	27/04/20 17:01	Reinspection Photo		Load JPG	☒
43	27/04/20 17:01	Reinspection Photo		Load JPG	☒
44	27/04/20 17:01	Reinspection Photo		Load JPG	☒
45	27/04/20 17:01	Reinspection Photo		Load JPG	☒
46	27/04/20 17:01	Reinspection Photo		Load JPG	☒
47	27/04/20 17:01	Reinspection Photo		Load JPG	☒
48	27/04/20 17:01	Reinspection Photo		Load JPG	☒
49	27/04/20 17:01	Reinspection Photo		Load JPG	☒
50	27/04/20 17:01	Reinspection Photo		Load JPG	☒
51	27/04/20 17:01	Reinspection Photo		Load JPG	☒
52	27/04/20 17:01	Reinspection Photo		Load JPG	☒
53	27/04/20 17:06	Reinspection Photo		Load JPG	☒
54	27/04/20 17:06	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	24/01/20 09:50	SHD9480Y - TP GIA		Load PDF	
2	24/01/20 09:50	MARKED ESTIMATE		Load PDF	
3	24/01/20 09:50	PRELIMINARY ADVICE		Load PDF	
4	24/04/20 13:00	Letter of Demand from Third Party		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI20001393/KTD3S2**Date:** 14/05/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000770
Claimant Vehicle No :	SHD9480Y	Insured Vehicle No :	SMQ9794P
Date of Loss:	20/01/2020	Nature of Claim:	TP
		Claim No:	M2000641

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9480Y		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C33837
Reg. Date:	27/06/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU703081950
Colour:	Metallic White/Red	Odometer:	50538 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,340.45	11,582.32	27,758.13	70.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,770.00	2,310.00	17,460.00	88.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	59,110.45	13,892.32	45,218.13	76.50
+ GST 7.00/7.00% (S\$)	4,137.73	972.46	3,165.27	76.50
Nett Amount (S\$)	63,248.18	14,864.78	48,383.40	76.50

INSPECTION

Date of Assignment:	24/01/2020		
Date Inspected:	22/01/2020	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$13,892.33

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 May 2020)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD9480Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER	Torn	516.00 FL	-	*516.00 FL
2	1		*BRACKET, FRONT BUMPER EXTENSION MOUNTING	Serviceable	103.40 FL	-	*- FL
3	1		*REINFORCEMENT, FRONT BUMPER	Serviceable	716.60 FL	-	*- FL
4	1		*REINFORCEMENT, FRONT BUMPER, NO.2	Serviceable	246.10 FL	-	*- FL
5	1		*COVER, FRONT BUMPER HOLE, RH	Dented	29.30 FL	-	*29.30 FL
6	1		*ABSORBER, FRONT BUMPER, LOWER	Serviceable	132.70 FL	-	*- FL
7	1		*ABSORBER, FRONT BUMPER, ENERGY	Cracked	79.60 FL	-	*79.60 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	80.10 FL	-	*80.10 FL
9	1		*COVER SUB-ASSY, ENGINE, NO.1	Serviceable	472.40 FL	-	*- FL
10	1		*COVER SUB-ASSY, ENGINE UNDER, NO.2	Serviceable	241.90 FL	-	*- FL
11	1		*EXTENSION, FRONT BUMPER, RH	Serviceable	120.10 FL	-	*- FL
12	1		*EXTENSION, FRONT BUMPER, LH	Serviceable	120.10 FL	-	*- FL
13	1		*FRONT LED LAMP (LOWER) RH	Missing	951.40 FL	-	*951.40 FL
14	1		*FRONT HEADLAMP RH	Mtg Broken	2,637.60 FL	-	*2,637.60 FL
15	1		*COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	Serviceable	960.50 FL	-	*- FL
16	1		*MOTOR, HEADLAMP LEVELING, RH	Serviceable	487.50 FL	-	*- FL
17	1		*FRONT FENDER RH	Bent	977.80 FL	-	*977.80 FL
18	1		*LINER, FRONT FENDER, RH	Distorted	206.70 FL	-	*206.70 FL
19	1		*EMBLEM, SIDE PANEL	Necessary	54.60 FL	-	*54.60 FL
20	1		*PAD, FRONT WHEEL OPENING EXTENSION, RH	Serviceable	59.60 FL	-	*- FL
21	1		*PROTECTOR, FRONT FENDER SIDE PANEL, RH	Serviceable	93.90 FL	-	*- FL
22	1		*SEAL, FENDER APRON MUDGUARD, RH	Serviceable	51.90 FL	-	*- FL
23	1		*COVER SUB ASSY, FRONT PILLAR, UPR RH	Repair	100.40 FL	-	*- FL
24	1		*GRILLE SUB-ASSY, RADIATOR	Serviceable	346.00 FL	-	*- FL
25	1		*GRILLE, RADIATOR, LOWER NO.1	Serviceable	170.10 FL	-	*- FL
26	1		*EMBLEM ASSY, RADIATOR GRILLE	Serviceable	90.80 FL	-	*- FL
27	1		*FRONT BONNET	Repair	983.10 FL	-	*- FL
28	1		*INSULATOR, HOOD	Serviceable	410.90 FL	-	*- FL
29	1		*HINGE ASSY, HOOD, RH	Repair	58.90 FL	-	*- FL
30	1		*HINGE ASSY, HOOD, LH	Repair	58.90 FL	-	*- FL
31	1		*LOCK ASSY, HOOD	Repair	135.00 FL	-	*- FL
32	1		*CABLE ASSY, HOOD LOCK CONTROL	Serviceable	54.90 FL	-	*- FL
33	1		*BRACE, HOOD LOCK SUPPORT	Repair	78.30 FL	-	*- FL
34	1		*COVER, RADIATOR SUPPORT OPENING	Serviceable	235.30 FL	-	*- FL
35	1		*WIRE, ENGINE ROOM MAIN	Serviceable	7,323.90 FL	-	*- FL
36	1		*WIRE, ENGINE	Serviceable	2,577.20 FL	-	*- FL
37	1		*SUPPORT SUB-ASSY, RADIATOR, RH	Repair	245.10 FL	-	*- FL
38	1		*SUPPORT SUB ASSY, RADIATOR, UPPER	Repair	377.10 FL	-	*- FL
39	1		*SUPPORT SUB ASSY, RADIATOR, LOWER	Bent	409.90 FL	-	*409.90 FL
40	1		*SUPPORT, RADIATOR, UPPER RH	Bent	78.90 FL	-	*78.90 FL
41	1		*LOUVER SUB ASSY, COWL TOP VENTILATOR	Serviceable	686.80 FL	-	*- FL
42	1		*SHIELD, COWL WATER EXTRACT, RH	Serviceable	19.60 FL	-	*- FL
43	1		*LOUVER, COWL TOP VENTILATOR, CENTER NO.1	Serviceable	98.60 FL	-	*- FL
44	1		*TANK, RESERVE SEALED W/O CAP	Dented	151.40 FL	-	*151.40 FL
45	1		*JAR ASSY, WINDSHIELD WASHER	Dented	219.10 FL	-	*219.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
46	1		*INLET SUB ASSY, WASHER	Serviceable	67.00 FL	-	*- FL
47	1		*MOTOR AND PUMP ASSY, WINDSHIELD WASHER	Serviceable	292.40 FL	-	*- FL
48	1		*APRON SUB-ASSY, FRONT FENDER, RH	Repair	979.40 FL	-	*- FL
49	1		*APRON ASSY, FRONT FENDER, RH	Repair	176.80 FL	-	*- FL
50	1		*MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT RH	Repair	62.80 FL	-	*- FL
51	1		*MEMBER, FRONT APRON TO COWL SIDE, UPPER RH	Repair	110.00 FL	-	*- FL
52	1		*BRACE SUB-ASSY, FENDER APRON, RH	Repair	292.50 FL	-	*- FL
53	1		*MEMBER SUB-ASSY, FRONT SIDE, RH	Repair	2,397.60 FL	-	*- FL
54	1		*MEMBER SUB-ASSY, FRONT SIDE, INNER RH	Repair	794.70 FL	-	*- FL
55	1		*REINFORCE SUB-ASSY, FRONT BUMPER MOUNTING, RH	Repair	184.60 FL	-	*- FL
56	1		*EXTENSION SUB-ASSY, FRONT SIDE MEMBER, RH	Repair	110.00 FL	-	*- FL
57	1		*PLATE, FRONT SIDE MEMBER, OUTER RH	Repair	292.10 FL	-	*- FL
58	1		*GUIDE, RADIATOR AIR, NO 3	Serviceable	112.70 FL	-	*- FL
59	1		*GUIDE, RADIATOR AIR, NO.1 RH	Serviceable	65.30 FL	-	*- FL
60	1		*SEAL, RADIATOR TO SUPPORT, NO.2	Serviceable	29.60 FL	-	*- FL
61	1		*COVER, MOTOR UNDER, REAR RH	Serviceable	80.10 FL	-	*- FL
62	1		*CONDENSER ASSY, COOLER	Serviceable	1,783.20 FL	-	*- FL
63	1		*SHAFT ASSY, FRONT DRIVE, RH	Bent	1,379.50 FL	-	*1,379.50 FL
64	1		*ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	Serviceable	760.10 FL	-	*- FL
65	1		*JOINT ASSY, LOWER BALL, FRONT RH	Serviceable	283.40 FL	-	*- FL
66	1		*KNUCKLE, STEERING, RH	Bent	663.40 FL	-	*663.40 FL
67	1		*LINK ASSY, FRONT STABILIZER, RH	Serviceable	237.10 FL	-	*- FL
68	1		*BAR, STABILIZER, FRONT	Serviceable	367.30 FL	-	*- FL
69	1		*FRONT SHOCK ABSORBER	Bent	438.30 FL	-	*438.30 FL
70	1		*SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	Serviceable	236.40 FL	-	*- FL
71	1		*GEAR ASSY, STEERING	Serviceable	1,955.40 FL	-	*- FL
72	1		*CYLINDER ASSY, FRONT DISC BRAKE, RH	Serviceable	1,077.90 FL	-	*- FL
73	1		*SENSOR, SPEED, FRONT RH	Serviceable	543.90 FL	-	*- FL
74	1		*CROSSMEMBER SUB-ASSY, FRONT SUSPENSION	Bent	2,585.50 FL	-	*2,585.50 FL
75	1		*REINFORCEMENT SUB-ASSY, SIDE RAIL, REAR RH	Serviceable	133.30 FL	-	*- FL
76	1		*MIRROR ASSY, OUTER REAR VIEW, RH	Serviceable	1,436.60 FL	-	*- FL
77	1		*MOULDING ASSY, BODY ROCKER PANEL, RH	Cracked	594.80 FL	-	*594.80 FL
78	1		*BRACKET, FRONT BUMPER SIDE, RH	Repair	59.30 FL	-	*- FL
79	1		*BRACKET, HEADLAMP, RH	Serviceable	34.80 FL	-	*- FL
80	1		*PANEL SUB ASSY, FRONT DOOR, RH	Repair	1,300.70 FL	-	*- FL
81	1		*HINGE ASSY, FRONT DOOR, UPPER RH	Repair	97.50 FL	-	*- FL
82	1		*HINGE ASSY, FRONT DOOR, LOWER RH	Repair	110.60 FL	-	*- FL
83	1		*CHECK ASSY, FRONT DOOR	Repair	183.80 FL	-	*- FL
84	1		*RUN, FRONT DOOR GLASS, RH	Serviceable	153.60 FL	-	*- FL
85	1		*WEATHERSTRIP, FRONT DOOR, RH	Serviceable	231.30 FL	-	*- FL
86	1		*TAPE, BLACK OUT, NO.1 RH	Not Necessary	13.30 FL	-	*- FL
87	1		*TAPE, BLACK OUT, NO.2 RH	Not Necessary	43.50 FL	-	*- FL
88	1		*TAPE, BLACK OUT, NO.3 RH	Not Necessary	26.30 FL	-	*- FL
89	1		*WIRE, FRONT DOOR, RH	Serviceable	532.60 FL	-	*- FL
90	1		*MOULDING ASSY, FRONT DOOR BELT, RH	Serviceable	92.00 FL	-	*- FL
91	1		*FRONT WHEEL RIM	Dented	1,879.40 FS	-	*1,879.40 FS
92	1		*FRONT WHEEL RIM COVER	Dented	211.50 FS	-	*211.50 FS
93	1		*FRONT TYRE 195/65/15 (@ \$350.00 DISC 90%)	Punctured	350.00 FS	-	*315.00 FS
94	1		*SET CLIP, FRONT FENDER LINER	Necessary	35.00 FS	-	*35.00 FS
95	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	-	*- FS
96	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	-	*66.00 FS
97	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
98	1		*SET CLIP (FOR RADIATOR SUPPORT OPENING COVER)	Not Necessary	30.00 FS	-	*- FS
99	1		*SET RADIATOR GRILLE CLIP	Not Necessary	35.00 FS	-	*- FS
100	1		*SET FRONT FENDER LINER SCREW	Not Necessary	30.00 FS	-	*- FS
101	1		*HEADLAMP PROTECTOR RETAINER	Not Necessary	35.00 FS	-	*- FS
102	1		*FRONT RH DOOR STICKER TRANS-CAB	Not Necessary	100.00 FS	-	*- FS
103	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	-	*- FS
104	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	-	*- FS
105	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	-	*- FS
106	1		*WINDSCREEN MOULDING CLIP	Not Necessary	30.00 FS	-	*- FS
107	1		*SET ROCKER PANEL MOULDING CLIP	Necessary	35.00 FS	-	*35.00 FS
108	1		*SET FRONT BUMPER RETAINER SCREW	Not Necessary	35.00 FS	-	*- FS
109	1		*SET DOOR HINGE SCREW	Not Necessary	10.00 FS	-	*- FS
110	1		*SET DOOR CHECK SCREW	Not Necessary	10.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	51,253.70	14,595.80
- List Item Discount on L Items 25.00/25.00% (S\$)	11,913.25	3,013.48
Total Parts (S\$)	39,340.45	11,582.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	7,500.00	700.00
2	TO PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	7,500.00	1,100.00
3	LABOUR CHARGE TO MOUNT ND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
4	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
5	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO TRANSFER OF BONNET FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
7	TO RUST-PROOFING PF THE AFFECTED AREAS.	New	170.00	60.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	20.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
12	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	New	380.00	200.00
13	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	New	380.00	0.00
14	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER	New	380.00	100.00
15	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	New	380.00	0.00
16	TOWING FEES.	New	150.00	50.00
17	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
18	TO TRANSFER OF DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
19	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	New	380.00	0.00
20	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS.	New	380.00	0.00
Gross Labour Cost (\$\$)			19,770.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >