

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20001399/AVD3E2

**Date:** 11/09/2020

#### REFERENCE

Insured/Claimant: LIM QIAN TING WINNIE (LIN QIANTING) Policy No: 1800006550-01  
Date of Loss: 20/01/2020 Nature of Claim: OD Claim No: 4339632966SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV9259D**  
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CHZ628994  
Reg. Date: 22/01/2018 (Man. Year: 2017) Chassis No: WAUZZZ8V3J1038980  
Colour: Blue Odometer: 21415 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$83,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,953.00	4,453.12	6,499.88	59.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,732.00	10,302.00	6,430.00	38.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,685.00</b>	<b>14,755.12</b>	<b>12,929.88</b>	<b>46.70</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	27,085.00	14,155.12	12,929.88	47.74
<b>+ GST 7.00/7.00% (S\$)</b>	1,895.95	990.86	905.09	47.74
<b>Nett Amount (S\$)</b>	<b>28,980.95</b>	<b>15,145.98</b>	<b>13,834.97</b>	<b>47.74</b>

#### INSPECTION

Date of Assignment: 23/01/2020  
Date Inspected: 23/01/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 12.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,851.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	182.00 FS	*- FS
3	1		*WHEEL HOUSING LINER ADAPTER-LH	Not Necessary	36.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	30.00 FS	*- FS
5	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	55.00 FS	*- FS
6	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	39.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	62.00 FS	*- FS
8	1		*SIDE PANEL-LH	Dented	2,195.00 FS	*1,756.00 FS
9	1		*REAR WINDSCREEN	Necessary	766.00 FS	*612.80 FS
10	1		*PRIMER	Necessary	19.00 FS	*14.80 FS
11	1		*SIDE WINDOW-LH	Necessary	537.00 FS	*429.20 FS
12	1		*WHEEL HOUSING LINER	Not Necessary	226.00 FS	*- FS
13	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	84.00 FS	*- FS
14	1		*REAR DOOR-LH	Repair	2,375.00 FS	*- FS
15	1		*REAR DOOR OUTER SEAL-LH	Not Necessary	151.00 FS	*- FS
16	1		*BONDING AGENT	Not Necessary	46.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
18	1		*REAR DOOR CATCH	Not Necessary	89.00 FS	*- FS
19	1		*REAR ALUMINIUM RIM-LH	Cut	666.00 FS	*532.40 FS
20	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
21	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
22	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
23	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
25	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
26	1		*SUNDRIES	Necessary	400.00 FS	*27.92 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 10,953.00 4,453.12**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	400.00
4	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK AND POWER WINDOW DEVICES	New	280.00	0.00
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
7	TO DISMANTLE REAR BUMPER,REAR LID AND LHS REAR DOOR.TO RENEW REAR BUMPER AND LHS REAR DOOR.CUT OUT AND WELD LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,300.00	3,000.00
8	TO RESPRAY REAR BUMPER,LHS REAR DOOR,LHS REAR FENDER,LHS SILL PANEL DOOR ENTRANCES,ROOC CHANNEL,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,600.00	2,750.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>16,732.00</b>	<b>10,302.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >