

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20001400/ACD3Q2

Date: 22/03/2021

REFERENCE

| | | | | | |
|-------------------|---------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | LIM TSEN YONG | Policy No: | 2100329576 | | |
| Date of Loss: | 19/01/2020 | Nature of Claim: | OD | Claim No: | 9611909573SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SKH9813P | | |
| Make & Model: | AUDI A4, 1.8 T FSI MU S-Line CVT ABS (A) | Engine No: | CJE017590 |
| Reg. Date: | 31/01/2013 (Man. Year: 2012) | Chassis No: | WAUZZZ8K6DA057923 |
| Colour: | Gold | Odometer: | 108562 km |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | S\$55,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/50R17 | Rear Tyre Size: | 225/50R17 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|------------------|-----------------|------------------|--------------|
| Parts | 10,833.00 | 1,889.36 | 8,943.64 | 82.56 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 10,082.00 | 1,850.00 | 8,232.00 | 81.65 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 20,915.00 | 3,739.36 | 17,175.64 | 82.12 |
| - Excess (S\$) | 800.00 | 800.00 | 0.00 | 0.00 |
| (S\$) | 20,115.00 | 2,939.36 | 17,175.64 | 85.39 |
| + GST 7.00/7.00% (S\$) | 1,408.05 | 205.76 | 1,202.29 | 85.39 |
| Nett Amount (S\$) | 21,523.05 | 3,145.12 | 18,377.93 | 85.39 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 23/01/2020 | | |
| Date Inspected: | 23/01/2020 | Inspected At: | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 5.0 days | | |

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|------------|
| 1 | 1 | | *FRONT BUMPER | Repair | 2,110.00 FS | *- FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 244.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE | Not Necessary | 215.00 FS | *- FS |
| 4 | 1 | | *FRONT BUMPER VENT GRILLE-RH | Not Necessary | 127.00 FS | *- FS |
| 5 | 1 | | *FRONT WHEEL SPOILER-RH | Not Necessary | 48.00 FS | *- FS |
| 6 | 1 | | *FRONT BUMPER GUIDE SECTION-RH | Not Necessary | 34.00 FS | *- FS |
| 7 | 1 | | *FRONT FENDER-RH | Distorted | 932.00 FS | *745.20 FS |
| 8 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Not Necessary | 54.00 FS | *- FS |
| 9 | 1 | | *FRONT FENDER BRACKET-RH | Not Necessary | 50.00 FS | *- FS |
| 10 | 1 | | *FRONT FENDER DEFORMATION ELEMENT BRACKET | Not Necessary | 46.00 FS | *- FS |
| 11 | 1 | | *FRONT FENDER BRACE-RH LOWER | Bent | 112.00 FS | *89.20 FS |
| 12 | 1 | | *WHEEL HOUSING LINER | Not Necessary | 226.00 FS | *- FS |
| 13 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 42.00 FS | *- FS |
| 14 | 1 | | *STONE CHIP GUARD | Necessary | 69.00 FS | *54.64 FS |
| 15 | 1 | | *ADHESIVE TAPE | Not Necessary | 52.00 FS | *- FS |
| 16 | 1 | | *BONNET | Repair | 2,629.00 FS | *- FS |
| 17 | 1 | | *BONNET PROTECTIVE FILM-FRONT | Not Necessary | 43.00 FS | *- FS |
| 18 | 1 | | *BONNET ATTACHMENT PARTS | Not Necessary | 159.00 FS | *- FS |
| 19 | 1 | | *BONNET EDGE PROTECTION-FRONT | Not Necessary | 26.00 FS | *- FS |
| 20 | 1 | | *HEADLIGHT MOUNTING-RH | Cracked | 112.00 FS | *89.20 FS |
| 21 | 1 | | *MOUNTING PLATE | Cracked | 100.00 FS | *79.28 FS |
| 22 | 1 | | *HEADLIGHT COUPLING ELEMENT | Not Necessary | 30.00 FS | *- FS |
| 23 | 1 | | *HALOGEN HEADLIGHT-RH | Cut | 1,027.00 FS | *821.60 FS |
| 24 | 1 | | *HALOGEN FOG LAMP-RH | Not Necessary | 247.00 FS | *- FS |
| 25 | 1 | | *FENDER TOP SUPPORT CONNECTING PLATE-RH UPPER | Repair | 489.00 FS | *- FS |
| 26 | 1 | | *FRONT ALUMINIUM RIM-RH | Not Necessary | 710.00 FS | *- FS |
| 27 | 1 | | *ACRYLIC SEALANT | Not Necessary | 180.00 FS | *- FS |
| 28 | 1 | | *CAVITY WAX | Not Necessary | 140.00 FS | *- FS |
| 29 | 1 | | *STONE CHIP | Not Necessary | 180.00 FS | *- FS |
| 30 | 1 | | *SUNDRIES | Necessary | 400.00 FS | *10.24 FS |

F=Franchise part. S=SpcNett.

| | | |
|--------------------------|------------------|-----------------|
| Total Parts (S\$) | 10,833.00 | 1,889.36 |
|--------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|--|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY | New | 360.00 | 0.00 |
| 2 | TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,BONNET,AND RHS HEADLIGHT.TO CUT OUT AND REWELD RHS FENDER TOP SUPPORT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 5,250.00 | 750.00 |
| 3 | TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,BONNET AND RHS FENDER TOP SUPPORT | New | 4,000.00 | 1,100.00 |
| 4 | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT | New | 280.00 | 0.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 10,082.00 | 1,850.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >