

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001407/R1PA3Q2

Date: 11/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLR8884B	Insured Vehicle No :	SH8735T
Date of Loss: 21/01/2020	Nature of Claim: TP	Claim No: MCT20010513

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8884B		
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE EU6 (A)	Engine No:	PE20917890
Reg. Date:	11/09/2017 (Man. Year: 2017)	Chassis No:	JM6GL1071H0124180
Colour:	White	Odometer:	64080 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,455.80	1,427.20	1,028.60	41.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	1,950.00	3,100.00	61.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,505.80	3,377.20	4,128.60	55.01
+ GST 7.00/7.00% (\$\$)	525.41	236.40	289.01	55.01
Nett Amount (\$\$)	8,031.21	3,613.60	4,417.61	55.01
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (\$\$)		321.00		
Nett Liability (\$\$)		3,934.60		

INSPECTION

Date of Assignment:	23/01/2020	
Date Inspected:	03/02/2020 Inspected At:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
		27A Tanjong Penjuru
		Singapore 609042
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2020)
Parts:	143	MAZDA 6 2.0 SEDAN EXECUTIVE EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8884B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,266.60 F	*1,266.60 F
2	1		*BRACKET CENTER	Serviceable	5.40 F	*- F
3	1		*TOWING COVER RHS	Serviceable	24.90 F	*- F
4	1		*RETAINER CENTER ,SENSOR	Serviceable	18.20 F	*- F
5	2		*SENSOR CENTER ,ULTRASONIC	Serviceable	361.80 F	*- F
6	4		*TAPE PROTECTOR ,SENSOR	Necessary	34.40 F	*34.40 F
7	4		*GROMMET ,REAR BUMPER	Necessary	12.00 F	*12.00 F
8	2		*GROMMET ,REAR BUMPER	Necessary	6.00 F	*6.00 F
9	2		*CLIP ,REAR BUMPER	Necessary	14.80 F	*14.80 F
10	6		*FASTENER ,REAR BUMPER	Necessary	18.00 F	*18.00 F
11	1		*REAR REINFORCEMENT	Serviceable	538.30 F	*- F
12	1		*GASKET LHS ,TAILLAMP	Necessary	27.70 F	*27.70 F
13	1		*GASKET RHS ,TAILLAMP	Necessary	27.70 F	*27.70 F
14	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,455.80** **1,427.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
2	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
3	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT .TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,980.00	660.00
4	TO RESPRAY REAR BUMPER ,REAR REINFORCEMENT AND REAR END PANEL	New	1,890.00	630.00
5	TO TRANSFER REVERSE SENSORS	New	330.00	330.00
6	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	0.00
Gross Labour Cost (S\$)			5,050.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >