

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 31 Jan 2020

**Preliminary Advice**

Vehicle No	: GBG7169R	Accident Date	: 23/10/2019
Make	: NISSAN NV350	Policy No.	: DMCVSN1935991900
Assignment Date	: 23/01/2020	Excess	: S\$350.00
Date of Inspection	: 29/1/2020	Est. Duration of Repair	: 35
Inspection At	: S THREE AUTOMOTIVE RECOVERY PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and front windscreen broken. The undercarriage and body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	103,353.30
Revised Amount	:S\$	48,346.50
Check Items (Estimated)	:S\$	40,395.30
Total	:S\$	88,741.80
 Lump Sum Repair (Estimated)	 :S\$	 71,000.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	51,000.00
COE / PARF Rebate	:S\$	32,952.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,048.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note the margin repair cost is \$18,048.00  
Repairer asking for Lump Sum Repair \$22,000/-.